

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-B1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 078505

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

SEYMOUR

9. WELL NO.

7

10. FIELD AND POOL, OR WILDCAT

BLANCO MESAVERDE

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SEC. 23, T-3TH, R-9E,
N.E.P.M.

12. COUNTY OR PARISH

SAN JUAN

13. STATE

NEW MEXICO

1. OIL ☐ GAS ☒ OTHER ☐
WELL WELL

2. NAME OF OPERATOR

SOUTHERN UNION PRODUCTION COMPANY

3. ADDRESS OF OPERATOR

P. O. Box 808, FARMINGTON, NEW MEXICO 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

1170 FEET FROM NORTH LINE & 970 FEET FROM THE EAST
LINE.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6436 D.F.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL


ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. RIG UP UNIT AND PULL TUBING. IF TUBING IS STUCK, CUT OFF TUBING AT APPROXIMATELY 5200 FT. AND PULL FROM HOLE.
2. SET 7" CEMENT RETAINER AT APPROXIMATELY 4900 FT. AND SQUEEZE OFF OPEN SHOT HOLE BELOW 7" CASING W/ APPROX. 300 SKS. (OPEN HOLE 5024-5615)
3. RUN CASING INSPECTION LOG IN 7" CASING. DETERMINE CONDITION OF CASING. RUN PACKER AND SQUEEZE OFF HOLES TO STOP WATER ENTRY AND CONDITION HOLE FOR WHIPSTOCKING WITH GAS.
4. SET 7" WHIPSTOCK AT APPROXIMATELY 4700 FT. AND CUT WINDOW.
5. DRILL 6" SIDETRACKED HOLE WITH GAS TO TOTAL DEPTH OF APPROXIMATELY 5900 FT.
6. RUN FULL STRING OF 4 1/2", 10.50#, J-55 CASING WITH 2 STAGE CEMENT JOB. SET STAGE COLLAR AT APPROXIMATELY 2800 FT. AND CEMENT TO SURFACE.
7. PERF AND FRAC MESAVERDE WITH TWO STAGE FRAC JOB.
8. BLOW DOWN WITH GAS AND CLEAN OUT TO P.T.D. AND RUN TUBING.



RECEIVED

MAY 11 1970

U. S. GEOLOGICAL SURVEY
ALBUQUERQUE

18. I hereby certify that the foregoing is true and correct

SIGNED

B. R. VANDERSLICE
B. R. VANDERSLICE

TITLE

AREA SUPERINTENDENT

DATE

MAY 7, 1970

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.