For (1	rm 9-831 a (Feb. 1951)					

(SUBMIT IN TRIPLICATE)

UNITED STATES **DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY**

Land Offic	. Senta Pe
Lease No.	079267
	n Juan 32-8

NOTICE OF INTENTION TO CHA NOTICE OF INTENTION TO TES' NOTICE OF INTENTION TO SHO NOTICE OF INTENTION TO PULL NOTICE OF INTENTION TO ABA	DRILL OR REPAIR WELL OOT OR ACIDIZE L OR ALTER CASING	x	SUBSEQUENT REPORT OF WATER SHUT-OFF SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING SUBSEQUENT REPORT OF ALTERING CASING SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR SUBSEQUENT REPORT OF ABANDONMENT SUPPLEMENTARY WELL HISTORY
(I	INDICATE ABOVE BY CHECK MA	ARK NAT	TURE OF REPORT, NOTICE, OR OTHER DATA, U. S. GEOLOGICAL SURVEY
N/4 Sec. 13	located 990 ft. fro	8	V NaMaPaka
(1/2 Sec. and Sec. No.)	(Twp.) at Dak. Sen J u	(Rai	nge) (Meridian) New Maxico
(Field)	(Coun	ity or Su	bdivision) (State or Territory)
The elevation of the de	rrick floor above sea	level	is 6522 ft.
	DET	AILS	OF WORK
	nthe to chicative cande, chaw		
(State names of and expected de			reights, and lengths of proposed casings; indicate mudding jobs, cement- important proposed work)
23-60 Total Dept fter logging, this dug and abendom in 1. Spot comment 2. Cut and pull 3. Cut and pull 4. Spot comment	ing points, and shall be following a	red : mine: o 50 eepa t £ri	inside of 7" casing. Inside of 7" casing. OCT20 1960
23-60 Total Dept fter logging, this dug and abendom in 1. Spot cement 2. Cut and pull 3. Cut and pull 4. Spot cement 5. Set surface	ing points, and so the following manual plug from 8156 to 7" casing at from 9 5/8" casing a plug in 9 5/8" so plug and erect de	red: mane: o 50 eepa t fri tub.	inside of 7" casing. OCT201960 DIST 3 OM.
23-60 Total Dept fter logging, this lug and abendon in 1. Spot cement 2. Cut and pull 3. Cut and pull 4. Spot cement 5. Set surface	ing points, and so the following manual plug from 8156 to 7" casing at from 9 5/8" casing at plug in 9 5/8" so plug and erect de plug and	red: same: o 50 eepa t fr tub. ry h	inside of 7" casing. Inside of 7" casing. OCT20 1960
1. Spot coment 2. Cut and pull 3. Cut and pull 4. Spot coment 5. Set surface lunderstand that this plan of	ing points, and so the following manual plug from 8156 to 7" casing at from 9 5/8" casing a plug in 9 5/8" so plug and erect de	red: same: o 50 eepa t fr tub. ry h	inside of 7" casing. OCT201960 DIST 3 OM.
1. Spot cement 2. Cut and pull 3. Cut and pull 4. Spot cement 5. Set surface	ing points, and so the following manual plug from 8156 to 7" casing at from 9 5/8" casing at plug in 9 5/8" so plug and erect de plug and	red: same: o 50 eepa t fr tub. ry h	inside of 7" casing. OCT201960 DIST 3 OM.
1. Spot cement 2. Cut and pull 3. Cut and pull 4. Spot cement 5. Set surface I understand that this plan of Company Box 930 Address	ing points, and so the following manual plug from 8156 to 7" casing at from 9 5/8" casing at plug in 9 5/8" so plug and erect de plug and	red: same: o 50 eepa t fr tub. ry h	inside of 7" casing. OCT201960 DIST 3 OM.