

135

F. Loc. 990/S; 990/W Elev. 6517 DF Spd. 9/26/52 Comp. 4/30/53 TD 5950 PB
 Casing 13-3/4 219 W 125 Sx. Int. @ W Sx. Pr. 7 @ 5068 W 225 Sx. T. @
 Csg. Perf. Prod. Stim.

Shot 2015 qts 5140-5940

L.P. 764 ~~BSX~~ MCF/D After 6 Hrs. Sic. P. 975 PSI After 3 Days GOR Grav. 1st Del. 4.22-53 SUG

TOPS		NITD	X	Well Log	X	TEST DATA						
Kirtland		C-102		Plat	X	Schd.	PC	Q	PW	PD	D	All.
Fruitland		C-103		Electric Log	X							
Pictured Cliffs	3400	C-104	X	C-110	X	*		No Test				
Cliff House	5000	Remarks * Poor deliverability					7-15-55	949	138	526	474	147 # 360
Menefee							7/15/56	745	112	528	472	120
Point Lookout	5460						1	745	113	528	472	120
Mancos												
Tocito												
Dakota												
Morrison												
Entrada												
✓	Pcd 3117											

P
 0 Blanco MV Co. San Juan s 8 T 31N R 8W U M Oper. SUG Lse. Oxnard No. 1