

Form 9-331
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

14-20-0603-7291

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NAVAJO TRIBAL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

NAVAJO TRIBAL 22-11

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

UNDISCOVERED

11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA

Sec 11, T30N, R18W

NMPM

12. COUNTY OR PARISH

SAN JUAN

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

STANDARD OIL COMPANY OF TEXAS

3. ADDRESS OF OPERATOR

A Division of Chevron Oil Company
3610 Avenue S, SHYDER, TEXAS

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface

Unit K, 1980 fsl, 1980 fwl Sec 11, T30N, R18W
SAN JUAN Co., New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

DF 4948.5

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well has been PLUGGED & ABANDONED in the following manner,

4-1-66 Move in ABANDONMENT TOOLS, MIX MUD

4-4-66 Squeezed Perf. 6523 to 6530 w/25% Cement

4-5-66 Pull Tbg out to Un plug, PERAN Tbg in hole

4-6-66 Circulat hole w/ 11.1"/gal mud, work Casing

4-7-66 Shot Csg (4 1/2") off @ 1189, Recoverd Same

Spot 75% plug from 1200 to 1050

Spot 10% plug @ Surface, Weld on Plate

over Surface Csg. Erect P&A MARKER

Clean & Level Location

18. I hereby certify that the foregoing is true and correct

SIGNED J. A. Hagan

TITLE Engineer

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE 5-16-66

DATE

*See Instructions on Reverse Side