UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



Sundry Notices and Reports 97 Wells7 71 3:28						
1. Type of Well GAS	070 FAFRANCI	Ді, МЛ ³ . 6.	Lease Number SF-078438 If Indian, All. or Tribe Name			
2. Name of Orange to 1		7.	Unit Agreement Name			
2. Name of Operator						
BURLINGTON RESOURCES _{OIL}	& GAS COMPANY		San Juan 32-9 Unit			
		8.				
3. Address & Phone No. of Opera PO Box 4289, Farmington, NM		9.				
4. Location of Well, Footage, S	Sec., T, R, M	10.	30-045-13216 Field and Pool			
1650'FSL, 790'FWL, Sec.18, 1	7-31-N, R-9-W, NMPM	11.	Blanco Mesaverde County and State San Juan Co, NM			
12. CHECK APPROPRIATE BOX TO IN	DICATE NATURE OF NOTICE, REPORT	RT, OTHER	DATA			
Type of Submission	Type of Action	c =1				
X Notice of Intent		nge of Pla Construct				
Subsequent Report	Plugging Back Non-	-Routine	Fracturing			
Final Abandonment		er Shut of	ff o Injection			
IIIIaI Abandonment		GISION C				
	X_ Other - Tubing repair					
13 Describe Proposed or Com						
13. Describe Proposed or Comp						
It is intended to repair	pleted Operations the tubing in the subject well	L accordin				
•	pleted Operations the tubing in the subject well	l accordi				
It is intended to repair	pleted Operations the tubing in the subject well	L accordi				
It is intended to repair	pleted Operations the tubing in the subject well	L according				
It is intended to repair	pleted Operations the tubing in the subject well	L according				
It is intended to repair	pleted Operations the tubing in the subject well	DE				
It is intended to repair	pleted Operations the tubing in the subject well		ng to the attached			
It is intended to repair	pleted Operations the tubing in the subject well		ng to the attached			
It is intended to repair procedure and wel	pleted Operations the tubing in the subject well		ng to the attached			
It is intended to repair procedure and wel	the tubing in the subject wellbore diagram.		ng to the attached			
It is intended to repair procedure and well 14. Thereby certify that the	the tubing in the subject wellbore diagram. The foregoing is true and correct (VGW5) Title Regulatory Admits		ng to the attached			

WORKOVER PROCEDURE -- TUBING REPAIR

SAN JUAN 32-9 UNIT #1 Blanco Mesaverde Sec. 18, T31N, R09W San Juan Co., New Mexico DPNO: 69837

- 1. Comply to all NMOCD, BLM, and BROG regulations. Conduct daily safety meetings for all personnel on location. Notify BROG Regulatory (Peggy Bradfield, 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document the approval in Dims/Wims. As much time as possible to the pump time is needed to the Agency to be able to show up for the cement job.
- 2. Install and test location rig anchors. Prepare blow pit. Comply to all NMOCD, BLM, and BROG safety regulations.
- 3. MOL and RU. Conduct safety meeting for all personnel on location. NU relief line. Blow down well and kill with 1% KCl water as necessary. ND wellhead and NU BOP. Test BOP.
- 4. TIH and tag bottom. Record depth. TOH with 2 3/8" tubing (190 jts.). Inspect tubing and replace all bad joints. (Note any buildup of scale, and notify Operations Engineer. If tubing is excessively scaled. acid wash may be run in perforations).
- 5. PU and RIH with 3 7/8" bit and 4 1/2" casing scraper to PBTD, 6148'. TOH and LD bit and scraper.
- 6. RIH open ended with tubing, SN one joint off bottom, (rabbit tubing in derrick before running in hole). CO with air. Land tubing @ bottom perforation, 5986'.
- 7. ND BOP, NU wellhead, rig down, move off location and restore location.

Recommended:

Approval:

Drilling Superintendent

Operations Engineer

12/ A/96

CONTACTS: Operations Engineer Gaye White 326-9875

San Juan 32-9 Unit #1

CURRENT -- 12/11/96

Blanco Mesaverde DPNO 69837 1650' FSL, 790' FWL,

Section 18, T-31-N, R-09-W, San Juan County, NM

Spud: 5-23-52 Completed: 8-8-52 Elevation: 6638' (GL)

6648' (KB) Logs: ES, GRI, Ind, DLC-GR, TS

Compression: B6 Workover(s):

5/70: Cut off stuck tubing. Squeeze open hole w/150 sxs cmt. Located holes in 7" casing. Squeezed holes w/125 sxs. Sidetracked w/4 1/2" casing. Cemented, perfed, fraced, and landed tubing.

Kirtland @ 2736

Fruitland @ 3113'

Pictured Cliffs @ 3470'


Lewis @ 3695'

Cliff House @ 5280'

Menefee @ 5358'

Point Lookout @ 5702'

Mancos @ 5793'



CASING PRESSURE	<u>s</u>	PRODUCTION	HISTORY	INTER	REST	PIPELINE
Initial SICP (6/70):	827 psi	Gas Cum: Current (10/96)	3.6 Bcf 399 Mcf/d	GWI:	42.50%	EPNG
Current SICP (8/93):	434 psi	Oil Cum:	117.6 Mbo	NRI:	32.86%	
		Current (10/96)	11 Bo/d	SJBT:	0.42%	