State of New Mexico +Submit 3 Copies Form C 103 to Appropriate Energy, Minerals and Natural Resources Department Revised 1-1-89 District Office DISTRICT I OIL CONSERVATION DIVISION WELL API NO. P.O. Box 1980, Hobbs, NM S8240 P.O. Box 2088 30 045 13369 DISTRICT II Santa Fe, New Mexico 87504-2088 5. Indicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 STATE FEE DISTRICT III 6. State Oil& Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 B 107964 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well State 2. Name of Operator 8. Well No. Conoco Inc. 3. Address of Operator 9. Pool name or Wildcat 10 Desta Dr. Ste 100W, Midland, Tx., 79705-4500 Mesa Verde (72319) 4. Well Location South 990 1580 Feet From The Line and Feet From The Line Section 36 Township Range **NMPM** County 30N 11W San Juan 10. Elevation (Show whether DF, RKB. RT, GR, etc.) 5978' GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON PERFORM REMEDIAL WORK REMEDIAL WORK **ALTERING CASING CHANGE PLANS TEMPORARILY ABANDON** COMMENCE DRILLING OPNS. **PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB** OTHER: Test Mesa Verde OTHER 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed It is proposed to recomplete this well to the Mesa Verde formation by the following procedure: .l. Rig up, blow well down and kill with minimum amount of 1% KCL. ND wellhead, NU BOPs, pull out of hole with 6673' of 2 3/8" 2. Rig up wireline, run in hole with CIBP & set @ approx. 6600' over Dakota zone; test csg to 1000 psi to ensure casing/plug inegrity. 3. Perforate the Mesa Verde from 4288' to 4882', / SPF. 4. Run in hole with packer & 2 3/8" tubing & spot acid across perforations & breakdown perfs, pull out of hole with tubing & packer and proceed with frac job. 5. Run in hole with 2 3/8" tubing, SN; test. Intend to file for downhole commingling permit, will run in hole with bit & drill out CIBP, clean out & produce commingled zones.

(this space for State Use)

APPROVED BY.

ORIGINAL SIGNED BY ERNIE BUSCH

DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE JUL 1 8

CONITIONS OF APPROVAL, IF ANY

BY ERNIE BUSCH TITLE WEPUTY UIL & GAS