UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY SEE

5	LEASE SEE		5 5	ŏ		מ	•	
٦	Cr.	7	78139	.— ≱ a)-s	ું જું	¥	5	1
ار	OF S	- <u>U</u>	10133	- 12		<u>=</u>	<u>(6</u>	_

DEPARTMENT OF THE INTERIOR	SF-078139 # 95 %
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	b da
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAMES & de belle de la
	bets lessification lessificati
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME 2 0 3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
1. oil m gas	I D. D. HILLOUL D
well well other	9. WELL NO. 2 5 2 5 5 5
2. NAME OF OPERATOR	9. WELL NO. 5 - 2 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
AMOCO PRODUCTION COMPANY	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Blanco Pictured Cliffs
501 Airport Drive Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17	AREA NW/4 NE/4 Section 34,
below.) 1113' FNL x 1453' FEL, Section 34,	T30N, R9W =
AT SURFACE: T30N, R9W	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same	San Juan 2 3 2 5 NM a 2
Same	14. API NO. 53-55 2 55 45
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	30-045-09653
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	5742 GL, 5755 RDB
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	ပ်ပိုင်လို့ မြင့် မြိမ့်ရွားရှိ
FRACTURE TREAT	
SHOOT OR ACIDIZE	ର ପ୍ରତ୍ୟ କଥା । ପ୍ରତ୍ୟ
REPAIR WELL \[\bigsize \bizeta \bigsize \bizeta	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9–330.)
MULTIPLE COMPLETE	
CHANGE ZONES ARANDON*	그는 그 이 이 일본부터 그리고 있었습니다.
ABANDON*	그는 그는 그리는 그를 가장하는 그를 위해 되었다. 그런 그는 그는
(Other)	· · · · · · · · · · · · · · · · · · ·
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	e all pertinent details, and give pertinent dates.
including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinen	irectionally drilled, give subsurface locations and
,	그 그 그 그 그 그 그 그 뭐 하는 그 그 그 그 게 되고 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그
Amoco Production Company proposes to repair a	suspected casing leak as follows:
	그 그 그 그를 사용 물통 이 활이 없었는 것
1) Locate casing leak by pressure testing wi	
2) Squeeze the casing with 300 sx Class "B"	Neat cement and circulate to surface.
Drill cement and bridge plug.	
	TO THE PLANE
Verbal approval obtained per conversation bet	ween B. E. Fackrell and Sims, 7/20/79
in the second	1 No. 24 - 11 - 12 - 12 - 12 - 12 - 12 - 12 -
	가족에 가는 그를 잃었다. 그는 그를 가는 표표를 받는 표표를 받는 것이 없다.

18. I hereby certify that the foregoing is true and correct Original Signed By

Subsurface Safety Valve: Manu. and Type ..

TITLE Dist. Adm. Supvr. DATE

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

SIGNED.

*See Instructions on Reverse Side

NMOCC

