submitted in lieu of Form 3160-5

#### UNITED STATES

# DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

ices and Reports on Wel	ls	
10 4 1 10 10 1 10 10 1 10 10 1 10 10 1 10 10	450 0 9 1999	Lease Number SF-078129 If Indian, All. or Tribe Name
& GAS COMPANY		Unit Agreement Name  Well Name & Number
	_	Pierce #9 API Well No. 30-045-20475
		<ul> <li>Field and Pool Blanco Pictured Cliffs</li> <li>County and State San Juan County, NM</li> </ul>
Type of A  _X_ Abandonment  Recompletion  Plugging Back  Casing Repair	Ction Change of P New Constru Non-Routine Water Shut	lans ction Fracturing off
d abandon the subject	well according	to the attached
<b>*</b>		_Date 4/19/99 
	& GAS COMPANY  tor  87499 (505) 326-9700  ec., T, R, M  30-N, R-9-W, NMPM  DICATE NATURE OF NOTICE  Type of Ac  X Abandonment  Recompletion  Plugging Back  Casing Repair  Altering Casing  Other  leted Operations  d abandon the subject agram.	& GAS COMPANY  tor  87499 (505) 326-9700  ec., T, R, M  30-N, R-9-W, NMPM  11  DICATE NATURE OF NOTICE, REPORT, OTHE  Type of Action  X Abandonment Change of P  Recompletion New Construction  Plugging Back Non-Routine  Casing Repair Water Shut  Altering Casing Conversion  Other  leted Operations  d abandon the subject well according agram.  foregoing is true and correct.  Title Regulatory Administrator

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



### Pierce #9

# Blanco Pictured Cliffs 1737' FNL & 990' FWL, Sec. 7, T30N, R9W AIN 5226701

Latitude / Longitude: 36° 49.7287' / 107° 49.4074' San Juan County, New Mexico PLUG AND ABANDONMENT PROCEDURE 4-12-99

Note: All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures.

- 1. Install and test location rig anchors. Prepare blow pit. Comply with all NMOCD, BLM, and Burlington safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. NU relief line and blow down well; kill with water as necessary. ND wellhead and NU BOP. Test BOP.
- 2. TOH and tally 100 joints 1-1/4" IJ tubing (3250'); visually inspect the tubing. If necessary LD tubing and PU workstring. Round trip 2-7/8" gauge ring down casing to 3180'.
- 3. Plug #1 (Pictured Cliffs interval and Fruitland top, 3180' 2806'): Set 2-7/8" wireline ClBP at 3180'. TIH with open ended tubing and tag CIBP. Load casing with water and establish circulation. Mix 12 sxs Class B cement to isolate Pictured Cliffs perforations and to cover Fruitland top. TOH and WOC. TIH and tag cement. Attempt to pressure test casing to 500#. If casing does not test, spot or tag subsequent plug as appropriate. TOH with tubing.
- 4. Plug #2 (Kirtland and Ojo Alamo tops, 2074' 1832'): Perforate 3 bi-wire squeeze holes at 2074'. Establish rate into squeeze holes if casing tested. Set 2-7/8" wireline cement retainer at 2024'. Establish rate under CR into squeeze holes. Mix 91 sxs Class B cement, squeeze 83 sxs cement outside 2-7/8" casing and leave 8 sxs cement inside casing to cover Ojo Alamo top. TOH and LD tubing.
- 5. Plug #3 (8-5/8" Surface casing at 225'): Perforate 3 bi-wire squeeze holes at 275'. Establish circulation out bradenhead with water. Mix and pump approximately 86 sxs Class B cement down 2-7/8" casing and then circulate good cement out bradenhead valve. Shut well in and WOC.
- 6. ND BOP and cut off casing below surface. Install P&A marker with cement to comply with regulations. RD, move off location, cut off anchors and restore location.

Recommended: 4/12/99
Operations Engineer

Approval:

Bruco D. Born 4.14.99 Drilling Superintendent

Operations Engineer:

L. Tom Loveland

Office: 326-9771

Pager: 324-2568 Home: 564-4418

## Pierce #9

#### Current

#### AIN 5226701

#### Blanco Pictured Cliffs

NW, Section 7, T-30-N, R-9-W, San Juan County, NM Latitude / Longitude: 36° 49.7287' / 107° 49.4074'

Today's Date: 4/12/99 Nac @ Surf. Spud: 5/8/69 8-5/8" 24# K-55 Csg set @ 225' Cmt w/ 165 sxs (Circulated to Surface) Completed: 6/30/69 12-1/4" hole Elevation: 6508' (GL) Logs: IES,FDC-GR, T.S. Workover History Apr '71: Ran 1-1/4" IJ tubing in well. Sep '93: Swab well, recovered 5 bbls fluid. Apr '98: Planned tubing repair: pulled tubing, in good shape; clean out fill from 3236' to 3276'; return well to production. Nov '98: Planned to restimulate well: pulled tubing; set RBP, found casing leak; land tubing. Ojo Alamo @ 1882' 1-1/4" Tubing Set at 3250' (100 jts, IJ, 2.33#) Kirtland @ 2024' TOC @ 2500' (T.S.) Fruitland @ 2856' Pictured Cliffs @3222' Pictured Cliffs Perforations: 3222' - 3242' PBTD 32841 2-7/8" 6.4# J-55 Csg set @ 3294' Cmt w/225 sxs 6-3/4" hole TD 3294'

# Pierce #9

# Proposed P&A

#### AIN 5226701

#### Blanco Pictured Cliffs

NW, Section 7, T-30-N, R-9-W, San Juan County, NM Latitude / Longitude: 36° 49.7287' / 107° 49.4074'

Today's Date: 4/12/99 Nac @ Surf. Spud: 5/8/69 8-5/8" 24# K-55 Csg set @ 225' Cmt w/ 165 sxs (Circulated to Surface) Completed: 6/30/69 12-1/4" hole Elevation: 6508' (GL) Lcgs: IES, FDC-GR, T.S. Perforate @ 275' Plug #3 275' - Surface Cmt with 86 sxs Class B Plug #2 2074' - 1832' Cmt with 91 sxs Class B, 83 sxs outside and 8 sxs inside. Ojo Alamo @ 1882' Cmt Retainer @ 2024' Kirtland @ 2024' Perforate @ 2074' TOC @ 2500' (T.S.) Plug #1 3180' - 2806' Cmt with 12 sxs Class B Fruitland @ 2856' Set CIBP at 3180' Pictured Cliffs @3222' Pictured Cliffs Perforations: 3222' - 3242' PBTD 3284' 2-7/8" 6.4# J-55 Csg set @ 3294' Cmt w/225 sxs 6-3/4" hole

TD 3294'