

submitted in lieu of Form 3160-5

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED  
BLM

99 MAY 14 AM 9:06

Sundry Notices and Reports on Wells

070 BURLINGTON, NM

1. Type of Well  
GAS

RECEIVED  
MAY 24 1999

2. Name of Operator

**BURLINGTON  
RESOURCES**

OIL & GAS COMPANY

OIL CON. DIV.  
DIST. 3

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

990' FNL, 1454' FWL, Sec.12, T-30-N, R-10-W, NMPM

5. Lease Number

NM-03562

6. If Indian, All. or  
Tribe Name

7. Unit Agreement Name

8. Well Name & Number  
Stickle #1

9. API Well No.  
30-045-20762

10. Field and Pool  
Blanco Pictured Cliffs

11. County and State  
San Juan County, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☒ Notice of Intent

☒ Abandonment

☐ Change of Plans

☐ Subsequent Report

☐ Recompletion

☐ New Construction

☐ Subsequent Report

☐ Plugging Back

☐ Non-Routine Fracturing

☐ Final Abandonment

☐ Casing Repair

☐ Water Shut off

☐ Altering Casing

☐ Conversion to Injection

☐ Other

13. Describe Proposed or Completed Operations

It is intended to plug and abandon the subject well according to the attached procedure and wellbore diagram.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Administrator Date 5/13/99

(This space for Federal or State Office use)

APPROVED BY /s/ Jim Lovato Title trc Date MAY 20 1999

CONDITION OF APPROVAL, if any:

## PLUG AND ABANDONMENT PROCEDURE

5-6-99

### Stickle #1

Blanco Pictured Cliffs  
990' FNL & 1454' FWL, Section 12, T30N, R10W  
San Juan County, New Mexico

Note: All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures.

1. Install and test location rig anchors. Prepare blow pit. Comply with all NMOCD, BLM, and Burlington safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. NU relief line and blow down well; kill with water as necessary. ND wellhead and NU BOP. Test BOP.
2. Due to casing leak tally and prepare an 1-1/4" IJ workstring. Round trip 2-7/8" gauge ring to 3170' or as deep as possible.
3. **Plug #1 (Pictured Cliffs interval and Fruitland Coal top, 3170' – 2806')**: Set a 2-7/8" wireline CIBP at 3170'. TIH with open ended tubing and tag CIBP. Load casing with water and establish circulation. Attempt to pressure test casing to 500#. If casing does not test, spot or tag subsequent plug as appropriate. Mix 12 sxs Class B cement and spot a balanced plug inside casing above the CIBP to isolate the Pictured Cliffs interval and cover Fruitland top. TOH to 2075'.
4. **Plug #2 (Kirtland and Ojo Alamo tops, 2075' – 1855')**: Mix 8 sxs Class B cement and spot inside the casing to cover Ojo Alamo top. TOH and LD tubing.
5. **Plug #3 (8-5/8" Surface casing at 143')**: Perforate 2 bi-wire squeeze holes at 193'. Establish circulation out bradenhead valve. Mix and pump approximately 70 sxs Class B cement down 2-7/8" casing and circulate good cement out bradenhead valve. Shut well in and WOC.
6. ND BOP and cut off casing below surface. Install P&A marker with cement to comply with regulations. RD, move off location, cut off anchors and restore location.

Recommended: \_\_\_\_\_  
Operations Engineer

Approval: \_\_\_\_\_  
Drilling Superintendent

# Stickle #1

Current

DPNO 5240601

Blanco Pictured Cliffs

NW Section 12, T-30-N, R-10-W, San Juan County, NM

Long: 107 deg. 50.27' / Lat: 36 deg. 49.86'

Today's Date: 5/6/99  
Spud: 4/13/77  
Completed: 5/5/71  
Elevation: 6621' (GL)  
Logs: C-DLC-GR, Ind.  
Temp. Survey

12-1/4" Hole

8-5/8" 24#, J-55 Casing set @ 143'  
Cmt w/ 85 sxs (Circulated to Surface)

TOC @ 1452' (Calc. @ 75%)

## WORKOVER HISTORY

Nov '98: Restimulation attempt. No tubing in well. set RBP at 3177' and load casing attempt to PT, leak 3/4 bpm at 1250#. reset RBP at 3077', attempt to PT, same leak; recover RBP; clean out with air from 3228' to 3267'; no tubing in well.

Ojo Alamo @ 1905'

Kirtland @ 2025'

Fruitland Coal @ 2856'

Pictured Cliffs @ 3220'

Pictured Cliffs Perforations:  
3222' - 3238' 16 holes

PBTD 3329'

6-3/4" Hole

2-7/8" 6.4#, J-55, Casing set @ 3340'  
Cemented with 270 sxs ( 512 cf)

TD 3340'

# Stickle #1

Proposed P&A

DPNO 5240601

Blanco Pictured Cliffs

NW Section 12, T-30-N, R-10-W, San Juan County, NM

Long: 107 deg. 50.27' / Lat: 36 deg. 49.86'

Today's Date: 5/6/99  
Spud: 4/13/77  
Completed: 5/5/71  
Elevation: 6621' (GL)  
Logs: C-DLC-GR, Ind.,  
Temp. Survey

12-1/4" Hole

8-5/8" 24#, J-55 Casing set @ 143'  
Cmt w/ 85 sxs (Circulated to Surface)

Perforate @ 193'

Plug #3 193' - Surface  
Cmt with 70 sxs Class B

TOC @ 1452' (Calc @ 75%)

Ojo Alamo @ 1905'

Plug #2 2075' - 1855'  
Cmt with 8 sxs Class B

Kirtland @ 2025'

Fruitland Coal @ 2856'

Plug #1 3170' - 2906'  
Cmt with 12 sxs Class B

Pictured Cliffs @ 3220'

Set CIBP @ 3170'

Pictured Cliffs Perforations:  
3222' - 3238' 16 holes

PBTD 3329'

6-3/4" Hole

2-7/8" 6.4#, J-55 Casing set @ 3340'  
Cemented with 270 sxs (512 cf)

TD 3340'