

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)


1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Salt Water Disposal well	7. Unit Agreement Name
2. Name of Operator Calvin Petroleum Corporation	8. Farm or Lease Name Kaempf SWD
3. Address of Operator c/o A. R. Kendrick, Box 516, Aztec, New Mexico 87410	9. Well No. #1
4. Location of Well UNIT LETTER N 790 FEET FROM THE South LINE AND 1500 FEET FROM THE West LINE, SECTION 19 TOWNSHIP 30N RANGE 11W NMPM.	10. Field and Pool, or Wildcat Basin-Dakota
15. Elevation (Show whether DF, RT, GR, etc.) 5644' GR	12. County San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Run tubing to 550'.
Pump 11 sack plug down tubing to be spotted from 568' to 168'. CO TD = 568'.
Pull tubing.
Perforate 2 7/8" casing @ 150' w/2 holes.
Circulate cement down 2 7/8" casing and up 5 1/2" casing to fill hole w/19 sacks.
Set marker.
Clean location.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ad Kendrick TITLE Agent DATE April 6, 1982
APPROVED BY Charles Gibson TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE APR 6 1982