UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

SF-080917

	Lease	Designation	and Serial No.	
5.	Lease	Designation	and Serial No.	

Do not use this form for proposale to drill or to decrea or recently to a different energy in	SF-080917
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT - " for such proposals PM 2: 0	6. If Indian, Allottee or Tribe Name
) If Unit or CA, Agreement Designation
Type of Well	
Oil S Gas Other	8. Well Name and No.
. Jame of Operator Attention:	Atlantic B LS #2A
AMOCO PRODUCTION COMPANY Gail M. Jefferson	9. API Weil No.
Address and Telephone No.	3004522988
P.O. BOX 800 DENVER, COLORADO 80201 (303) 830-6157	10. Field and Pool, or Exploratory Area
Cation of Well (Footage, Sec., T., R., M., or Survey Description)	Blanco Mesaverde
1010' FNL 990' FWL Sec. 4 T 30N R 10W UNIT D	11. County or Parish, State
1010 1145 990 7445 0000 1 1 0000 10 1000	SAN JUAN NEW MEXICO
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REP	ORT OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION	ONT, ON OTHER DATA
TITE OF SUBMISSION	
Abandorment	Change of Plans
Nation of Intent	New Construction
	Non-Routine Fracturing
	Water Shut-Off Conversion to Injection
Final Abandonment Notice Other Downshole Commingle	Dispose Water
(Nate: Report resu	ults of multiple completion on Well Completion or Recompletion Report and Log form.
	efferson for any administrative SEIVED V 1 6 1998 SON DIV
14. I hereby certify that the Megoing is true and correct Signed	Asst. Date 10-29-1998 Date NOV 1 0 1998
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, ficticious, or fraudulent statements or rep	resentations as to any matter within its jurisdiction.

Atlantic B LS #2A TD = 5656' PBTD = 5640' Page 2 of 2

- 1. Check anchors. MIRUSU.
- 2. Check and record tubing, casing and bradenhead pressures.
- 3. Blow down wellhead, kill if necessary.
- 4. Nipple down wellhead, nipple up and pressure test BOP.
- 5. Tally OH with 1.25" tubing.
- 6. Tally OH with 2.375" tubing.
- 7. TIH with tubing and bit.
- 8. Drill-out Model D packer (set at 3160') and TOH with tubing and bit.
- 9. TIH with tubing and packer-picker.
- 10. TOH with tubing, packer-picker, and packer.
- 11. TIH with 2.375" tubing, SN and notched collar on bottom, insure fill is below bottom perforation (5580'), clean-out fill if necessary and circulate hole clean.
- 12. Land 2.375" tubing at +/-5550'.
- 13. Put well back on production.

