State of New Mexico Submit 3 Copies to Appropriate District Office  State of New Mexico Energy, Minerals and Natural Resou	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION I P.O.Box 2088	DIVISION WELL API NO. 3004525559
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 875	04-2088  5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WEI  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN DIFFERENT RESERVOIR. USE "APPLICATION FOR PER  (FORM C-101) FOR SUCH PROPOSALS.)  1. Type of Well:	OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name
OIL GAS WELL OTHER  2. Name of Operator Attention:	8. Well No.
2. Name of Operator	Haefele 1E
Address of Operator     P.O. Box 800 Denver Colorado 80201	(303) 830-4988 9. Pool name or Wildcat Basin Dakota
4. Well Location Unit Letter D: 825 Feet From The North	Line and 1050 Feet From The West Line
occion = -	nge 11W NMPM San Juan County
10. Elevation (Show whether	5727' GR
11. Check Appropriate Box to Indicate N NOTICE OF INTENTION TO:	ature of Notice, Report, or Other Data SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON X	REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	CASING TEST AND CEMENT JOB
OTHER:	OTHER:
12. Describe Proposed or Completed Operations (Clearly state all pertinent detail work) SEE RULE 1103.	s, and give pertinent dates, including estimated date of starting any proposed
Amoco Production Company intends to plug and abandon the s	subject well per the attached procedure.
	PEGEIVED MAY - 1 1995
I hereby certify that the information above is true and complete to the best of m	me et a colonia
SIGNATURE Patty Haefele	
TYPE OR PRINT NAME Patty Haefele	TELEPHONE NO. (303) 830-4988
(This space for State Use)	. MAY - 1 1005
CONDITIONS OF APPROVAL IF ANY: AT  Notify (ACD) in time to	THE DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE MAY - 1 1995
Notify QCD intime to	

## . STATE OF NEW MEXICO NERGY AND MINURALS DEPARTMENT

## P. O. BOX 2088 SANTA FE, NEW MEXICO 87501

Form C-107 Revised 10-1-13


All distances must be from the cuter boundaries of the Section.

***************************************			Lease				Well No.
Operator  AMOGO PRODUCTION COMPANY			BRUINGTON GAS CON "C"				1E
AMOCO PRODUCTION COMPANY Unit Letter Section Township			Runge County			-	
	21	30N		11W	San Juan		and property of the state of th
Actual Footage Location		<u> </u>					
0	ot from the North	line and	1050	fe <sub>0</sub>	t from the Wes		Hine
Ground Level Elev:	Producing Formation		Pool			h -	ated Acreoger
5727	Dakota			Dakota	Annual Control of the	<del>بالسسس</del>	320 Дегал
1. Outline the a	one lease is dedicated to						It below. I (both us to working
3. If more than dated by com	one lease of differe munitization, unitiza ] No - II answer	is "yes;" type	of consolic	dation	Conmu	niLizatio	
this form if n	ecessary.)	the mall outil o	ll interests	s have been	consolidated (	by commun is been app	(Use reverse side of itization, unitization, moved by the Commission of the Commissi
In an annual consequence of the same	DO THE BUILD HAVE THE PARTY OF	THE PERSON NAMED IN COLUMN TWO DOES	CECHARIC PARTY	CALIFORNIA STATES		CI	RTIFICATION
1050' ©			 		// // // // // // // // // // // // //	tained herein best of my kno  no li H  no  1. H. SHO	y that the information con- is true and complete to the swiedge and belief. EMAKER
	 		 	and the second of the second o		ompany	ENGINEER DUCTION COMPANY 5, 1983
MA'	EIVED + 1 1995 DISTIL 3	21	J. J.	Divio Di	<b>V.</b>	shown on thi notes of act under my suj	
	 	:	CIL	13T. 3	1	December registred Promise Cand Cand's Fred B.	

Bruington Gas Com C 1E Orig. Comp. 7/83 TD = 6826', PBTD = 6779'

- 1. Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 3. POOH with 2 3/8" tbg.. RIH with tbg and cement retainer. Set retainer at 6500'. Test casing integrity to 500#.. Squeeze perfs at 6554' to 6756' with 122 cuft of cement. Pull out of retainer and spot cement plug to 5580' with 87 cuft cement. Pull up hole and spot cement plug from 3620' to 3720' (MV) with 9 cuft cement.
- 4. Pull up hole and place 100' plug at the following:
  Pictured Cliffs at 2010' to 2110'
  Fruitland Coal at 1700' to 1800'
  Ojo Alamo at 750' to surface.
  Estimated 90 cuft cement.
- 5. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 6. Turn over to John Schwartz for reclamation.
- 7. Rehabilitate location according to BLM or State requirements.

## BRUINGTON GAS COM C #1E Location — 21D — 30N — 11W Basin Dakota Orig.Completion — 7/83 LAST FILE UPDATE — 8/91 BY CSW



1 STAGE 431 CUFT CEMENT 118 CUFT TAILED 2ND STAGE 539 CUFT CEMENT 118 CUFT TAILED 3RD STAGE 1478 CUFT CEMENT 118 CUFT TAILED