

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

SF080212

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Malco Copple

9. WELL NO.

RD&P #5 MC

10. FIELD AND POOL, OR WILDCAT

Verde Gallup

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 5 T30N R15W

12. COUNTY OR PARISH 13. STATE

San Jaun

NM

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR

Reeves Drilling & Petroleum Corp.

3. ADDRESS OF OPERATOR

P.O. Box 1667 Farmington NM.

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface

1730' FNL and 1790' FWL Sec. 5 T30N R15W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5463 GR.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDISE

ABANDON*

SHOOTING OR ACIDISING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We intend to plug and abandon this well do to lost steel in hole, and apply for offset location.

The drill steel is stuck in the hole at 822', we plan to back off the first joint of drill pipe, at approximately 25' below surface and leave the rest of pipe in hole. Then place 200' plug of cement in top of hole. The depth of hole is still in the Mesa Verde formation. We would like to place a flat dry hole marker on the hole so that it will not interfere with offset operations.

RECEIVED
SEP 23 1985
OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

Jenny Reeves

TITLE

Pres.

APPROVED
DATE Sept. 17 1985
AS AMENDED

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE 2 2 0 1985

CONDITIONS OF APPROVAL, IF ANY:

John P. Miller
M. MILLENBACH
AREA MANAGER

See Instructions on Reverse Side