UNITED STATES

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Not	cices and Repor	ts on Wells	PH 2: 13	-	
		<u> </u>		5.	Lease Number SF-081098
Type of Well GAS					
				7.	Unit Agreement Name
2. Name of Operator MERIDIAN OIL				0	Maria C Number
3. Address & Phone No. of Opera	ator			8.	Well Name & Number Riddle E #3
PO Box 4289, Farmington, NI		326-9700		9.	API Well No. 30-045-26474
4. Location of Well, Footage,	Sec., T, R, M			10.	Field and Pool Blanco Pictured Cliffs
1040'FNL, 1460'FEL, Sec.4, '	T-30-N, R-9-W,	NMPM		11.	County and State San Juan Co, NM
12. CHECK APPROPRIATE BOX TO I	NOT CAME NAMIDE	OF NOTICE	REPORT.	OTHER	DATA
Type of Submission	T	ype of Act	ion		
X Notice of Intent	Abandonm	ent	Change	of Pla	ans
	Recomple	tion	New Con	struct	racturing
Subsequent Report	Plugging Casing R	enair	- Water S	hut of	ff
Final Abandonment	Altering	Casing	Convers	ion to	o Injection
	X_ Other -	Workover	_		
	-labed Omemotic				
13. Describe Proposed or Com					•
It is intended to workov		well accor	ding to t	he at	tached procedure and
wellbore diagram	•				the second second
				- 4	
				ş	
14. I hereby certify that th	ne foregoing is	true and c	correct.		
	(LWD5)Title			<u>Da</u>	te 6/27/95
(This space for Federal or Sta	ate Office use) Title			ate	<u> </u>
APPROVED BY CONDITION OF APPROVAL, if any:				_	APPROVED
				•	· · · · · · · · · · · · · · · · · · ·

WORKOVER PROCEDURE -- CLEAN OUT

Riddle E #3 Blanco Pictured Cliffs NE/4 Sec. 4, T30N, R9W San Juan Co., New Mexico

 Strip location for workover rig. Test location rig anchors and repair if 	necessary	1.
----------------------------------------------------------------------------------------------	-----------	----

- 2. MOL and RU coil tubing unit. Set flow-back tank and frac tank, and NU relief line to flow back tank. Fill frac tank as needed with 1% KCL water.
- 3. Comply to all NMOCD, BLM, and MOI regulations. Conduct safety meeting for all personnel on location.
- 4. Test coil tubing BOP's and all surface equipment.
- 5. Gauge ring ran 3-8-95 and tagged fill @ 3027'
- TIH with Baker Inflatable Hole Hunter (2 7/8", 6.5#) and set @ 2900'. PT casing to 500# psi. (Notify Operations Engineer with test results). Isolate and squeeze any leaks. POH with Hole Hunter.
- 7. RU Nitrogen unit and test surface lines. TIH with high velocity wash tool to the top of sand and clean out to PBTD (3081') with Nitrogen Foam wash.
- 8. Pull up hole to 2900' and allow well to flow 2 hours. Go back to bottom to check for fill.
- 9. If no fill is present and well is flowing, POOH and rig down coil tubing unit.
- 10. Release coil tubing unit.

	·		
	Recommended: O	perations Engineer	
	Approval:P	roduction Superintendent	
Contacts	Operations Engineer	Larry Dillon	326-971 4

PERTINENT DATA SHEET 4/20/95

				_				
WELLNAME:	Riddle E #3				DP NUMBER: PROPERTY NUMBER:	54242A 012563300		
WELL TYPE:	Blanco Pictured C	liffs			ELEVATION:	GL: 6151' KB: 6163'		
LOCATION:	1040' FNL, 146 Sec. 4, T30N, R9 San Juan County,		0		INITIAL POTENTIAL: INITIAL SITP: CURRENT SICP:	AOF 12/85 1,036	Mcf/d psig psig	
OWNERSHIP:	GWI: NRI: SJBT:	100.0000% 83.5000% 0.0000%			DRILLING:	SPUD DATE: COMPLETED: TOTAL DEPTH: PBTD:		08-13-85 12-11-85 3100' 3081'
CASING RECORD:								
HOLE SIZE	<u>SIZE</u>	WEIGHT	GRADE	DEPTH	EQUIP.	CEMENT	_	тос
12 1/4"	8-5/8"	24#	K55	233'	-	153 cf	Circ.	Surface
6 3/4"	2 7/8"	6.5#	K55	3091'	8RD - EUE	747 cf	Circ.	Surface
FORMATION TOPS:	Nacimiento Ojo Alamo Kirtland Fruitland Pictured Cliffs Chacra Cliffhouse Menefee		1600' 1750' 2550' 2938'		Point Looko Gallup Greenhorn Graneros Dakota	ut		
LOGGING:	Correlation-GR; Induction Electrolog; Comp. Densilog, Comp. Neutron-GR; Ind. Elec-GR							
PERFORATIONS	2950', 2957', 2963	3', 2971', 297	79', 2987',	2995', 30	003', 3011', 3019', 3041', 305	8' w/1 spz (Total of12	holes)	-
STIMULATION:	77,000# 10/20 sarıd & 84,960 gal. treated water							
WORKOVER HISTORY:	None							
PRODUCTION HISTORY: Cumulative as of 1995: Current:	<u>Gas</u> 21.8 MMcf 0 Mcf	<u>Qil</u> 0 Bo 0 Bo			DATE OF LAST PRODUCT	ION: <u>Gas</u> per, 1992 17 Mcf	QII 0 Bo	
PIPELINE:	EPNG							4.5

Riddle E #3

The second secon


CURRENT -- 4-20-95

Blanco Pictured Cliffs DPNO 54242A

1040' FNL, 1460' FEL, Section 4, T-30-N, R-9-W, San Juan County, NM

Spud: 8-13-85

Completed: 12-11-85



PBTD 3081

TD 3100'

8-5/8", 24#, K55 Csg set @ 233' Circulated 153 cf cmt to surface

Fruitland @ 2550'

Ojo Alamo @ 1600'

Kirtland @ 1750'

Pictured Cliffs @ 2938'

Perf @ 2950', 2957', 2963', 2971', 2979', 2987', 2995', 3003', 3011', 3019', 3041', 3058' w/1 spz (Total of 12 holes)

2 7/8", 6.5#, K55, Csg set @ 33091', cmt w/747 cf cmt. Circ. to Surface