### UNITED STATES

# DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Noti	ces and Reports on Wel	ls		
			5.	
l. <b>Type of Well</b> GAS	<b></b>	ing very 1899	6.	SF-081098 If Indian, All. or Tribe Name
			7.	Unit Agreement Name
2. Name of Operator				
MERIDIAN OIL			8.	Well Name & Number
3. Address & Phone No. of Operat				Riddle E #3
PO Box 4289, Farmington, NM	87499 (505) 326-9700		9.	<b>API Well No.</b> 30-045-26474
4. Location of Well, Footage, Sec., T, R, M 1040'FNL, 1460'FEL, Sec.4, T-30-N, R-9-W, NMPM			10.	Field and Pool Blanco Pictured Clift
, , ,	·		11.	County and State San Juan Co, NM
12. CHECK APPROPRIATE BOX TO IND	ICATE NATURE OF NOTICE	. REPORT.	OTHER	DATA
Type of Submission	Type of Ac			
X Notice of Intent	Abandonment	X Change	of Pla	ans
Caller and the Daniel	Recompletion	New Con	struci	tion Fracturing
Subsequent Report	Plugging Back _ Casing Repair	Water S		
Final Abandonment	Altering Casing			
<del></del>	X Other - Workover			
13. Describe Proposed or Compl	eted Operations			
Attached is a revised proc procedure was appro		of the su	bject.	well. The original
		ר ה		7 0 v a
		[D]		图 人 医 少
		171	AHO	3 DIVI
			AUG :	3 1995
		<b>@</b>   [	. ලබ	M. DAV.
		~ <u>~</u>		100 1011/0
			שפש	<b>₫</b> 0 <b>②</b>
14. I hereby certify that the	foregoing is true and	correct.		
Signed Day Stalkuld	(LWD5)Title Regulato	ry Adminis	trato	<u>r</u> Date 7/21/95
(This space for Federal or State	e Office use)			
APPROVED BY CONDITION OF APPROVAL, if any:	Title	Da	te 🐴	PROVED
, <u>-</u>				3 1 1995

#### **WORKOVER PROCEDURE -- CLEAN OUT**

### Riddle E #3 Blanco Pictured Cliffs NE/4 Sec. 4, T30N, R9W San Juan Co., New Mexico

1.	Strip location	for coil	tubing	unit.
----	----------------	----------	--------	-------

- 2. MOL and RU coil tubing unit. Set flow-back tank, and NU relief line to flow back tank. Either a frac tank or water trunks may be used.
- 3. Comply to all NMOCD, BLM, and MOI regulations. Conduct safety meeting for all personnel on location.
- 4. Test coil tubing BOP's and all surface equipment.
- 5. Gauge ring ran 3/95 and tagged fill @ 3027'.
- 6. TIH with a mechanical set packer (2 7/8", 6.5#) and set @ 2900'. PT casing to 500# psi. (Notify Operations Engineer with test results). If casing fails go to step 6a & b, if casing test OK go to step 7.
  - 6a. Isolate and squeeze any leaks using a drillable bridge plug and mechanical packer.
  - 6b. Drill out cement with downhole motor and PT squeeze holes. Drill out BP and continue to clean-out to PDTD (3081') with 1% KCL water. If circulation is lost, pump nitrogen foam and continue to clean-out. (Continue to step 8)
- 7. POOH and LD packer. RU Nitrogen unit and test surface lines. TIH with high velocity wash tool to the top of sand and clean out to PBTD (3081') with Nitrogen Foam wash.
- 8. Pull up hole to 2900' and allow well to flow. Go back to bottom every 30 minutes to check for fill.
- 9. If no fill is present and well is flowing, POOH and rig down coil tubing unit.
- 10. Release coil tubing unit.

Recommended:
Operations Engineer
Approval:
Production Superintendent

Contacts:

Operations Engineer

Larry Dillon

326-9714

## **PERTINENT DATA SHEET**

4/20/95

WELLNAME:	Riddle E #3				DP NUMBER:	5	4242A		
					PROPERTY NUMBER:	0	12563300		
WELL TYPE:	Blanco Pictured	Cliffs			ELEVATION:	GL: KB:	6151' 6163'	-	
LOCATION:	1040' FNL, 14 Sec. 4. T30N. R San Juan Count		o		INITIAL POTENTIAL:  INITIAL SITP:  CURRENT SICP:	AOF 12/85	1,036	Mcf/d psig psig	
OWNERSHIP:	GWI: NRI: SJBT:	100.0000% 83.5000% 0.0000%			DRILLING:	co	PUD DATE: MPLETED: AL DEPTH: PBTD:		08-13-85 12-11-85 3100' 3081'
CASING RECORD:									
HOLE SIZE	SIZE	WEIGHT	GRADE	DEPTH	EQUIP.	CI	EMENT	-	тос
12 1/4"	8-5/8"	24#	<b>K5</b> 5	233'	-	1	53 cf	Circ.	Surfac
6 3/4"	2 7/8"	6.5#	K55	3091'	8RD - EUE	7	<b>74</b> 7 cf	Circ.	Surfac
FORMATION TOPS:	Nacimiento Ojo Alamo Kirtland Fruitland Pictured Cliffs Chacra Cliffhouse Menefee		1600' 1750' 2550' 2938'		Point Looko Gallup Greenhorn Graneros Dakota	out			
LOGGING:	Correlation-GR;	Induction Elec	ctrolog; Co	omp. Den	silog, Comp. Neutron-GR; Ir	nd. Elec-GR			
PERFORATIONS	2950', 2957', 29	63', 2971', 29	79', 2987',	2995', 3	003', 3011', 3019', 3041', 30	58' w/1 spz	(Total of12	holes)	
STIMULATION:	77,000# 10/20 s	sand & 84,960	gal. treate	ed water					
WORKOVER HISTORY:	None								
PRODUCTION HISTORY: Cumulative as of 1995: Current:	<u>Gas</u> 21.8 MMcf 0 Mcf	<u>Oil</u> 0 Bo 0 Bo			DATE OF LAST PRODUC	TION:	Gas 17 Mcf	Qil 0 Bo	
PIPELINE:	EPNG								<del></del>

### Riddle E #3


### **CURRENT -- 4-20-95**

### Blanco Pictured Cliffs DPNO 54242A

1040' FNL, 1460' FEL, Section 4, T-30-N, R-9-W, San Juan County, NM

Spud: 8-13-85

Completed: 12-11-85



8-5/8", 24#, K55 Csg set @ 233' Circulated 153 cf cmt to surface

بالغاد والمحجوبة والمستجددة أتحالف

Ojo Alamo @ 1600'

Kirtland @ 1750'

Fruitland @ 2550'

Pictured Cliffs @ 2938'

Perf @ 2950', 2957', 2963', 2971', 2979', 2987', 2995', 3003', 3011', 3019', 3041', 3058' w/1 spz (Total of 12 holes)

2 7/8", 6.5#, K55, Csg set @ 33091', cmt w/747 cf cmt. Circ. to Surface

TD 3100'