



GARREY CARRUTHERS  
GOVERNOR

STATE OF NEW MEXICO  
**ENERGY AND MINERALS DEPARTMENT**  
OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO 87410  
(505) 334-6178

March 26, 1987

Mr. Bob Frank  
Union Texas Petroleum Corp.  
375 US Highway 64  
Farmington, NM 87401

Re: Haynie #2M E-04-30N-11W

Dear Bob:

According to the latest cement bond log, the cement top does not adequately cover the Mesaverde formation. You are hereby directed to re-enter the well and begin remedial work to correct the deficiency, bringing the cement top up at least 50' above the Mesaverde or 3758'. Please contact this office prior to commencing work, so that someone can witness the operation.

If you have any questions, please contact me.

Yours truly,

A handwritten signature in cursive script, appearing to read "Ernie Busch".

Ernie Busch  
Geologist/Deputy Oil & Gas Inspector

EB/dj

xc: E. Busch  
Well File  
Operator File