FORM APPROVED Form 3160-5 UNITED STATES Budget Bureau No. 1004-0135 DEPARTMENT OF THE INTERIOR (June 1990) Expires: March 31, 1993 **BUREAU OF LAND MANAGEMENT** 5. Lease Designation and Serial No. SF-081089 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT - " for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE Type of Well <u>San Juan 32-8 Unit</u> ell Name and No. X Gas 2. Name of Operator **32-8 Unit #237** Phillips Petroleum Company . API Well No. 3. Address and Telephone No. 30-045-28209 5525 Highway 64, NBU 3004, Farmington, NM 87401 Field and Pool, or exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) DIST. 3 Unit G, 1790' FNL & 1093' FEL Basin Fruitland Coal Section 23, T31N, R8W 11. County or Parish, State San Juan. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 12. TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Change of Plans Recompletion New Construction Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off Final Abandonment Notice Altering Casing Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Plans are to pull the tubing and liner and cleanout to TD, then recavitate the coal interval. We will RIH with a new 5-1/2" liner, perforate, land tubing and return well to production. A brief description of the work planned is as follows: MIRU. Install BPV & ND WH. NU & test BOP. Retrieve BPV. POOH w/tubing. RIH w/bit on 2-7/8" DP & cleanout to TD. PU & recaviate coal interval. POOH. RIH w/new 5-1/2" 15.5# J-55 liner with hanger. Set liner on bottom. Set hanger. RU wireline and perforate the liner. RIH w/tubing and land. Set BPV. ND BOP & NU WH. Retrieve BPV & return well to production. A 25' X 60' liner (3 sided fenced) pit will be utilized during workover. 14. I hereby certif (This space for Federal or State office use) Approved by Conditions of approval, if any: Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction