Submit 3 Copies To Appropriate District Office	State of New Mexico				Form C-103
District I	Energy, Minerals and Natural Resources			····	Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.	
District II	OIL CONSERVATION DIVISION			30-045-28979	
811 South First, Artesia, NM 88210				5. Indicate Type	of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.			STATE	FEE 🛛
District IV	Santa Fe, NM 87505			6. State Oil & G	
1220 S. St. Francis Dr., Santa Fe, NM		,		o. State Off & O	ras Lease No.
87505				<u> </u>	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK 2002					
DIFFERENT RESERVOIR. USE "APPLIC	SALS TO DRILL OR TO DEEP	EN OR PLU	DG BACKSIMA	5	ļ
PROPOSALS.)	CATION FOR FERMIT (FORM	1 C-10 () FC	5 d 6 d 6 d 6 d 6 d 6 d 6 d 6 d 6 d 6 d	Lorra	ine Gas Com
1. Type of Well:		1		[정]	
	Other		CIST. 8		
2. Name of Operator		100	<u></u>	8. Well No.	
BP America Production Company	Attn:	Mary &	rieu a 1 🕅	70. WOM 110.	19
3. Address of Operator	7()11)	<i>711.01</i> 7 00	S. V.	9. Pool name or V	
•	77253				in Dakota
4. Well Location	77233			Dus	III Dakota
4. Wen Location					
Unit Letter D	1170 feet from the	Nionth	line and 1000	fact from the	West line
Unit Letter D 1170 feet from the North line and 1090 feet from the West line					
Section 26	Township 30N	Range	08W N	IMPM San Jua	n County
Section 20	10. Elevation (Show w				County
	10. Lievation (Show wi	588			
11 Check A	nnronriate Roy to Ind		· · · · · · · · · · · · · · · · · · ·	Penort or Other	Data
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
				BSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🔲		REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRIL	LING OPNS.	PLUG AND
TEMPORARIET ABANDON			ABANDONMENT		
PULL OR ALTER CASING	MULTIPLE		CASING TEST AND		
	COMPLETION		CEMENT JOB		
OTHER:			OTHER:		
	1 (0)	. 11			
12. Describe proposed or complete					
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion					
or recompilation.					
BP America respectfully request permission to temporarily abandon the subject well as per the attached procedure.					
or reflection to specifying request permission to rempetating abundant the subject went as per the arrabited procedure.					
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
M//n.,	11/1/11				
SIGNATURE ////	TI'	TLESr	. Regulatory Analy	vst DATE	03/18/2001
Type or print name Mary Corle	2y /			Telephone No. 2	281-366-4491
(001	' 			1	
(Time space for otherwise)	EX CHANGE T. PERSON	9	PUTY BE & EAS IN	SPECTER RIFE AG	MAR 1 9 2002
APPPROVED BY		TITLE	·	ome atto a original (40 TO 1 a 東野家	DATE DATE
Conditions of approval, if any:			.,		


Lorraine GC #1Y Plugback Procedure

Procedure:

- 1. Check anchors. MIRU workover rig.
- 2. Check and record tubing, casing, and bradenhead pressures.
- 3. Blow down wellhead. Kill with 2% KCL water ONLY if necessary.
- 4. Nipple down WH. NU BOPs.
- 5. TOH with 2-3/8" production tubing currently set a 7354'.
- 6. TIH with 4-1/2" tubing-set CIBP. Set CIBP at 7300'.
- 7. Load wellbore with inhibited 2% KCL. Pressure test casing to 500 psi.
- 8. Spot 50' cement plug on top of CIBP.
- 9. TOH and LD 2-3/8" tubing.
- 10. ND BOP's. NU WH. Leave well in T&A'd status.

Lorraine GC #1Y

Sec 26, T30N, R8W API # 30-045-28979



NOTES:

- 1) Major drilling problems encountered drilling this well to the Morrison
- 2) Liner top produced cement which caused tubing to become stuck Problem was corrected during 1994 workover.