ASA ULIMALII	is to drill or to deepen or reentry to a different reservoir. ON FOR PERMIT - " for such proposals	6, If Irelian, Allottes or Tribe Name
		7, If Unit of CA, Agreement Designation
Type of Well		E. Woll Name and No.
Office State Office		Northeast Blanco Unit #30
Name of Operator	Attention: Patty Haefele	S. API Well No.
Amoco Production Company Address and Telephore No.	Fatty Hacicie	3004528985
	CO 80201 (303) 830-4988	
P.O. Box 800, Denver,		10. Field and Pool, or Exploretory Area Gallery Book 9
, Legation of Wall (Footage, Sec., T., R., M., or Sun		11. County or Parish, State
1070' FNL 1025' FEL	Sec. 33 T 31N R 7W	San Juan New Mexico
CHECK APPROPRIAT	E BOX(s) TO INDICATE NATURE OF NOTIC	E , REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACT	TION
	<u>~</u>	П
Nedge of Intent	Abendonment	Change of Plans New Construction
Notice of Interk	Recompletion Plugging Sack	Non-Routine Frecturing
Subsequent Report	Caving Repair	Weter Stut-Off
	Altering Casing	Conversion to Injection Dispose Water
Final Abandonment Notice	Uther	her Report results of multiple completion on Well Completion or completion Report and Log form. }
Amogo Production Company	requests permission to plug and abandon this well per	I starting any proposed work . If well is directionally drilled, give the attached procedure.
Amogo Production Company	ILEM GODERN (OL MI INDEPAND ME VALUE DA MINISTER AS THE COMMITTEE OF THE C	the attached procedure. APR 2 5 503
Amoco Production Company	requests permission to plug and abandon this well per proval on 4/3/96 at 3:55 a.m. for this abandonment.	the attached procedure. AFR 2 5 503

* See Instructions on Reverse Side

NMOCD

APPROVED
APPRES 1996

NEBU 308 Orig. Comp. 9/93 TD=8172 PBTD 7932 Page 2 of 2

- 1. RIH with tbg and spot cement plug from 7932' to 7795' with 17 cuft cement. POOH RIH with tbg and cement retainer and set retainer at 7410'. Squeeze perfs at 7460' to 7530' with 100' plus 100% excess (31 cuft cement). Place 150' plug inside casing (13 cuft cement). Spot 50' cement plug on top. (5 cuft cement)
- RIH with CIBP and set at 6479' (on top on the 4 1/2" liner). Spot 50' cement plug on top of CIBP (11 cuft cement). Pull up hole and spot cement plugs as follows, 5340' to 5240 (MV), 3525 to 3425 (PC), 3238 to 3138 (FT), 2569 to 2368 (OJ), 1134 to 1034 (NM), and 445 to surface with 232 cuft cement.
- 4. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 5. Contact FMC and ship surface equipment to yard or other location per instructions.
- 6. Turn over to John Schwartz for reclamation.
- 7. Rehabilitate location according to BLM or State requirements.