Form 3150-5 (August 1999)

## UNITED STAFES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED	
OMB NO. 1004-0135	į
Expires: November 30-2	n

Э.	Lease Serial No.
	NMSF080597

		REPORTS O	
Do not use this	form for propo	sals to drill or	to re-enter∕an
Do not use this abandoned well.	Use form 3160	0-3 (APD) for si	uch proposals.

De met wee this	141VIST 000337								
Do not use thi abandoned wei	6. If Indian, Allottee or Tribe Name								
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agree	ement, Name and/or No.			
Type of Well     Oil Well	a a r			8. Well Name and No. GARTNER A 2R					
2. Name of Operator		MARY CORL		9. API Well No.					
BP AMERICA PRODUCTION		@bp.com		30-045-29137-00-S1					
3a. Address P. O. BOX 3092 HOUSTON, TX 77253		(include area code .4491 0700	)	10. Field and Pool, or Exploratory BLANCO MESAVERDE					
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description,	)			11. County or Parish, and State				
Sec 28 T30N R8W NWNE 079 36.78769 N Lat, 107.67792 W				SAN JUAN COL	NTY, NM				
12. CHECK APPE	ROPRIATE BOX(ES) TO	INDICATE I	NATURE OF I	NOTICE, RI	EPORT, OR OTHE	R DATA			
TYPE OF SUBMISSION			ТҮРЕ О	F ACTION					
Matica of Intent	☐ Acidize	☐ Deep	en	☐ Product	ion (Start/Resume)	■ Water Shut-Off			
☑ Notice of Intent	☐ Alter Casing	☐ Fracti	ure Treat	□ Reclam	ation	■ Well Integrity			
☐ Subsequent Report	☐ Casing Repair	□ New	Construction	☐ Recomp	olete	Other			
☐ Final Abandonment Notice	☐ Change Plans	Plug	and Abandon	☐ Tempor	arily Abandon	Workover Operations			
_	☐ Convert to Injection	□ Plug l		☐ Water I	=				
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  BP America respectfully request permission to add pay in the subject well as follows:  1. Check anchors. MIRU workover rig.  2. Kill w/2% KCL WTR if necessary. NDWH. NU BOPs & diversion spool w/3" outlets & 3" pipe to the blow tank. Pressure test BOPs to 500 psi.  3. Tag for fill & tally OH w/2-3/8" production TBG. Visually inspect TBG while POOH.  4. TIH with bit and scraper for 7" liner to 5229'.  5. TIH with tubing-set RBP. Set RBP at 5200'. Load hole with 2% KCL.  6. Dump 50' sand on top of RBP. Pressure test casing to 2500 psi.  7. RIH w/ CBL/VDL/GR log.  8. RIH w/3-1/8" casing guns 1 SPF 120 deg phasing with Schlumberger's Prospector, select-fire charge. Perforate Menefee (correlate to GR log).  9. RU frac equipment & install wellhead isolation tool. Use 2% KCL-N2 foam in fracture									
, , ,	# Electronic Submission # For BP AMERICA ## Committed to AFMSS for processing to the committed to a second committed committed to a second committed com	A PRODUCTION essing by Marti	I CO, sent to the new Halbert on	e Farmingtor 10/03/2002 (0	1 ້				
The state of the s			7.0.110						
Signature (Electronic S	Submission)		Date 09/23/2	002	,				
	THIS SPACE FO	R FEDERAI	OR STATE	OFFICE U	SE				
Approved By Conditions of approval, if any, are attached	d. Approval of this notice does		Title Potiti	J. Eng.		OCT 9			
certify that the applicant holds legal or equ which would entitle the applicant to condu		subject lease	Office BI	M-FFC	)				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## Additional data for EC transaction #14468 that would not fit on the form

## 32. Additional remarks, continued

stimulation.

- sumulation.

  10. Frac Menefee according to pump schedule.

  11. Flowback frac fluid immediately.

  12. RIH and set CIBP above top of Menefee perforations.

  13. RIH with 3-1/8" casing guns 1 SPF 120 deg phasing with Schlumberger's Prospector, select-fire charge. Perforate Cliffhouse (correlate to GR log).

  14. RU frac equipment and install wellhead isolation tool. Use 2% KCL-N2 foam in fracture stimulation.
- stimulation.

15. Frac the Cliffhouse according pump schedule.

16. Frac the Cliffnouse according pump schedule.

16. Flowback frac fluid immediately.

Note: The number of frac stages will be determined after receiving the log result. If possible, the frac job will be performed in 1 stage to save cost.

17. TIH with tubing and bit. Cleanout CIBP. POH.

18. RIH with RBP pulling tool. POH with RBP.

19. RIH with open ended work string and clean out well as deep as possible. Blow well dry with air at that dooth

- at that depth.

  20. RIH with 2-3/8" production tubing and land.
- 21. Swab water from the tubing with the sandline.22. ND BOP's. NU WH. Test well for air. Return well to production.

## Gartner A 002R

Sec 28, T30N, R8W

