


F. Loc. 1750'N; 1150'E Elev. 6080'DF Spd. 2/15/54 Comp. 3/15/54 ID 5117 PB
 Casing S. 9-5/8 @ 173 W 125 Sx. Int. @ W Sx. Pr. 7" @ 4900 W 500 Sx. T. 2" @ 5090'
 Csg. Perf. SOF 4900-5117 Prod. Stim.

I.P. 3937 ~~2576~~ MCF/D After 3 Hrs. Sic. P. 992 PSI After 7 Days GOR Grav. 1st Del. 7/1/54 TRANS EPNG

TOPS		NITD	X	Well Log	✓	TEST DATA						
Kirtland	1992	C-102		Plat	X	Schd.	PC	Q	PW	PD	D	AIL
Fruitland	2396	C-103		Electric Log	X							
Pictured Cliffs	2722	C-104	X	C-110	X	54	784	720	431	392	760	
Cliff House	4337					55	795	310	512	398	373	
Menefee	4476			Remarks 		11/5/53	761	245	524	381	346	
Point Lookout	4963					11/23/53	710	366	455	355	367	
Mancos							58					
Tocito						11/4/53	832	511	117	117	387	
Dakota												
Morrison												
Entrada												
	3357											

P
o Blanco MV Co. San Juan S 31 T 31N R LOW U H Oper. EPNG Lse. Atlantic No. 3-C
o