NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Notice of Intention to Change Plans	Notice of Intention to Temporarily Abandon Well	XXX	Notice of Intention to Drill Deeper	
Notice of Intention to Plug Well	Notice of Intention to Plug Back		Notice of Intention to Set Liner	
Notice of Intention to Squeeze	Notice of Intention to Acidize		Notice of Intention to Shoot (Nitro)	
Notice of Intention to Gun Perforate	Notice of Intention (Other)		Notice of Intention (Other)	
OIL CONSERVATION COMMISSION SANTA FE, NEW MEXICO	Farmington (Place)	, Nev M	exico December	13, 1961
Gentlemen: Following is a Notice of Intention to do	carrain work as described below	at the	Beaver Lodge State	1
El Paso Natural Gas Co	monny		2	<u>.</u> A
NE /4 NB /4 of Sec. 36	Lee!	Je	73 W 17-	(Unit)
(40-acry Subdivision) San Juan	, T. 31N , R. 11W	, NMP M	I, BIRNCO MESA VO	Pool Pool
(FOLLOW It is intended to temporarily Move in pulling unit. See Attempt to pull tubing.	t tubing choke at about tubing is free, pu	JLES AND the followt 5450	REGULATIONS) Llowing manner:	iron bridge
(FOLLOW It is intended to temporarily 1. Move in pulling unit. Se 2. Attempt to pull tubing. plug with dump bailer. N	INSTRUCTIONS IN THE RI abandon this well in t tubing choke at abo If tubing is free, pu ipple up Wellhead. choke and cut tubing ning 2% calcium Chlor ubing. If plug is 0.	JLES AND the followt 5450 Ill and I 50' - 10 Ide. Po	REGULATIONS) Llowing manner: Lay down. Run cast Oo' below 7" casing all 20 joints and wa	with acid cutte
(FOLLOW It is intended to temporarily L. Move in pulling unit. Se 2. Attempt to pull tubing. plug with dump bailer. N 3. If tubing is stuck, pull Spot 100 sack plug contai 6 hours. Tag plug with t	INSTRUCTIONS IN THE RI abandon this well in t tubing choke at abo If tubing is free, pu ipple up Wellhead. choke and cut tubing ning 2% calcium Chlor ubing. If plug is 0.	JLES AND the followt 5450 Ill and I 50' - 10 Ide. Po	REGULATIONS) Llowing manner: Lay down. Run cast 00' below 7" casing all 20 joints and was lown 10 joints and 1	with acid cutted it on cement ceave remainder
(FOLLOW It is intended to temporarily 1. Move in pulling unit. Se 2. Attempt to pull tubing. plug with dump bailer. N 3. If tubing is stuck, pull Spot 100 sack plug contai 6 hours. Tag plug with t of tubing hanging. Nippl	INSTRUCTIONS IN THE RU abandon this well in t tubing choke at about tubing is free, put ipple up Wellhead. choke and cut tubing ning 2% calcium Chlor tubing. If plug is 0. e up wellhead.	JLES AND the followt 5450 LL and 1 50' - 10 LL and 1 LL a	REGULATIONS) Llowing manner: Lay down. Run cast 00' below 7" casing all 20 joints and was lown 10 joints and 1	with acid cutte
(FOLLOW It is intended to temporarily 1. Move in pulling unit. Se 2. Attempt to pull tubing. plug with dump bailer. N 3. If tubing is stuck, pull Spot 100 sack plug contai 6 hours. Tag plug with t of tubing hanging. Nippl	INSTRUCTIONS IN THE RU abandon this well in t tubing choke at about tubing is free, put ipple up Wellhead. choke and cut tubing ning 2% calcium Chlor tubing. If plug is 0. e up wellhead.	JLES AND the followt 5450 LL and 1 50' - 10 LL and 1 LL a	REGULATIONS) Lowing manner: Lay down. Run cast 00' below 7" casing all 20 joints and wallown 10 joints and I	with acid cutted it on cement leave remainder
(FOLLOW It is intended to temporarily 1. Move in pulling unit. Se 2. Attempt to pull tubing. plug with dump bailer. N 3. If tubing is stuck, pull Spot 100 sack plug contai 6 hours. Tag plug with t of tubing hanging. Nippl	Instructions in the rule abandon this well in t tubing choke at about tubing is free, put ipple up Wellhead. choke and cut tubing ning 2% calcium Chlor tubing. If plug is 0. e up wellhead.	JLES AND The follows 5450 11 and 1 50' - 10 13e. Pa K. lay OR 1260 Petrole	REGULATIONS) Llowing manner: Lay down. Run cast 00' below 7" casing all 20 joints and was lown 10 joints and J RECE DEC 1: Vetural Gas Chipany	with acid cutted it on cement ceave remainder
(FOLLOW It is intended to temporarily 1. Move in pulling unit. Se 2. Attempt to pull tubing. plug with dump bailer. N 3. If tubing is stuck, pull Spot 100 sack plug contai 6 hours. Tag plug with t of tubing hanging. Nippl DEC 1 5 1964 Approved	INSTRUCTIONS IN THE RI abandon this well in t tubing choke at abo If tubing is free, pu ipple up Wellhead. choke and cut tubing ning 2% calcium Chlor abing. If plug is 0. e up wellhead. By By	ULES AND The followt 5450 ULL and I 50' - 10 Ide. Pa K. lay Carrelle Petrole	REGULATIONS) Llowing manner: Lay down. Run cast Oo' below 7" casing ill 20 joints and we lown 10 joints and I RECE DEC1 Natural Gas Chipary Company or operator.	with acid cutton cement ceave remainder
(FOLLOW It is intended to temporarily 1. Move in pulling unit. Se 2. Attempt to pull tubing. plug with dump bailer. N 3. If tubing is stuck, pull Spot 100 sack plug contai 6 hours. Tag plug with t of tubing hanging. Nippl Approved Except as follows: Approved OIL CONSERVATION COMMISSIONOr	INSTRUCTIONS IN THE RI abandon this well in t tubing choke at abo If tubing is free, pu ipple up Wellhead. choke and cut tubing ning 2% calcium Chlor abing. If plug is 0. e up wellhead. By By	ILES AND The follow 5450 Ill and I 50' - 10 Ide. Particle R. lay Petrole E. S. (REGULATIONS) Llowing manner: Ley down. Run cast Oo' below 7" casing all 20 joints and was lown 10 joints and 1 RECE DEC 1: Company or operator Company or operator	with acid cutted it on cement cove remainder

TANGER OF COMME
Resident Anna Comment
U.S. 20. 10. 10. 10. 10. 10. 10. 10. 10. 10. 1
TRANSPOLITER 103
PERFORM CITY OF THE CONTROL OF THE C