

30-045-10374

FE

F.Loc. 1095/N; 1075/E Elev. 5829 KB Spd. 10-356 Comp. 4/8/57 TD 1-905 PB 6742Casing S. 1074 @ 152 W 70 Sx Int. 7" @ 4378 W 150 Sx Pr. 4 1/2 @ 275 Sx T. 2 @ 1074

Csg. Perf.

Prod. Stim. 300 FJ 1688-6-119/40778 T. 275SWF 1000000, 900000I.P. 1494 MCF/D After 3 Hrs. SICP 992 PSI After _____ Days GOR _____ Grav. _____ 1st Del. 8-27-57 SHG

TOPS		NITD	Well Log	TEST DATA						
				Schd.	PC	Q	PW	PD	D	Ref. No.
Kirtland	<u>315</u>	C-102	Plot							
Fruitland		C-103	Electric Log							
Pictured Cliffs	<u>2124</u>	C-104	C-110							
Cliff House	<u>4460</u>		C-122							
Menefee		Ditr	Dfa							
Point Lookout		Datr	Dac							
Mancos	<u>4760</u>	Remarks m. 2. abandoned. E 320 DC-419 Formerly Colc. West.								
Tocito	<u>57</u>									
Dakota	<u>6676</u>									
Morrison	<u>6810</u>									
Entrada										

DC° Blanco MV Co SJ s 25 T 31N R 13W U A One Consolidated C & G Lse. Cain No. 1