16.

## UNITED STATES SUBMIT IN TRIPLICATE\* Other instructions on reverse side Other instructions on reverse side

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

NM 013642

OGICAL SURVEY	1


GEC	ノレしい	1CAL	SUL	VAE	1	

SUNDRY NOTICE  (Do not use this form for proposals to Use "APPLICATION")		or plug back to a different res	+	IF INDIAN, ALLOTTEE	OR TRIBE NAME
OIL GAS X OTHER			7	. UNIT AGREEMENT NA	MR
. NAME OF OPERATOR			8	FARM OR LEASE NAM	E
Koch Exploration Compar	y (Division	of Koch Ind., Inc.	.)	GARDNER	
. ADDRESS OF OPERATOR			9	. WELL NO.	
P.O. Box 2256; Wichita,	Kansas 67	201		2	
LOCATION OF WELL (Report location clear)			1	O. FIELD AND POOL, OR	WILDCAT
See also space 17 below.) At surface			E	lanco Mesa Ve	erde
1775' FNL & 1550' FEL	SW NE		1	1. SEC., T., R., M., OR B SURVEY OR AREA	LK. AND
				Sec. 31-32N-	8W
4. PERMIT NO. 11	ELEVATIONS (Show	whether DF, RT, GR, etc.)	1	2. COUNTY OR PARISH	13. STATE
	GR 6516'	KB 6527'	9	San Juan	New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			r:					
		1		1	[			
TEST WATER SHUT-OFF		PULL OR ALTER CASING			WATER SHUT-OFF	Ri	PAIRING WELL	
FRACTURE TREAT		MULTIPLE COMPLETE			FRACTURE TREATMENT		TERING CASING	
SHOOT OR ACIDIZE		ABANDON*			SHOOTING OR ACIDIZING		BANDONMENT*	
REPAIR WELL		CHANGE PLANS			(Other) Completic			
(Other) Squeeze	off	perfs	X		(Note: Report resulting Completion or Recom	ts of multiple co apletion Report a	mpletion on Wel nd Log form.)	1

- 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*
  - Kill well w/water.
  - Pull 1-1/2" & 2-3/8" tbg string & Baker "AD" pkr now set @ 5049'.
  - Set ret BP @ 3550' & spot two sx sand on top.
  - Set pkr @ 3300' & squeeze P.C. perfs 3433-3489 w/200 sx cmt.
  - Reset pkr @ 2900' & WOC 6 hrs; squeeze Fruitland perfs 3068-3110 w/200 sx cmt.
  - 6. Drill out cmt. Test csg to 1000#.
  - 7. Pull ret BP & run prod tbg.
  - Swab well in & blow dry. 8.
  - Complete as Mesa Verde gas well only.



			DIST.	`/
18. I hereby certify that the foregoing is tout and correct				
SIGNED Owall & Schmidt	TITLE	Operations Manager	_ DATE	9-7-77
(This space for Federal or State office use)				
APPROVED BYCONDITIONS OF APPROVAL IF ANY:	TITLE _		_ DATE	