Form 3160-5

UNITED STATES

FORM APPROVED Budget Bureau No. 1004-0135

June 1990)	DEPARTMENT BUREAU OF L	Expires: March 31, 1993 5. Lease Designation and Serial No.				
		SF-080517				
Do not use	this form for proposals to dri	AND REPORTS ON WELLS II or to deepen or reentry to a different reservoir. R PERMIT—" for such proposals	6. If Indian, Allottee or Tribe Name			
	SUBMIT	7. If Unit or CA, Agreement Designation				
1. Type of Well	Gas		8. Well Name and No.			
Well Z Name of Operat	Well L Other		Holmberg Gas Com C #1			
•		n: John Hampton	9. API Well No.			
3. Address and Te	lephone No.		30 045 26216			
P.O. Box	800, Denver, Colorado	80201	10. Field and Pool, or Exploratory Area Cedar Hill Fruitland Basal Coal			
4. Location of We	ll (Footage, Sec., T., R., M., or Survey De	scription)	11. County or Parish, State			
1255' F	FNL, 1450' FEL, Sec. 2	28, T32N-R10W	San Juan, New Mexico			
12. CH	IECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA			
	PE OF SUBMISSION	TYPE OF ACTION				
	Notice of Intent	Abandonment	Change of Plans			
	, 110,000 0, 2,000	Recompletion	New Construction			
	Subsequent Report	Plugging Back	Non-Routine Fracturing Water Shut-Off			
[1	Casing Repair Altering Casing	Conversion to Injection			
L	Final Abandonment Notice	Other Perf & Frac	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			
	G. J. J. Downstone (Cheerly state a	Il pertinent details, and give pertinent dates, including estimated date of starting dates for all markers and zones pertinent to this work.)*				
13. Describe Propo give subst	or completed Operations (Clearly state a urface locations and measured and true vertice	cal depths for all markers and zones pertinent to this work.)*				
_	m 1 line Commons int	ends to perforate and fracture the upp	per Fruitland Coal.			
Amoco	production company inc tached for procedure:	ends to perforate and readers.				
see at						
VED	P. 2: 08		DECEIVE			
교	~ ·		JUN - 3 1992			
RECEIVE	13 TAN 21		OIL COM. DIV			
T£ 110	on Chy questions r	olease call Julie Acevedo at 303-830-6	D išt. 3 003.			
II yc	ou have any quescions p	, 10000 Cultural 1				
	•					
			•			
14. I hereby cert	ify that the foregoing is true and correct	a of Stadeshall Contra	Date 5/19/92			
Signed	Harpling got	Tide Sr. Staff Admin, Supv.	Date J/ 1/ /			
/	for Federal or State office use)	Title	APPROVED			
Approved by Conditions o	f approval, if any:		XX.			
		MMCCO	✓ JUN 01 1992			

PROCEDURE HOLMBERG GAS COM C 1

- 1. Record TP, CP, and bradenhead pressure.
- 2. MIRUSU.
- 3. Install BOP. Kill well with fresh water.
- 4. Pull rods and pump.
- 5. Lower tubing and clean out fill if necessary to 2870'.
- 6. Raise bottom of tubing to 2750'.
- 7. Pump, down tubing, $38\overline{00}$ gal of 15% HCl at 5 10 BPM. No diverter is required, displace with 20 bbl of fresh water. SI overnight.
- 8. Flow back or swab load for two days.
- 9. TOH with tubing.
- 10. TIH with RBP and set at 2800'.
- 11. Swab fluid level down to 2100' from surface.
- 12. Install frac head.
- 13. TIH with 4" casing gun and perforate the Fruitland Coal using 4 JSPF, 90 or 120 degree phasing, and 23 gram charges for the intervals 2588' - 93' and 2615' - 25'. Depths are correlated from Welex's Gamma Ray Log dated
- 14. RU fracture company. Frac well down casing at 60 BPM according to the attached procedure. SI overnight.
- 15. Blow well down.
- 16. TIH with tubing and retrieve RBP. TOH.
- 17. TIH with mule shoe, seating nipple, and 2 7/8" tubing. Slowly flow back load water from frac attempting to avoid sand production.
- 18. When there are no signs of fill entering the wellbore, land bottom of tubing at 2850'.
- 19. Run original rod and pump design.
- 20. Return well to production.

Note: All acid must contain 50 lb of citric acid per 1000 gal. of solution to serve as an iron sequestering agent.

FRACTURE STIMULATION PROCEDURE

Well Name: Holmberg Gas Com C 1 Upper Stage Frac

Formation: Fruitland Coal

Frac down: 5 1/2" casing/liner. Frac with: 20/40 mesh. Use Brady.

Packer set at :

PERFORATIONS :	:		top	INTERV	ALS bottom	FEET PERFED
	top	perf	2588 2615		2593 2625	5 10 0 0 0 0 0 0 0 0 0
		t	otal f	- Teet of	perforations	0 15

STA	.GE	FLUID TYPE (water)	FLUID VOLUME (gal.)	PROPPANT TYPE (mesh)	PROPPANT CONC. (ppg)	PROPPANI VOLUME (1b)	CUM. PROPPANT (1b)	BOTTOM HOLE RATE (bpm)	STAGE TIME (min)
 (pad)	1 2 3 4 5 6 7	slick slick slick slick slick slick slick	40,000 5,250 9,625 2,333 1,750 1,400 1,167		- 1 2 3 4 5 6	5,250 19,250 7,000 7,000 7,000 7,000	0 5,250 24,500 31,500 38,500 45,500 52,500	60 60 60 60 60 60	15.9 2.2 4.2 1.1 0.8 0.7 0.6
Total			62,000	gallons		52,500	IDS		23.4

NOTE: All slick water used in this procedure should contain 0.75 gal / 1000 gal of Western FR-28 friction reducer or equivalent. No other additives are required.

```
Casing capacity = 0.0232 bbl/ft. Liner capacity = bbl/ft. If no liner exists, leave blank. Liner top = ft. If no liner exists, leave blank. Casing vol. to top perf = 60.0 bbl. Flush w/ 55 barrels of water
```

Holmberg Gas Com C 1 Upper Stage Frac

Pertinent Data:

At 60 BPM, travel time from the wellhead to

the top perf is 1 min. and 0 sec.

Maximum treating pressure 4800 psi.

Have 5 400 bbl tanks of water

Tanks should be clean prior to filling. Water should be clean and filtered.

Sand bins should be cleaned prior to loading of sand.

Sand	sieve	analysis:			20/40	mesh
		less than	1%	less than	50	mesh
		less than	1%	greater than	16	mesh
		greater th	an	90% between	20/40	mesh