Form 3160-5 (June 1990)

Approved by

Conditions of approval, if any:

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

JUN 16 1995

BUREA			
	5. Lease Designation and Serial No.		
SUNDRY NO	NM-013686		
Do not use this form for prop	6. If Indian, Allottee or Tribe Name		
Use "APPLIC	ATION FOR PERMIT - " for such proposals		
		7 H H is a CA A second Decision	
		7. If Unit or CA, Agreement Designation	
1. Type of Well			
Oil See Well Other		8. Well Name and No.	
2. Name of Operator	Pritchard B 5		
Amoco Production Company	9. API Well No.		
3. Address and Telephone No.	3004526991		
P.O. Box 800, Denver, Colorad	10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or	Basin Fruitland Coal		
1840' FSL 1175FWI	11. County or Parish, State		
1640 F3L 1175FWL	San Juan New Mexico		
		<u> </u>	
.,	CE , REPORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF AC	TION	
		П	
Notice of Intent	Abendonment	Change of Plans	
Nouce of intent	Recompletion Plugging Back	New Construction Non-Routine Frecturing	
Subsequent Report	Casing Repair	Water Shut-Off	
	Altering Casing	Conversion to Injection	
Final Abandonment Notice	Other Liner	Dispose Water	
		lote; Report results of multiple completion on Well Completion or scompletion Report and Log form. )	
13. Describe Proposed or Completed Operations	  Clearly state all pertinent details, and give pertinent dates, including estimated date of	of starting any proposed work . If well is directionally drilled, give	
subsurface locations and measured and true	s vertical depths for all markers and zones pertinent to this work.}*		
		tod seeding	
Amoco Production Company	requests permission to perform liner work per the attack	nea procedure.	
Verbal approval on 6/14/95	from Wayne Townsend to Mike Kutas.	• <b>C</b>	
verbai approvai on o/14/55	Total Wayne Townsello to Wike Rutus.	SE JUN RE	
	en e	BLWED 15 PHI2: 42	
		6 - 3< 1	
		PHID: 12	
	<b>- 同居企管科</b>		
	UN 191	1995	
	JUN 1 3 1	1000 · ···	
		ENDAG	
	@NL G@N.		
	DITI. I	3	
14. I hereby certify that the foregoing is true and	covert		
Patt. Hook	C+nff	Assistant A P P.R 06V4-E9D	
Signed Talk	Title Starr	Assistant A P P.R 06V4-E9D	
(This space for Endered or State office (see)			

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fiction representations as to any matter within its jurisdiction.

Re: Pritchard "B" #5

Cleanout/Recavitation/Liner Proposal

Following steps are recommended based on data presented at the forum in SJOC on cavitation and the various meetings and phone conferences held during the last two weeks with and between the field personnel, the engineering group and the drilling groups. Please feel free to comment, cuss or discuss any one of the procedures. Due to the experimental nature of this procedure, I would recommend performing the job on either this well or the McEwen and strenuously evaluating the results prior to working on the second well.

- MIRURT--for this initial attempt, a drilling rig is recommended because of its greater versatility and capability. (If this is second well in series, usage of service unit should be discussed.
- 2. ND tree, rig up BOP's w/cavitation capability. Test BOE. TOH w/3.500" X 2.875" tapered tubing string laying it down.
- 3. Pick up 4.750" tricone bit, 3.750" drill collars, 500' of 2.875" drill pipe and fill out with 3.500" drill pipe. Clean out fill from 2,843' to total depth (3,013') using air and foam. Hole was underreamed during a recavitation in February, 1994, so should not be required again. Stabilize hole as quickly as possible to allow running liner (after reaching TD, trip out to casing shoe and wait for 4-6 hours and then check to determine amount of fill and how difficult it is to clean out.
- 4. Run 3.500", 9.3#/ft, J-55 EUE (if IJ tubing available, consider utilizing it as coupling OD of EUE is 4.500" and drift of 5.500" is 4.825" from TD back to 2,450'. Install a tri-cone bit on bottom with a float immediately above bit and a Baker Model SLR-P Liner Hanger Packer. Strip in hole and drill to bottom if necessary. Hang liner, lay down drill pipe. (Probably will use a full bore permanent packer to hang liner instead of hanger and packer.)
- 5. Perforate the uncemented liner as follows:

COAL ZONES		<u>PERFORATIONS</u>			
Ignacio	2,828 to 2,834	2,8262,856			
-6	2,850 to 2,854	2,8262,856	4 jspf	120 holes	
Cottonwood	2,882 to 2,903	2,8802,905	4	100	
Cahn #1	2,923 to 2,929	2,9212,931	4	40	
Cahn #2	2,984 to 3,000	2,9823,002	4	_80	
	-,-	•		340 holes	

6. Run 2.163" integral joint tubing to 3,000' with mule shoe on bottom and SN one joint from bottom with plug in place. Land tubing, ND BOE, NU tree and RDMORT. Retrieve plug and bring well on line slowly in attempt to minimize any cavitation effect.

Dependent on speed of hole stabilization, I estimate this procedure to require approximately 4 days and to cost \$95,000 (see attached AFE form).

Brad 06/07/95 4:33 PM