

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for each proposal.)

6. LEASE DESIGNATION AND SERIAL NO.

NM-013642

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NA

7. UNIT AGREEMENT NAME

NA

8. FARM OR LEASE NAME

Gardner-C

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Basin Fruitland Coal

11. SEC. T. R. M. OR BLK. AND SURVEY OR AREA

24-32N-9W

12. COUNTY OR PARISH

SAN JUAN

13. STATE

NM

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Koch Exploration Company

3. ADDRESS OF OPERATOR

3605 N. DUSTIN Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

1630'-F-SH + 1010'FWH.

14. PERMIT NO.

15. ELEVATIONS (Show whether BW, ST, OR, etc.)

GR. 6575'

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and source pertinent to this work.)

We have filed to drill this well through the coal and run & cement the pipe through the formation. We want to change the plan as follows. Drill 200' of 11 3/4" hole. Run 9 5/8" surface casing 200'. Cement with 87 sk. 100 cu. ft, 100% excess to circulate to surface. Drill 8 3/4" hole to top of coal zone. Run & cement 7" 26" casing at 3100 ft. with 1230 sks. 1475 Cu. ft. cement. 100% excess to circulate to surface. Drill 6 1/4" hole through the coal zone (3100' to 3450' Complete open hole, then run a 5 1/2" liner from 3050 to 3450 Do No cement.

RECEIVED

SEP 1 1990

OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED Delores H. Eckard TITLE Dist. Supt.

DATE 8-29-90

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

KOT TOWNSEND
FARMING