List wells with bradenhead gas casing failures or bradenhead		ells worked over be	ecause of
Operator AZTEC OIL & GAS COMPA	ANY Well Name HO	ORTON #1	
Elevation 6016 Well Location	Section 35-32N-11W		
Date of Completion 3-11-55 D	ate of Workover Compl	etion 10-17-63	
Surface Casing Set @ 161 Int	ermediate Casing Set	@ None Cement to	p Surface
Casing Circ. Cement Top Inter	mediate Casing		
Formation Tops: Ojo Alamo	1596	Pictured Cliffs	2736
Kirtland	1710	Levis	2820
Fruitland	23 20		
Reason for Workover Bradenhea	ud gas & water flow		
Method & Results of Workover	Perf. 7" casing at 1	.830 pumped in 150	sacks
Class C cement with Brader	head open. Squeezed	off perfs with 130	sacks
Class C cement and pumped	50 sacks dow n Br ad enh	nead. Shut off bot	h water
and gas at bradenhead			
Results of Bradenhead Test if A Duration of Blowdown or Volume of Blowdown or F. Analysis of Bradenhead (Flow Continuous Low Continuous		
Present Condition of Bradenhead	i Flow: Shut In C) Flowing	0
Gas Kicks while Drilling:	Depth	Magnitude of Light or Seve	
		HIGHT OF DOVE	

Page 1 - 1	englishmati-dise		
Remarks:			
		JAN 2 2 1964 DIL CON. COM. DIST. 3	