

Conditions of Approval

- 1) Wind socks phased at 90° will be required while commencing workover operation.
- 2) Blooie line with continuous pilot light required.
- 3) H₂S detection equipment must be calibrated and on hand during workover operations.
- 4) Contact this office should permanent abandonment or squeeze cementing operations be required.