UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	Sundry Noti	ces and Reports on W			
1. Ty	pe of Well GAS	Burea	RECEIVE APR 0.6 2000 u of Land Managem urango Colorado	5. Le I: T: T: I: T:	ease Number -22-IND-2772 f Indian, All. o ribe Name ndian nit Agreement Na
2. N a	me of Operator	b	Urango Colorado). U.	mit Agreement Na
4	URLINGTON ESOURCES		Olorado	AUA	
1	ESCORCES OIL	GAS COMPANY			••
3. Ad	dress & Phone No. of Operat	or			ell Name & Numbe te #12
	O Box 4289, Farmington, NM				PI Well No.
		······································	<u> </u>	_	0-045-11426
	cation of Well, Footage, Se 08'FSL, 1608'FWL, Sec.16, T				ield and Pool arker Creek
21	00 F3E, 1000 FWE, Sec.10, 1	-32-N, R-14-W, MMPM		11. C	ounty and State an Juan Co, NM
2. 0	HECK APPROPRIATE BOX TO IND	DICATE NATURE OF NOTI	CE, REPORT, OT	HER DA	TA
	pe of Submission	Type of			
	Notice of Intent	Abandonment	Change of		
	_	<pre> Recompletion</pre>	New Const	ructio	
	Y Subsequent Penort	Dlugging Rack	Non-Pouti	no Ero	aturina
	X Subsequent Report	Plugging Back Casing Repair	Non-Routi: Water Shu		cturing
	X Subsequent Report Final Abandonment	<pre>Plugging Back Casing Repair Altering Casing</pre>	Water Shu	t off	_
		Casing Repair	Water Shu	t off	_
L3.	Final Abandonment	Casing Repair Altering Casing _X_ Other - tubing	Water Shu	t off	_
13.		Casing Repair Altering Casing _X_ Other - tubing	Water Shu	t off	_
.3.	Final Abandonment Describe Proposed or Compl 3-14-00 MIRU. SDON.	Casing Repair Altering Casing _X_ Other - tubing eted Operations	Water Shu g Conversion repair	t off n to I	Injection
3.	Describe Proposed or Compl 3-14-00 MIRU. SDON. 3-15-00 ND WH. NU BOP. Pu	Casing Repair Altering Casing _X_ Other - tubing eted Operations amp 750 gal 15% HCL.	Water Shu g Conversion repair	t off n to I	Injection
3.	Final Abandonment Describe Proposed or Compl 3-14-00 MIRU. SDON.	Casing Repair Altering Casing X Other - tubing eted Operations amp 750 gal 15% HCL. cr. SDON.	Water Shu [Conversion repair Work stuck pip	t off n to I	njection s pkr. TOOH w/
.3.	Final Abandonment Describe Proposed or Compl 3-14-00 MIRU. SDON. 3-15-00 ND WH. NU BOP. Pu 2 7/8" tbg & pk 3-16-00 TIH w/bit, tag up @ 8689-8720'. C	Casing Repair Altering Casing X Other - tubing eted Operations amp 750 gal 15% HCL. cr. SDON. 0 @ 8689'. Pump 750 g	Water Shu y Conversion repair Work stuck pip yal 15% HCL. Dr	t off in to I e. Rls ill th	s pkr. TOOH w/
.3.	Final Abandonment Describe Proposed or Compl 3-14-00 MIRU. SDON. 3-15-00 ND WH. NU BOP. Pu 2 7/8" tbg & pk 3-16-00 TIH w/bit, tag up @ 8689-8720'. C 3-17-00 TIH w/269 jts 2 7	Casing Repair Altering Casing X Other - tubing eted Operations amp 750 gal 15% HCL. Cr. SDON. 0 @ 8689'. Pump 750 g CO to PBTD @ 8784'. T 1/8" 6.5# L-80 tbg, s	Water Shu Conversion repair Work stuck pip yal 15% HCL. Dr COOH w/bit. SDO set @ 8670'. 7"	t off in to I e. Rls ill th	s pkr. TOOH w/
13.	Final Abandonment Describe Proposed or Compl 3-14-00 MIRU. SDON. 3-15-00 ND WH. NU BOP. Pu 2 7/8" tbg & pk 3-16-00 TIH w/bit, tag up @ 8689-8720'. C 3-17-00 TIH w/269 jts 2 7	Casing Repair Altering Casing X Other - tubing eted Operations amp 750 gal 15% HCL. cr. SDON. 0 @ 8689'. Pump 750 g	Water Shu Conversion repair Work stuck pip yal 15% HCL. Dr COOH w/bit. SDO set @ 8670'. 7"	t off in to I e. Rls ill th	s pkr. TOOH w/
L3.	Final Abandonment Describe Proposed or Compl 3-14-00 MIRU. SDON. 3-15-00 ND WH. NU BOP. Pu 2 7/8" tbg & pk 3-16-00 TIH w/bit, tag up @ 8689-8720'. C 3-17-00 TIH w/269 jts 2 7	Casing Repair Altering Casing X Other - tubing eted Operations amp 750 gal 15% HCL. Cr. SDON. 0 @ 8689'. Pump 750 g CO to PBTD @ 8784'. T 1/8" 6.5# L-80 tbg, s	Water Shu Conversion repair Work stuck pip yal 15% HCL. Dr COOH w/bit. SDO set @ 8670'. 7"	t off in to I e. Rls ill th	s pkr. TOOH w/
13.	Final Abandonment Describe Proposed or Compl 3-14-00 MIRU. SDON. 3-15-00 ND WH. NU BOP. Pu 2 7/8" tbg & pk 3-16-00 TIH w/bit, tag up @ 8689-8720'. C 3-17-00 TIH w/269 jts 2 7	Casing Repair Altering Casing X Other - tubing eted Operations amp 750 gal 15% HCL. Cr. SDON. 0 @ 8689'. Pump 750 g CO to PBTD @ 8784'. T 1/8" 6.5# L-80 tbg, s	Water Shu Conversion repair Work stuck pip yal 15% HCL. Dr COOH w/bit. SDO set @ 8670'. 7"	t off in to I e. Rls ill th	s pkr. TOOH w/
L3.	Final Abandonment Describe Proposed or Compl 3-14-00 MIRU. SDON. 3-15-00 ND WH. NU BOP. Pu 2 7/8" tbg & pk 3-16-00 TIH w/bit, tag up @ 8689-8720'. C 3-17-00 TIH w/269 jts 2 7	Casing Repair Altering Casing _X_ Other - tubing .eted Operations .mmp 750 gal 15% HCLcr. SDON0 @ 8689'. Pump 750 g .CO to PBTD @ 8784'. T ./8" 6.5# L-80 tbg, s .NU WH. RD. Rig relea	Water Shu g Conversion repair Work stuck pip gal 15% HCL. Dr COOH w/bit. SDO set @ 8670'. 7" ased.	t off in to I e. Rls ill th	s pkr. TOOH w/
13.	Final Abandonment Describe Proposed or Compl 3-14-00 MIRU. SDON. 3-15-00 ND WH. NU BOP. Pu 2 7/8" tbg & pk 3-16-00 TIH w/bit, tag up @ 8689-8720'. C 3-17-00 TIH w/269 jts 2 7	Casing Repair Altering Casing _X_ Other - tubing .eted Operations .mmp 750 gal 15% HCLcr. SDON0 @ 8689'. Pump 750 g .CO to PBTD @ 8784'. T ./8" 6.5# L-80 tbg, s .NU WH. RD. Rig relea	Water Shu g Conversion repair Work stuck pip gal 15% HCL. Dr COOH w/bit. SDO set @ 8670'. 7" ased.	t off in to I e. Rls ill th	s pkr. TOOH w/
L3.	Final Abandonment Describe Proposed or Compl 3-14-00 MIRU. SDON. 3-15-00 ND WH. NU BOP. Pu 2 7/8" tbg & pk 3-16-00 TIH w/bit, tag up @ 8689-8720'. C 3-17-00 TIH w/269 jts 2 7	Casing Repair Altering Casing _X_ Other - tubing .eted Operations .mmp 750 gal 15% HCLcr. SDON0 @ 8689'. Pump 750 g .CO to PBTD @ 8784'. T ./8" 6.5# L-80 tbg, s .NU WH. RD. Rig relea	Water Shu g Conversion repair Work stuck pip gal 15% HCL. Dr COOH w/bit. SDO set @ 8670'. 7" ased.	t off in to I e. Rls ill th	s pkr. TOOH w/
13.	Final Abandonment Describe Proposed or Compl 3-14-00 MIRU. SDON. 3-15-00 ND WH. NU BOP. Pu 2 7/8" tbg & pk 3-16-00 TIH w/bit, tag up @ 8689-8720'. C 3-17-00 TIH w/269 jts 2 7 8586'. ND BOP.	Casing Repair Altering Casing X Other - tubing Leted Operations Lamp 750 gal 15% HCL. Lar. SDON. Lar. STOR HCL. Lar. SDON. Lar. SDON. Lar. STOR HCL. Lar. SDON. Lar. STOR H	Water Shu y Conversion repair Work stuck pip yal 15% HCL. Dr COOH w/bit. SDO set @ 8670'. 7" ased.	t off in to I e. Rls ill th	s pkr. TOOH w/
13.	Final Abandonment Describe Proposed or Compl 3-14-00 MIRU. SDON. 3-15-00 ND WH. NU BOP. Pu 2 7/8" tbg & pk 3-16-00 TIH w/bit, tag up @ 8689-8720'. C 3-17-00 TIH w/269 jts 2 7 8586'. ND BOP.	Casing Repair Altering Casing X Other - tubing eted Operations amp 750 gal 15% HCL. Cr. SDON. 0 @ 8689'. Pump 750 g CO to PBTD @ 8784'. T 1/8" 6.5# L-80 tbg, s	Water Shu y Conversion repair Work stuck pip yal 15% HCL. Dr COOH w/bit. SDO set @ 8670'. 7" ased.	t off in to I e. Rls ill th	s pkr. TOOH w/
14.	Final Abandonment Describe Proposed or Compl 3-14-00 MIRU. SDON. 3-15-00 ND WH. NU BOP. Pu 2 7/8" tbg & pk 3-16-00 TIH w/bit, tag up @ 8689-8720'. C 3-17-00 TIH w/269 jts 2 7 8586'. ND BOP.	Casing Repair Altering Casing X_ Other - tubing Leted Operations Lamp 750 gal 15% HCL. Lar. SDON. D @ 8689'. Pump 750 g CO to PBTD @ 8784'. T 1/8" 6.5# L-80 tbg, s NU WH. RD. Rig relea foregoing is true and	Water Shu Conversion repair Work stuck pip gal 15% HCL. Dr COOH w/bit. SDO set @ 8670'. 7" ased.	e. Rls	s pkr. TOOH w/ aru hard scale R-3 pkr, set @
	Final Abandonment Describe Proposed or Compl 3-14-00 MIRU. SDON. 3-15-00 ND WH. NU BOP. Pu 2 7/8" tbg & pk 3-16-00 TIH w/bit, tag up @ 8689-8720'. C 3-17-00 TIH w/269 jts 2 7 8586'. ND BOP.	Casing Repair Altering Casing X Other - tubing Leted Operations Lamp 750 gal 15% HCL. Lar. SDON. Lar. STOR HCL. Lar. SDON. Lar. SDON. Lar. STOR HCL. Lar. SDON. Lar. STOR H	Water Shu Conversion repair Work stuck pip gal 15% HCL. Dr COOH w/bit. SDO set @ 8670'. 7" ased.	e. Rls	s pkr. TOOH w/ aru hard scale R-3 pkr, set @
l 4. Signe	Final Abandonment Describe Proposed or Compl 3-14-00 MIRU. SDON. 3-15-00 ND WH. NU BOP. Pu 2 7/8" tbg & pk 3-16-00 TIH w/bit, tag up @ 8689-8720'. C 3-17-00 TIH w/269 jts 2 7 8586'. ND BOP.	Casing Repair Altering Casing X Other - tubing eted Operations amp 750 gal 15% HCL. cr. SDON. @ 8689'. Pump 750 g O to PBTD @ 8784'. T //8" 6.5# L-80 tbg, s NU WH. RD. Rig relea foregoing is true an Title Regulatory	Water Shu Conversion repair Work stuck pip gal 15% HCL. Dr COOH w/bit. SDO set @ 8670'. 7" ased.	e. Rls	expkr. TOOH w/ mru hard scale R-3 pkr, set @ 1/5/00