

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

14-20-604-5546

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Middle Canyon

9. WELL NO.

#1

10. FUEL AND POWER

Indesignat

11. SECTION, TOWNSHIP, RANGE, COUNTY OR AREA

Section 14-3

12. COUNTY OR PARISH

San Juan

No 100

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR
Aztec Oil & Gas Company

3. ADDRESS OF OPERATOR
P. O. Drawer 570, Farmington, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1600 FSL & 2500 FWL, Section 14-32N-15W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Spot 200 plug from 3200-3408' - Perfs & top of Dakota.
2. Shoot off casing at approximately 1900' & pull same.
3. Spot 100' plug over casing cut-off.
4. Spot 100' plug from 1250-1350' - Top of Mancus.
5. Spot 50' plug from 275-325' - Surface Casing Shoe.
6. Spot 10 Sx plug in surface & set dry hole marker.
7. Fill pits & Clean location.
(Fill hole with mud between plugs)



18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE District Superintendent DATE June 22, 1971

(See for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
REASONS OF APPROVAL, IF ANY: