		•			A. 11	· · · · · · · · · · · · · · · · · · ·	
NO. OF COPIES RECEIVED	->		COUNTION COUNT	CCION	○○○○○○ *	45-27008	
DISTRIBUTION		NEW MEXICO OIL CON	SERVATION COMMI	331014	Revised 1-1-65		
SANTA FE	 		5A. Indicate T	'ype of Lease			
FILE	1/-	5/JF 50 1/4/70 4/2533 STATE					
u.s.g.s.	2	<u>.</u>	chia con chia	\mathcal{O}_{ϵ}	.5. State Oil &	Gas Lease No.	
LAND OFFICE				, c			
OPERATOR		. V20200	7-20-	<u> </u>	mm		
	TION FOR PER	RMIT TO DRILL, DEEPE	N, OR PLUG BACI		7. Unit Agree	nent Name	
1a. Type of Work					,		
DRILL	7	DEEPEN 🗌	P	LUG BACK	8 Form or Le	ase Name	
b. Type of Well	<u>م</u>	_	amar [17]	MULTIPLE	8. Farm or Lease Name		
OIL GAS WELL	OTHE	R	SINGLE X	ZONE	Montoya g. Well No.		
2. Name of Operator					1		
Consolidated Oil	& Gas, Inc.	·	·		1-A		
3 Address of Operator		-			10/Field and Pool, or Wildcat Mesaverde/Dakota		
1860 Lincoln Stre	et. Lincolr	Tower Building, De	enver, Colorad	lo 80295	Lucius	de∖n akoc α	
4. Location of Well	11541 7	LOCATED 1980	FEET FROM THE	SouthLINE			
UNIT L	ETTEN	2000100					
AND 790 FEET F	ROM THE East	LINE OF SEC. 35	TWP.32 Norther	E. 13 Westnmpm	777777	<i>mHHHH</i>	
AND 730 FEET F	THITTHE THE				12. County		
					San Jua	, 111111111 v	
HHHHHH	<i>HHHHH</i>	<i>HHHHHHH</i>					
	+++++++	/////////////////////////////////////	19. Proposed Depth	19A. Formatio	on	20. Rotary or C.T.	
			6800'	Dakota		Rotary	
		21A. Kind & Status Plug. Bond	\ Y		22. Approx.	Date Work will start	
21. Elevations (Show whether	er Dr., K1, etc.)	Blanket bond in	NA		June	15, 1978	
5874'		fores					
23.		force PROPOSED CASING	AND CEMENT PROGE	RAM			
		I = =====	SETTING D	EDTH SACKS C	E CEMENT I	EST. TOP	
SIZE OF HOLE		CASING WEIGHT PER F			F CEMENT	Circ	
12-1/4"	8-5/8"	24	250'	200	F CEMENT	Circ.	
		24			F CEMENT		
12-1/4" 7-7/8"	8-5/8" 5-1/2"	24 15.5	250' 6800'	200 500		Circ. 2000'	
12-1/4" 7-7/8"	8-5/8" 5-1/2"	24 15.5	250' 6800'	200 500		Circ. 2000'	
12-1/4" 7-7/8"	8-5/8" 5-1/2"	24	250' 6800'	200 500		Circ. 2000'	
12-1/4" 7-7/8" 1. Drill 12-1/4	8-5/8" 5-1/2" " hole to <u>+</u>	24 15.5	250' 6800'	200 500		Circ. 2000'	
12-1/4" 7-7/8" 1. Drill 12-1/4' 2. WOC 12 hours	8-5/8" 5-1/2" " hole to <u>+</u>	24 15.5 250'. Set 8-5/8"	250' 6800' casing. Circ	200 500 ulate cement	: to surfa	Circ. 2000' ace.	
12-1/4" 7-7/8" 1. Drill 12-1/4' 2. WOC 12 hours	8-5/8" 5-1/2" " hole to <u>+</u>	24 15.5 250'. Set 8-5/8"	250' 6800' casing. Circ	200 500 ulate cement	: to surfa	Circ. 2000' ace.	
12-1/4" 7-7/8" 1. Drill 12-1/4' 2. WOC 12 hours 3. Install blow	8-5/8" 5-1/2" " hole to <u>+</u>	24 15.5	250' 6800' casing. Circ	200 500 ulate cement	: to surfa	Circ. 2000' ace.	
12-1/4" 7-7/8" 1. Drill 12-1/4' 2. WOC 12 hours	8-5/8" 5-1/2" " hole to <u>+</u>	24 15.5 250'. Set 8-5/8"	250' 6800' casing. Circ	200 500 ulate cement	: to surfa	Circ. 2000' ace.	
12-1/4" 7-7/8" 1. Drill 12-1/4' 2. WOC 12 hours 3. Install blowd 1000#.	8-5/8" 5-1/2" " hole to <u>+</u> out prevent	24 15.5 250'. Set 8-5/8" ers. Pressure test	250' 6800' casing. Circ surface casi	200 500 ulate cement	: to surfa	Circ. 2000' ace.	
12-1/4" 7-7/8" 1. Drill 12-1/4' 2. WOC 12 hours 3. Install blowd 1000#.	8-5/8" 5-1/2" " hole to <u>+</u> out prevent	24 15.5 250'. Set 8-5/8"	250' 6800' casing. Circ surface casi	200 500 ulate cement	: to surfa	Circ. 2000' ace.	
12-1/4" 7-7/8" 1. Drill 12-1/4' 2. WOC 12 hours 3. Install blowd 1000#. 4. Drill 7-7/8"	8-5/8" 5-1/2" " hole to <u>+</u> out prevent hole to <u>+</u>	24 15.5 250'. Set 8-5/8" ers. Pressure test 6800' with fresh wa	250' 6800' casing. Circ surface casi	200 500 ulate cement ng and blowd	: to surfa	Circ. 2000' ace.	
12-1/4" 7-7/8" 1. Drill 12-1/4' 2. WOC 12 hours 3. Install blowd 1000#. 4. Drill 7-7/8"	8-5/8" 5-1/2" " hole to <u>+</u> out prevent hole to <u>+</u>	24 15.5 250'. Set 8-5/8" ers. Pressure test	250' 6800' casing. Circ surface casi	200 500 ulate cement ng and blowd	: to surfa	Circ. 2000' ace.	
12-1/4" 7-7/8" 1. Drill 12-1/4' 2. WOC 12 hours 3. Install blowd 1000#. 4. Drill 7-7/8" 5. Run 5-1/2" c.	8-5/8" 5-1/2" hole to ± out prevent hole to ± asing and c	24 15.5 250'. Set 8-5/8" ers. Pressure test 6800' with fresh wa	250' 6800' casing. Circles surface casing ter gel mud.	200 500 ulate cement ng and blowd Log.	to surfa	Circ. 2000' ace.	
12-1/4" 7-7/8" 1. Drill 12-1/4' 2. WOC 12 hours 3. Install blowd 1000#. 4. Drill 7-7/8" 5. Run 5-1/2" cd 6. Selectively	8-5/8" 5-1/2" hole to + out prevent hole to + asing and contents	24 15.5 250'. Set 8-5/8" ers. Pressure test 6800' with fresh wa cement same with app	250' 6800' casing. Circles surface casing ter gel mud.	200 500 ulate cement ng and blowd Log.	to surfa	Circ. 2000'	
12-1/4" 7-7/8" 1. Drill 12-1/4' 2. WOC 12 hours 3. Install blowd 1000#. 4. Drill 7-7/8" 5. Run 5-1/2" cd 6. Selectively	8-5/8" 5-1/2" hole to + out prevent hole to + asing and o	24 15.5 250'. Set 8-5/8" ers. Pressure test 6800' with fresh wa cement same with app	250' 6800' casing. Circles surface casing ter gel mud.	200 500 ulate cement ng and blowd Log.	to surfa	Circ. 2000'	
12-1/4" 7-7/8" 1. Drill 12-1/4' 2. WOC 12 hours 3. Install blowd 1000#. 4. Drill 7-7/8" 5. Run 5-1/2" cd 6. Selectively	8-5/8" 5-1/2" hole to + out prevent hole to + asing and o	24 15.5 250'. Set 8-5/8" ers. Pressure test 6800' with fresh wa cement same with app	250' 6800' casing. Circles surface casing ter gel mud.	200 500 ulate cement ng and blowd Log.	to surfa	Circ. 2000' ace.	
12-1/4" 7-7/8" 1. Drill 12-1/4' 2. WOC 12 hours 3. Install blown 1000#. 4. Drill 7-7/8" 5. Run 5-1/2" con 6. Selectively and regulating	8-5/8" 5-1/2" hole to + out prevent hole to + asing and o perforate a ons.	24 15.5 250'. Set 8-5/8" ers. Pressure test 6800' with fresh wa cement same with app nd stimulate the Me	250' 6800' casing. Circles surface casing ter gel mud. coroximately 30 esaverde and c	200 500 ulate cement ng and blowd Log. 00 sx. omplete as n	to surface	Circ. 2000' ice. iters to	
12-1/4" 7-7/8" 1. Drill 12-1/4" 2. WOC 12 hours 3. Install blown 1000#. 4. Drill 7-7/8" 5. Run 5-1/2" conditions of the second regulations of the	8-5/8" 5-1/2" hole to + out prevent hole to + asing and o perforate a ons.	24 15.5 250'. Set 8-5/8" ers. Pressure test 6800' with fresh wa cement same with app nd stimulate the Me	250' 6800' casing. Circles surface casing ter gel mud. coroximately 30 esaverde and c	200 500 ulate cement ng and blowd Log. 00 sx. omplete as n	to surface	Circ. 2000' ice. iters to	
12-1/4" 7-7/8" 1. Drill 12-1/4" 2. WOC 12 hours 3. Install blowd 1000#. 4. Drill 7-7/8" 5. Run 5-1/2" constant regulation of the second regulation reg	8-5/8" 5-1/2" hole to + out prevent hole to + asing and comperforate a ons.	24 15.5 250'. Set 8-5/8" ers. Pressure test 6800' with fresh wa cement same with app nd stimulate the Me	250' 6800' casing. Circles surface casing ter gel mud. croximately 30 esaverde and company	200 500 ulate cement ng and blowd Log. 00 sx. omplete as 1	to surface	Circ. 2000' ice. iters to	
12-1/4" 7-7/8" 1. Drill 12-1/4" 2. WOC 12 hours 3. Install blowd 1000#. 4. Drill 7-7/8" 5. Run 5-1/2" compand regulation of the second regulation regulation of the second regulation regula	8-5/8" 5-1/2" hole to + out prevent hole to + asing and comperforate a ons.	24 15.5 250'. Set 8-5/8" ers. Pressure test 6800' with fresh wa cement same with app nd stimulate the Me	250' 6800' casing. Circles surface casing ter gel mud. croximately 30 esaverde and company	200 500 ulate cement ng and blowd Log. 00 sx. omplete as 1	to surface	Circ. 2000' ice. iters to	
12-1/4" 7-7/8" 1. Drill 12-1/4" 2. WOC 12 hours 3. Install blowd 1000#. 4. Drill 7-7/8" 5. Run 5-1/2" compand regulation of the second regulation regulation of the second regulation regula	8-5/8" 5-1/2" hole to + out prevent hole to + asing and comperforate a ons.	24 15.5 250'. Set 8-5/8" ers. Pressure test 6800' with fresh wa cement same with app nd stimulate the Me complete to the best of	250' 6800' casing. Circles surface casing ter gel mud. croximately 30 esaverde and complete and complete and complete and complete and believed to the saverde and believe	200 500 ulate cement ng and blowd Log. 00 sx. omplete as 1	to surface to the surface of the sur	Circ. 2000' Ice. Iters to Youles E AND PROPOSED NEW PROD	
12-1/4" 7-7/8" 1. Drill 12-1/4" 2. WOC 12 hours 3. Install blowd 1000#. 4. Drill 7-7/8" 5. Run 5-1/2" conditions of the condition of the	8-5/8" 5-1/2" hole to + out prevent hole to + asing and compensed proposed propos	24 15.5 250'. Set 8-5/8" ers. Pressure test 6800' with fresh wa cement same with app nd stimulate the Me complete to the best of	250' 6800' casing. Circles surface casing ter gel mud. croximately 30 esaverde and company	200 500 ulate cement ng and blowd Log. 00 sx. omplete as 1	to surface to the surface of the sur	Circ. 2000' Ice. Iters to Youles E AND PROPOSED NEW PROD	
12-1/4" 7-7/8" 1. Drill 12-1/4" 2. WOC 12 hours 3. Install blowd 1000#. 4. Drill 7-7/8" 5. Run 5-1/2" constant regulation of the second regul	8-5/8" 5-1/2" hole to + out prevent hole to + asing and comperforate a ons. BE PROPOSED PREVENTER PROGRAM ormation above is partiam	24 15.5 250'. Set 8-5/8" ers. Pressure test 6800' with fresh wa cement same with app nd stimulate the Me complete to the best of	250' 6800' casing. Circles surface casing ter gel mud. croximately 30 esaverde and complete and complete and complete and complete and believed to the saverde and believe	200 500 ulate cement ng and blowd Log. 00 sx. omplete as 1	to surface to the surface of the sur	Circ. 2000' Ice. Iters to Youles E AND PROPOSED NEW PROD	
12-1/4" 7-7/8" 1. Drill 12-1/4" 2. WOC 12 hours 3. Install blown 1000#. 4. Drill 7-7/8" 5. Run 5-1/2" c. 6. Selectively and regulating and regulating and regulating and regulating and results	8-5/8" 5-1/2" hole to + out prevent hole to + asing and compensed proposed propos	24 15.5 250'. Set 8-5/8" ers. Pressure test 6800' with fresh wa cement same with app nd stimulate the Me Cogram: If Proposal is to det Title and complete to the best of	250' 6800' casing. Circles surface casing ter gel mud. croximately 30 esaverde and compensate and compensate and compensate and compensate and believe production.	200 500 ulate cement ng and blowd Log. 00 sx. omplete as 1	to surface to the surface of the sur	Circ. 2000' Ice. Iters to Youles And Proposed New Prop	
12-1/4" 7-7/8" 1. Drill 12-1/4" 2. WOC 12 hours 3. Install blowd 1000#. 4. Drill 7-7/8" 5. Run 5-1/2" constant regulation of the second regul	8-5/8" 5-1/2" hole to + out prevent hole to + asing and comperforate a ons. BE PROPOSED PREVENTER PROGRAM ormation above is partiam	24 15.5 250'. Set 8-5/8" ers. Pressure test 6800' with fresh wa cement same with app nd stimulate the Me Cogram: If Proposal is to det Title and complete to the best of	250' 6800' casing. Circles surface casing ter gel mud. croximately 30 esaverde and compensate and compensate and compensate and compensate and believe production.	200 500 ulate cement ng and blowd Log. 00 sx. omplete as 1	to surface to the surface of the sur	Circ. 2000' Ice. Iters to Youles E AND PROPOSED NEW PROD	
12-1/4" 7-7/8" 1. Drill 12-1/4" 2. WOC 12 hours 3. Install blown 1000#. 4. Drill 7-7/8" 5. Run 5-1/2" c. 6. Selectively and regulating and regulating and regulating and regulating and results	8-5/8" 5-1/2" hole to + out prevent hole to + asing and comperforate a ons. BE PROPOSED PREVENTER PROGRAM ormation above is partiam	24 15.5 250'. Set 8-5/8" ers. Pressure test 6800' with fresh wa cement same with app nd stimulate the Me Cogram: If Proposal is to det Title and complete to the best of	250' 6800' casing. Circles surface casing ter gel mud. croximately 30 esaverde and complete and complete and complete and complete and believed to the saverde and believe	200 500 ulate cement ng and blowd Log. 00 sx. omplete as 1	to surface to the surface of the sur	Circ. 2000' Ice. Iters to Youles And Proposed New Prop	
12-1/4" 7-7/8" 1. Drill 12-1/4' 2. WOC 12 hours 3. Install blowd 1000#. 4. Drill 7-7/8" 5. Run 5-1/2" Company of the second of	8-5/8" 5-1/2" hole to + out prevent hole to + asing and comperforate a ons. BE PROPOSED PROP	24 15.5 250'. Set 8-5/8" ers. Pressure test 6800' with fresh wa cement same with app nd stimulate the Me Cogram: If PROPOSAL IS TO DEE HE ANY. true and complete to the best of itle Senic	250' 6800' casing. Circle surface casing ter gel mud. croximately 30 csaverde and complete and complete and complete and below Production.	200 500 ulate cement ng and blowd Log. 00 sx. omplete as 1	to surface to the surface of the sur	Circ. 2000' Ice. Iters to Youles And Proposed New Prop	
12-1/4" 7-7/8" 1. Drill 12-1/4' 2. WOC 12 hours 3. Install blowd 1000#. 4. Drill 7-7/8" 5. Run 5-1/2" Company of the second of	8-5/8" 5-1/2" hole to + out prevent hole to + asing and comperforate a ons. BE PROPOSED PROP	24 15.5 250'. Set 8-5/8" ers. Pressure test 6800' with fresh wa cement same with app nd stimulate the Me Cogram: If PROPOSAL IS TO DEE HE ANY. true and complete to the best of itle Senic	250' 6800' casing. Circle surface casing ter gel mud. croximately 30 csaverde and complete and complete and complete and below Production.	200 500 ulate cement ng and blowd Log. 00 sx. omplete as 1	to surface to the surface of the sur	Circ. 2000' Ice. Iters to Youles And Proposed New Prop	
12-1/4" 7-7/8" 1. Drill 12-1/4' 2. WOC 12 hours 3. Install blowd 1000#. 4. Drill 7-7/8" 5. Run 5-1/2" Company of the second of	8-5/8" 5-1/2" hole to + out prevent hole to + asing and comperforate a ons. BE PROPOSED PROP	24 15.5 250'. Set 8-5/8" ers. Pressure test 6800' with fresh wa cement same with app nd stimulate the Me Cogram: If Proposal is to det Title and complete to the best of	250' 6800' casing. Circle surface casing ter gel mud. croximately 30 csaverde and complete and complete and complete and below Production.	200 500 ulate cement ng and blowd Log. 00 sx. omplete as 1	to surface to the surface of the sur	Circ. 2000' Ice. Iters to Youles And Proposed New Prop	

NEW MEXICO OIL CONSERVATION COMMISSION WELL LOCATION AND ACERAGE DEDICATION PLAT

	All distances	must be from t	he outer bour	idories of the Section			
Operator CONSCLIDATED OI	I AND GAS.	Leos		ONTOYA		Well	
Unit Letter Section	Township 32 NOI	Ā	enge	County	JUAN		
Actual Footage Location of Well: 1980 feet from the		line and	790	feet from the	EAST	line	
Ground Level Elev. Producing 5874 Me		Pool	Blanco	Mesaverde	De	dicated Ave	Acres
2. If more than one lease is interest and royalty),3. If more than one lease of by communitization, unitizat	different ownersh	nip is dedicate					
: 1 Yes () No	If answer is "yes,"	" type of cons	solidation .			************	
if answer is "no," list the ow	ners and tract de	scriptions whic	h have ac	tually consolidated.	(Use rever	se side o	f this form if
No allowable will be assigned pooling or otherwise) or until	to the well until o	all interests ha unit, eliminatir	ve been co ig such int	onsolidated (by cor erests, has been ap;	mmunitization proved by th	on, unitiz ne Commi:	ation, forced- ssion.

35 | N

SCALE-4 INCHES EQUALS 1 MILE

dpp oved by the commission.
CERTIFICATION
I hereby certify that the information contained herein is true and complete to the best of my
knowledge and belief.
Name Name Malan
Charles M. Parham
Position
Sr. Production Engineer
Company.
Consolidated Oil & Gas, Inc.
Dote
April 19, 1978
South the second
E 3510 M
I hereby certify that the well location shows or
this plat was plotted from field notes of actua
surveys made by me or under my supervision, and
that the same is true and correct to the best of
knowledge and beliefy of Action
0.
The street
30 March, 1978
Pare Surveyed D
Jone J. Pearl
Reclistered Professional Engineer
and or Land Surveyor

1463 Certificate No.

FARMINGTON, N. M.