## State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

/	Sundry Notices and Re	eports on Wells	<del></del>
		<b>API</b>	# (assigned by OCD) 30-045-24512 Lease Number
1. Type of Well GAS		6.	Fee State Oil&Gas Lease #
2. Name of Operator		7.	Lease Name/Unit Name
EURLINGTON RESOURCES OIL & GAS COMPANY		8.	
3. Address & Phone No. of Operat PO Box 4289, Farmington, NM	or 87499 (505) 326-9700	9.	19 Pool Name or Wildcat Aztec Pictured Cliffs
4. Location of Well, Footage, Se 975'FNL, 790'FEL, Sec.29, T-3	ec., T, R, M 2-N, R-12-W, NMPM, San	<del></del>	Elevation:
Type of Submission	Type of Ac	tion	
_X_ Notice of Intent Subsequent Report	_X_ Abandonment	Change of Pl New Construc Non-Routine	tion Fracturing
Final Abandonment	Casing Repair Altering Casing Other -	Water Shut o Conversion t	
It is intended to plug and procedure and well	d abandon the subject we bore diagram.	well according t	o the attached
		DECE M MAY 2 7	IVED 1897
		<b>09</b> 634	
SIGNATURE Lang Stmann	△ (KM4) Regulatory	Administrator_	_May 23, 1997
(This space for State Use)			
Original Signed by FRANK 1	TitleSUPERVISO	R DISTRICT # 3	MÁY 2 7 199

Culpepper Martin #19

Aztec Pictured Cliffs 975' FNL, 790' FEL NE, Sec. 29, T32N, R12W San Juan County, New Mexico

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures.

- 1. Install and/or test rig anchors. Prepare blow pit. Comply to all NMOCD, BLM and Meridian safety rules and regulations.
- 2. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. NU relief line. Blow down well and kill with water as necessary. ND wellhead and NU BOP. Test BOP. PU 1-1/4" EUE tubing work string.
- 3. Plug #1 (Pictured Cliffs perforations and Fruitland top, 2398' 1758'): RIH with open ended tubing to 2398' or as deep as possible. Pump 15 bbls water down tubing. Mix and spot 15 sxs Class B cement from 2398' to 1853' to cover Pictured Cliff perforations; pull up hole to 1853' and spot another 15 sxs cement to cover Fruitland top. POH with tubing. WOC then RIH and tag cement. Pressure test casing to 500#. POH and LD tubing if casing tested.
- 4. Plug #2 (Kirtland, Ojo Alamo and Surface): Perforate 2 squeeze holes at 490'. If casing tested, then establish circulation out bradenhead valve. Mix and pump approximately 150 sxs Class B cement down 2-7/8" casing, circulate good cement out bradenhead valve. Shut in well and WOC. If casing did not test, then prior to perforating run a 2-7/8" gauge ring to 500'. After perforating, set a wireline cement retainer at 450'. PU stinger and RIH; sting into retainer and establish rate into squeeze holes. With casing valve open, mix and pump approximately 135 sxs Class B cement, circulate good cement out bradenhead valve; sting out of retainer and spot 15 sxs inside 2-7/8" casing above CR to circulate cement out casing valve. POH and LD tubing. If casing flows while stung into retainer, then shut casing valve. WOC.
- 5. ND BOP and cut off wellhead below surface casing. Install P&A marker to comply with regulations. RD, MOL, cut off anchors, and restore location.

DECEIVED

NAY 2 7 1997

OM SOM DOWN

Recommended:

Operations Engineer

Approval:

Drilling Superintendent

## Culpepper Martin #19

## Proposed P & A DPNO 10657

Today's Date: 12/20/96 Spud: 12/31/80 Completed: 6/15/81

Elevation: 5955' (GL)
Logs: IES; Den-GR;
GR-CBL/CCL

Workovers: None

Nacimiento @ Surf

Ojo Alamo @ 478'

Kirtland @ 500'

Fruitland @ 1818'

Pictured Cliffs @ 2329'


6-3/4 hole

**PBTD 2531** 

TD 2550'

**Aztec Pictured Cliffs** 

NE Section 29, T-32-N, R-12-W, San Juan County, NM




8-5/8" 24# Csg set @ 179' 135 sxs (Circulated to Surface)

Plug #2 490' - Surface Cmt with 150 sxs Class B.

Perf @ 490'

TOC @ 500' (CBL)



Pictured Cliffs Perforations: 2330' - 2348' (10 holes)

2-7/8" 6.5# J-55 Csg set @ 2539' Cmt w/ 750 sxs

## Culpepper Martin #19

Current -- 4/28/97 DPNO 10657

Today's Date: 12/20/96 Spud: 12/31/80

Completed: 6/15/81

Elevation: 5955' (GL)

Logs: IES; Den-GR; GR-CBL/CCL

Workovers: None

Nacimiento @ Surf

Ojo Alamo @ 478'


Kirtland @ 500'

Fruitland @ 1818'

Pictured Cliffs @ 2329'

Aztec Pictured Cliffs

NE Section 29, T-32-N, R-12-W, San Juan County, NM



PBTD 2531

TD 2550'

6-3/4 hole

8-5/8" 24# Csg set @ 179' 135 sxs (Circulated to Surface)

TOC @ 500' (CBL)

Note: Well has a casing fallure at an unknown depth.

Pictured Cliffs Perforations: 2330' - 2348' (10 holes)

2-7/8" 6.5# J-55 Csg set @ 2539' Cmt w/ 750 sxs