


Form 9-331a
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office 7-235Lease No. 2

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 13, 1954

Thompson

Well No. 1 is located 770 ft. from N line and 770 ft. from E line of sec. 2
27 ft. from S line and 122 ft. from W line of sec. 2

San Juan (Twp.) San Juan (Meridian) San Juan (State or Territory)
 (Field) (County or Subdivision)

The elevation of the derrick floor above sea level is 5794 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well is leaking water and unable to shutoff. It is proposed to place retainer approx 50' in the casing above shoe and pump cement into the open hole below casing until it does not take any more and pressure builds up. A fifty foot cement plug is to be placed in the top of the casing. A cement plug is to be placed in top plug.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.
January 13, 1954

Company 213 First National Bank Bldg.Address Marillo, TexasBy H. ThompsonTitle Manager