

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
FE	1
U.S.	
OFFICE	
OF T R	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Bedford, Inc. agent for Black Diamond Oil Company & State of New Mexico	8. Farm or Lease Name Unknown
3. Address of Operator P. O. Box E, Farmington, New Mexico 87401	9. Well No. 1
4. Location of Well UNIT LETTER C 920 FEET FROM THE N LINE AND 1520 FEET FROM THE W LINE, SECTION 27 TOWNSHIP 29N RANGE 11W NMPM.	10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.)	12. County

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>


SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been plugged & abandoned as follows:

- 11-9-78 Move in, rig up, ran bit on 2" tbg. to 20', tag up on wood plug.
- 11-10-78 Go in hole w/ Auger bit, clean out to bottom. Spot 30 sx plug 500' to 400', pull tbg to 150', spot 60 sx plug, did not stop water flow.
- 11-16-78 Go in hole w/tbg. tag plug @ 400' spot 180 sx plug & shut well in.
- 11-17-78 Set P & A marker w/10 sx. plug, clean loc.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Larry G Bedford TITLE Agent for State

DATE 11-27-78

APPROVED BY AP Kendrick TITLE SECRETARY DIST. 3

DATE NOV 27 1978

CONDITIONS OF APPROVAL, IF ANY: