State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

Sundry Notices and Reports on Wells	
	API # (assigned by OCD) 30-045-07937
1. Type of Well	5. Lease Number
GAS	Fee
	6. State Oil&Gas Lease #
2. Name of Operator	7. Lease Name/Unit Name
BURLINGTON	
RESCURCES OIL & GAS COMPANY	Dallabetta
	8. Well No. 1
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	9. Pool Name or Wildcat Fulcher Kutz Pict.Cli
4. Location of Well, Footage, Sec., T, R, M	10. Elevation:
330'FSL, 1650'FWL, Sec. 20, T-29-N, R-11-W, NMPM, San	
Type of Submission Type of Action	on
X Notice of Intent Abandonment	Change of Plans
Recompletion	New Construction
Subsequent Report Plugging Back	Non-Routine Fracturing Water Shut off
	Conversion to Injection
X_ Other - Restimulate	
13. Describe Proposed or Completed Operations	
It is intended to restimulate the Pictured Cliffs in the following manner:	formation of the subject well
It is intended to restimulate the Pictured Cliffs in the following manner: Pull 1" tubing. Clean out to plug back tota foam fracture treat the Pictured Cliffs zon to production.	al depth at 1640'. Acidize and
in the following manner: Pull 1" tubing. Clean out to plug back tota foam fracture treat the Pictured Cliffs zon	al depth at 1640'. Acidize and
in the following manner: Pull 1" tubing. Clean out to plug back tota foam fracture treat the Pictured Cliffs zon	al depth at 1640'. Acidize and
in the following manner: Pull 1" tubing. Clean out to plug back tota foam fracture treat the Pictured Cliffs zon	al depth at 1640'. Acidize and
in the following manner: Pull 1" tubing. Clean out to plug back tota foam fracture treat the Pictured Cliffs zon	al depth at 1640'. Acidize and ne. Clean out and return well
in the following manner: Pull 1" tubing. Clean out to plug back tota foam fracture treat the Pictured Cliffs zon	al depth at 1640'. Acidize and ne. Clean out and return well
in the following manner: Pull 1" tubing. Clean out to plug back tota foam fracture treat the Pictured Cliffs zon	al depth at 1640'. Acidize and ne. Clean out and return well
in the following manner: Pull 1" tubing. Clean out to plug back total foam fracture treat the Pictured Cliffs zon to production.	al depth at 1640'. Acidize and ne. Clean out and return well
in the following manner: Pull 1" tubing. Clean out to plug back total foam fracture treat the Pictured Cliffs zon to production. SIGNATURE Anny Jon (MDWPC) Regulatory	Administrator_October 6, 1997

Dallabetta #1 **Pertinent Data Sheet**

API #: 300450793700

Location: 330 'FSL & 1650 'FWL, Unit N, Section 20, T29N, R11W, San Juan County, New Mexico

Latitude: 36° - 42.29'

Longitude: 108° - 1.06'

Field: Fulcher Kutz PC

Elevation: 5409 'GL

TD: 1641'

5419 'KB

PBTD: 1640'

Spud Date: 11/3/46

Compl Date: 12/1/46

DP #: 11535 Lease: SRC 0023002 (Private)

GWI: 25 %

Initial Potential: 1265 Mcfd NRI: 21.875 %

Prop#: 23002 Original SIP: 503 psi

Casing Record:

Cement Top Depth Set (Ft.) Cernent (Sx.) Hole Size (In.) Csg Size (In.) Wt. (#'s) & Grade circ to surf 42 17 1/2 15 1/2 ? ? 10 25 1387' @ 75% eff. 1,534 77/8 5 1/2 14 J-55 150 594' @ 75% eff. 4 3/4 3 1/2 7.7 J-55 1,640

Tubing Record:

Wt. & Grade Depth Set # Joints Comments Tbg. Size 71 (est) 1.7 Line Pipe 1,500 '

Formation Tops:

Ojo Alamo:

202'

All Tops are Estimated

Kirtland Shale: 324' Fruitland:

1,383

Pictured Cliffs: 1,511

Logging Record:

Original Stimulation: Original: Natural, Restim: Perfd 1514-74' w/ 2 SPF, SWF w/ 16,296 gal wtr, 10,000# 20/40,

and 8,000# 10/20 sd

Workover History:

7/27/64: 3-1/2 Restim (see above Stimulation)

Production History:

7/97 PC capacity: 0 MCF/D. 7/97 PC cum: 1326 MMCF.

Pipeline:

WFS

Filfe: Q: area !!pcteam 1998 welldata restim RSTMPERT.DOC

Dallabetta #1

Section 20 N, T-29 -N R-11 -W San Juan, New Mexico

Fulcher Kutz Pictured Cliffs Field Wellbore Schematic

