



OIL CONSERVATION COMMISSION

STATE OF NEW MEXICO
1000 RIO BRAZOS RD. - AZTEC

87410

DIRECTOR
JOE D. RAMEY

LAND COMMISSIONER
PHIL R. LUCERO



STATE GEOLOGIST
EMERY C. ARNOLD

July 30, 1976

Mr. B. R. Vanderslice
Southern Union Production Co.
P. O. Box 808
Farmington, New Mexico

Re: Southern Union Production Co.
Summit B #5
F-33-29N-11W
Fulcher Kutz Pictured Cliffs Pool

Dear Mr. Vanderslice:

During a recent field inspection of the location of the subject well a gas odor was detected on the location.

The Southern Union Gas Company had Mr. Kenneth Blancett to meet with us to check their gathering line near the well yesterday.

We attempted to contact you, but you were not available on short notice.

Please observe this well closely. We believe that you may have a casing failure in this well. If so, Rule 108 requires the operator of a well with defective casing to proceed with diligence to repair or plug and abandon the well.

Please file your proposed plan of action prior to any field operations to repair a casing failure.

If there are questions please contact us.

Yours very truly,

A. R. Kendrick
A. R. Kendrick
Supervisor, District #3

ARK:mc

xc: Oil Conservation Commission, Santa Fe, New Mexico

United States Geological Survey, Farmington, New Mexico