<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

Revised 5/4/06 I CW

Cident - nPRS0612250785 Polication-PPAC0613138862

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

	OPERA	TOR	X Initia	l Report	Final Report	
Name of Company Chevron USA, Inc. Contact Wayne Minchew						
Address HCR 60 Box 432 Lovington, NM 88260	Telephone No.505-396-4414 X101					
Facility Name Central Vacuum Unit	Facility Typ	Facility Type Satellite 3 Injection truck line.				
Surface Owner State Mineral Owner State			L agga N	Lease No.		
Surface Owner State Mineral Owner State Lease No.						
LOCATION OF RELEASE						
	h/South Line	Feet from the	East/West Line	ast/West Line County		
31 17S 35E				-		
D						
Latitude 32 47 40.87' Longitude 103 30 15.15'						
Datitude_32 47 40.07 Longitude_103 30 13.13 _						
NATURE OF RELEASE						
Type of Release Produced Water	Volume of	Release 600 bbl		Volume Recovered 425bbl		
Source of Release 6" fiberglass injection trunk line					Hour of Discovery	
		11:00 Pm 4/8/06 11:30 Pm 4/08/06				
Was Immediate Notice Given? If YES, To Whom?						
X Yes No Not Required Guy Wink						
By Whom? Wayne Minchew	Date and Hour 11:00 am 4/09/06					
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.			.		
☐ Yes X No	and the state of t					
If a Watercourse was Impacted, Describe Fully.*						
if a watercourse was impacted, Describe runy.						
•	-					
Describe Cause of Problem and Remedial Action Taken.*						
Hole came in 6" fiberglass injection trunk line going under Hwy 238. This line is inside of conduit and water was released on both sides of roadway into						
the pastures. Possible cause could have been a week spot in the fiberglas	SS.					
Describe Area Affected and Cleanup Action Taken.*						
An Area of 30' x 300' on the West side of the Hwy and 30" x 390", 396" x 190" on the East side of the Hwy. Will clean up Iron Sulfide and let land dry						
up. Remove top soil and replace with good top soil.						
I hereby certify that the information given above is true and complete to	the heet of my	knowledge and w	ndometend that miner	want to NMOCD	mulas and	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger						
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability						
should their operations have failed to adequately investigate and remedia	ate contamination	on that pose a thre	eat to ground water.	surface water. h	uman health	
or the environment. In addition, NMOCD acceptance of a C-141 report	does not relieve	e the operator of	responsibility for co	mpliance with a	ny other	
federal, state, or local laws and/or regulations.						
		OIL CONSERVATION DIVISION				
Signature: any little						
organice. I will be a second		5 1.1.6				
Printed Name: Larry Williams	Approved by District Supervisor:					
				· · · · · · · · · · · · · · · · · · ·		
Title: HES Champion	Approval Date	Approval Date:		Expiration Date:		
F. mail Addresse land@charmen age						
E-mail Address: lcwl@chevron.com	Conditions of	Approval:		Attached		
Date: 4/13/06 Phone: 505-394-1237						
Attach Additional Sheets If Necessary						