<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

						-,						
			Rele	ease Notific	catio	on and Co	orrective A	ction	l			
						OPERATOR						
Name of Company Devon Energy Production						Contact Kenny Kidd						•
Address 64	88 Seven	Rivers Hwy	VM 88220	Telephone No. 575-513-8545								
Facility Name Shinnery 14 Fed 5 SWD						Facility Type Disposal Well SWD						
Surface Owner Federal Mineral Owner						r Federal			API No. 30-025-30719			
								741110. 30 023 30717				
						ON OF RELEASE th/South Line Feet from the Eas			st/West Line County			
OIII Letter	Section	Township	Kange	reet from the	Nort	n/South Line	East/	west Line	County			
Н	14	18S	32E	2310		N 660			E Lea			
		1	atitude:	N 32'74'83.04'	,	Loi	ngitude: W 103	3'73'05	5.63"			
				NAT	URI	E OF REL	EASE					
Type of Rele	ase Spill	Volume of Release 50bbl			Volume Recovered 40 bbl							
Source of Release									Date and Hour of Discovery			
2x1 swedge connection plumbed into wellhead Was Immediate Notice Given?									4/7/2015	5 @ 12:30 pm		
Was Immed	iate Notice		LM DM.B	If YES, To Whom?								
		M	No Not Re									
By Whom?						Tomas Oberding @ OCD Date and Hour						
Ruben Garcia						4/7/2015 @3:17 pm						
						4/7/2015 @3:30 pm						
Was a Water	rcourse Re		If YES, Volume Impacting the Watercourse									
			Yes 🛚	No								
If a Watercourse was Impacted, Describe Fully.*						RECEIVED						
Describe Cause of Problem and Remedial Action Taken.*						By OCD District 1 at 1:29 pm, Jul 09, 2015						
source of the noticed that the	leak and no he 1" thread s not suffici	ticed it was co ls on the 2x1 s ently supporte	oming from swedge we ed. 50 bbls	n the 2x1 swedge are cracked and was s of produced wat	conne	ection plumbed e pump was rui	water on location into the wellhead ming it would spr th side of the pad	l. Upon ay wate	further inver	estigation Le	ase Op	erator e wellhead
Describe Are	ea Affected	and Cleanup	Action T	aken.*								
be scraped up	at a later d	ate.					Legendary Truck					
regulations al public health should their o	l operators or the envir operations h nment. In a	are required to conment. The ave failed to a ddition, NMO	report an acceptanc dequately CD accep	d/or file certain r e of a C-141 repo investigate and re	elease ort by tl emedia	notifications ar he NMOCD mate contaminati	knowledge and und perform correct arked as "Final Roon that pose a throet the operator of returns of the operator of returns of the operator op	tive acti eport" d eat to gr	ons for rele oes not reli ound water	eases which eve the oper surface wa	may en ator of ter, hur	danger liability nan health
Signature: Corina Moya						OIL CONSERVATION DIVISION						
bigilature, Co	or orwo le	io yw										
Printed Name: Corina Moya						Approved by Environmental Specialist:						
Title: Field Admin Support						Approval Date: 07/09/2015 Expiration Date: 10/10/2015				5		
E-mail Addre	ss: corina.	nova@dvn.co	om			Conditions of	Approval:					6127
E-mail Address: corina.moya@dvn.com						Site samples required. Delineate and remediate Attached				6137		
						as per MNOCD guides. Geotag photographs of				1RP-372	0	

remediation required.