Dear Ms. Wilson:

Please address these concerns for delineation report for 1RP-4708:

- Initial photos of release indicate that a pooling location is at the Southeast corner of the bermed area (South of S-3). NMOCD requests that an additional delineation sample location be established at the aforementioned spot, especially as the site was initially sampled more than 6 months after the incident date in May 2017.
- What is the reason for elevated chloride levels for S-5 and S-6 areas outside of the impacted tank battery?
- Bottom and edge/sidewalls of the areas represented by S-5 and S-6 will be required.

Also, please note that the GPS coordinates of the release location are incorrect on pg. 1.

Thanks, Olivia

From: Kimberly M. Wilson [mailto:kwilson@talonlpe.com]

Sent: Monday, February 5, 2018 10:46 AM

To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; Naranjo, Mark <MNaranjo@slo.state.nm.us>
Cc: Mike Shoemaker <mike.shoemaker@dvn.com>; David J. Adkins <dadkins@talonlpe.com>
Subject: Outland State #2 Work Plan

Good Morning,

Please find attached the work plan for the above referenced location. If you have any questions or concerns please feel free to contact our office.

Respectfully Submitted,

Kimberly

Kimberly M. Wilson Project Manager Office: 575.746.8768 Direct: 575.616.4023 Cell: 575.602.3826 Fax: 575.746.8905 Emergency: 866.742.0742 Web:



www.talonlpe.com