Submit 3 Copies To Appropriate District Office	State of New Mexico				Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources 88240			March 4, 2004 WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION			30 <b>-</b> 025-363	83	
District III 1220 South St. Francis Dr.			5. Indicate Type		
District IV Santa Fe, NM 87505				6. State Oil & G	
1220 S. St. Francis Dr., Santa Fe, NM 87505				0. 5440 01 40 0	as Dease 145.
SUNDRY NOTION	CES AND REPORTS	ON WELLS		7. Lease Name	or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				ALVES	
PROPOSALS.)  1. Type of Well:				8. Well Number	
Oil Well 💢 Gas Well 🗌 Other				4	
2. Name of Operator				9. OGRID Num	
LANEXCO, INC.					013046
3. Address of Operator 1105 WEST KANSAS, JAL, NM 88252				10. Pool name or Wildcat PENROSE SKELLY GRAYBURG	
4. Well Location					
Unit Letter H :	1800 feet from th	he NORTH	line and 66	O feet fro	om the EAST line
Section 18			inge 37E		
Section -5	11. Elevation (Show				County LEA
Pit on Polony guada Tonk Application (Fr	348	83	·		
Pit Or Below-grade Tank Application (For Pit Location: ULSectTwp					
Distance from nearest surface water					
feet from theline and			1 wp	Kiig :	
					10.1415167
10 01 1 4	mmonwinto Dougle	T 11 . 3.T			
12. Check A	appropriate Box to	Indicate N	ature of Notice.	Report or Other	· Data
NOTICE OF IN	TENTION TO:		ature of Notice, SUB	Report or Other SEQUENT RE	Data  PORT OF
NOTICE OF INT PERFORM REMEDIAL WORK	TENTION TO:		ature of Notice, SUB REMEDIAL WOR	SEQUENT RE	Data PORT OF CASING 1
NOTICE OF IN	TENTION TO:		SUB	SEQUENT RE	PORT OF ALTERING CASING & PLUG AND A PLUG AN
NOTICE OF IN	TENTION TO: PLUG AND ABANDO	ON 🗆	SUB REMEDIAL WOR	SEQUENT RE	PORT OF ALTERING CASING DIABANDONMENT
NOTICE OF IN' PERFORM REMEDIAL WORK   TEMPORARILY ABANDON	TENTION TO: PLUG AND ABANDO CHANGE PLANS MULTIPLE	ON 🗆	SUB: REMEDIAL WORK COMMENCE DRI	SEQUENT RE	PORT OF ALTERING CASING & PLUG AND A PLUG AN
NOTICE OF IN' PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING   OTHER:  13. Describe proposed or complete.	TENTION TO: PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clea	ON	SUB: REMEDIAL WORL COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Description of the details and	SEQUENT RE  K	PEUG AND LOCASINE DANDONMENT
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or complete of starting any proposed work.	TENTION TO: PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION eted operations. (Cleark). SEE RULE 1103.	ON	SUB: REMEDIAL WORL COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Description of the completions: Att	SEQUENT RE  K	PEUG AND ABANDONMENT  Les, including estimated date ram of proposed completion
NOTICE OF IN  PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING   OTHER:  13. Describe proposed or complete of starting any proposed work or recompletion. Rig up	TENTION TO: PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION eted operations. (Cleark). SEE RULE 1103. unit. Set CIB	ON	SUB: REMEDIAL WORK COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Detrinent details, and le Completions: Att	SEQUENT RE  K	PEUG AND ABANDONMENT  Des, including estimated date ram of proposed completion on top PBID 3970 ft.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMP	TENTION TO: PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION  eted operations. (Cleark). SEE RULE 1103. o unit. Set CIB 3746 - 3756. R	ON   Conclusion  The state all properties. For Multiples at 3990 Run packer	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Dertinent details, and oft. Dump 20 c and acidize	SEQUENT RE  K	PEUG AND ABANDONMENT  Des, including estimated date ram of proposed completion on top PBTD 3970 ft. allons 15% NE/FE
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY ABANDON TO THER:  13. Describe proposed or complete of starting any proposed work or recompletion. Rig up Perforate 10 holes and balls. Swab bar	TENTION TO: PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION  eted operations. (Cleark). SEE RULE 1103. o unit. Set CIB 3746 - 3756. R	ON   Conclusion  The state all properties. For Multiples at 3990 Run packer	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Dertinent details, and oft. Dump 20 c and acidize	SEQUENT RE  K	PEUG AND ABANDONMENT  Des, including estimated date ram of proposed completion on top PBTD 3970 ft. allons 15% NE/FE
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMP	TENTION TO: PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION  eted operations. (Cleark). SEE RULE 1103. o unit. Set CIB 3746 - 3756. R	ON   Conclusion  The state all properties. For Multiples at 3990 Run packer	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Dertinent details, and oft. Dump 20 c and acidize	SEQUENT RE  K	PEUG AND ABANDONMENT  Des, including estimated date ram of proposed completion on top PBTD 3970 ft. allons 15% NE/FE
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY ABANDON TO THER:  13. Describe proposed or complete of starting any proposed work or recompletion. Rig up Temporate 10 holes and balls. Swab bat 12 bbls water.	TENTION TO: PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION  eted operations. (Cleark). SEE RULE 1103. unit. Set CIB 3746 - 3756. R ck load. Put w	ON   Control  Control  Control  Arriy state all parriy st	SUB REMEDIAL WORK COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Dertinent details, and le Completions: Att Oft. Dump 20 r and acidize	SEQUENT RE  K	PEUG AND ABANDONMENT  Les, including estimated date ram of proposed completion on top PBTD 3970 ft. Allons 15% NE/FE  10 MCF gas
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY ABANDON TO THER:  13. Describe proposed or complete of starting any proposed work or recompletion. Rig up Perforate 10 holes and balls. Swab bar	TENTION TO: PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION  eted operations. (Cleark). SEE RULE 1103. unit. Set CIB 3746 - 3756. R ck load. Put w	ON   The state all party state all party state all party. For Multiple BP at 3990 Run packer well on purple to the best of the best state and party.	SUB: REMEDIAL WORL COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Dertinent details, and le Completions: Att Oft. Dump 20 r and acidize Lump. Produced	SEQUENT RE    Comparison   Comp	PEUG AND ABANDONMENT  Les, including estimated date ram of proposed completion on top PBTD 3970 ft. Allons 15% NE/FE 10 MCF gas
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY ABANDON TO THER:  13. Describe proposed or complete of starting any proposed work or recompletion. Rig up Temporate 10 holes and balls. Swab bate 12 bbls water.  I hereby certify that the information a	TENTION TO: PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION  eted operations. (Cleark). SEE RULE 1103. unit. Set CIB 3746 - 3756. R ck load. Put w	ON   Carly state all party state all party. The state all party and packed well on purely collected to the become guidelines.	SUB: REMEDIAL WORL COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Dertinent details, and le Completions: Att Oft. Dump 20 r and acidize Lump. Produced	SEQUENT RE  K	PEUG AND ABANDONMENT  Les, including estimated date ram of proposed completion on top PBTD 3970 ft. Allons 15% NE/FE 10 MCF gas
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY ABANDON TO PULL OR ALTER CASING THER:  13. Describe proposed or complete of starting any proposed work or recompletion. Right up Perforate 10 holes and balls. Swab bate 12 bbls water.  I hereby certify that the information a grade tank has been/will be constructed or estimated the constructed or estimated the constructed or estimated the constructed or estimated.	TENTION TO: PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION  eted operations. (Cleark). SEE RULE 1103. o unit. Set CIB 3746 - 3756. R ck load. Put w	ON   Carly state all party state all party. The state all party and packed well on purely collected to the become guidelines.	SUB: REMEDIAL WORK COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Dertinent details, and le Completions: Att Oft. Dump 20 r and acidize and acidize est of my knowledge l, a general permit  RODUCTION SUP	SEQUENT RE    Comparison   Comp	PLUG AND ABANDONMENT  Les, including estimated date ram of proposed completion on top PBTD 3970 ft.  allons 15% NE/FE 10 MCF gas  Let certify that any pit or below- mative OCD-approved plan
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY ABANDON TO PULL OR ALTER CASING THER:  13. Describe proposed or complete of starting any proposed work or recompletion. Rig up Perforate 10 holes and balls. Swab bate 12 bbls water.  I hereby certify that the information a grade tank has been/will be constructed or c	TENTION TO: PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION  eted operations. (Cleark). SEE RULE 1103. o unit. Set CIB 3746 - 3756. R ck load. Put w	ON   The state all properties of the become and the	SUB: REMEDIAL WORL COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Dertinent details, and le Completions: Att Oft. Dump 20 r and acidize amp. Produced est of my knowledge l, a general permit  RODUCTION SUP	SEQUENT RE  K	PEUG AND ABANDONMENT  Les, including estimated date ram of proposed completion on top PBTD 3970 ft.  Allons 15% NE/FE 10 MCF gas  Let certify that any pit or belownative OCD-approved plan  DATE 9-2-04
NOTICE OF IN PERFORM REMEDIAL WORK  TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:  13. Describe proposed or complete of starting any proposed work or recompletion. Rig up Perforate 10 holes and balls. Swab bates and balls. Swab bates are supported to the starting and balls. Swab bates and balls water.  I hereby certify that the information a grade tank has been/will be constructed or of SIGNATURE.  Type or print name MIKE COPELANT.	TENTION TO: PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION  eted operations. (Cleark). SEE RULE 1103. o unit. Set CIB 3746 - 3756. R ck load. Put w	ON   The state all properties of the become and the	SUB REMEDIAL WORK COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Dertinent details, and le Completions: Att Oft. Dump 20 r and acidize amp. Produced est of my knowledge l, a general permit RODUCTION SUP	SEQUENT RE  K  LLING OPNS.  By the pertinent date and wellbore diagnostic to the cement with 1000 gas and belief. I further an (attached) alternal (attached) alternal (attached) alternal (attached) alternal (attached) alternal (attached) alternal (attached).	PEUG AND  ABANDONMENT  Les, including estimated date ram of proposed completion on top PBTD 3970 ft.  Allons 15% NE/FE  10 MCF gas  Let certify that any pit or belownative OCD-approved plan .  DATE 9-2-04  Lelephone No505-395-3056
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY ABANDON TEMPORARILY ABANDON TO THER:  13. Describe proposed or complete of starting any proposed work or recompletion. Rig up Perforate 10 holes and balls. Swab bates and balls. Swab bates and balls water.  I hereby certify that the information a grade tank has been/will be constructed or constru	TENTION TO: PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION  eted operations. (Cleark). SEE RULE 1103. o unit. Set CIB 3746 - 3756. R ck load. Put w	ON   The state all properties of the properties	SUB REMEDIAL WORK COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Dertinent details, and le Completions: Att Oft. Dump 20 r and acidize amp. Produced est of my knowledge l, a general permit RODUCTION SUP	SEQUENT RE  K  LLING OPNS.  By the pertinent date and wellbore diagnostic to the cement with 1000 gas and belief. I further an (attached) alternal (attached) alternal (attached) alternal (attached) alternal (attached) alternal (attached) alternal (attached).	PEUG AND ABANDONMENT  Les, including estimated date ram of proposed completion on top PBTD 3970 ft.  Allons 15% NE/FE 10 MCF gas  Let certify that any pit or belownative OCD-approved plan  DATE 9-2-04