State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

	OIL CONSERVA	ATTOM DIVISION		
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240		St. Francis Dr. NM 87505	WELL API NO. 30-025-	26935
DISTRICT II	,		5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE X	FEE
DISTRICT III			6. State Oil & Gas Lease No.	, , l
1000 Rio Brazos Rd, Aztec, NM 87410				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreeme	ent Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			 NORTH HOBBS (G/SA) U	INIT
(=	APPLICATION FOR PERMIT" (Form C-1		Section 30	
1. Type of Well:		, , , , , , , , , , , , , , , , , , , ,	8. Well No. 232	<u>-</u>
Oil Well Gas Well Other Injector			232	
2. Name of Operator			9. OGRID No. 157984	
Occidental Permian Ltd.				
3. Address of Operator			10. Pool name or Wildcat	HOBBS (G/SA)
1017 W. Stanolind Rd., HOBBS,	NM 88240 505/39	7-8200		, ,
4. Well Location				
Unit Letter K : 1400	Feet From The SOUTH	1370 Feet	t From The WEST	Line
Section 30	Township 18-S	Range 38-E	NMPM	LEA County
	11. Elevation (Show whether DF, RF 3651' GR	(B, RT GR, etc.)		
Die - Dalam and Taul Annlinetian		***		
Pit or Below-grade Tank Application	or Closure			
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
NOTICE OF IN	ENTION TO.	3063	EQUENT REPORT OF	·
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	X ALTERING	CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS.			NS. DLUG & AE	BANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN	IT JOB	
OTHED:		OTHER:		
OTHER:		OTHER:		
13. Describe Proposed or Completed Op	perations (Clearly state all pertinent d . For Multiple Completions: Attach w	etails, and give pertinent dates		arting any
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103	. For Multiple Completions: Attach w	etails, and give pertinent dates		arting any
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103 1. RUPU. Pull injection equipmen	For Multiple Completions: Attach wt.	etails, and give pertinent dates		arting any
 Describe Proposed or Completed Opproposed work) SEE RULE 1103 RUPU. Pull injection equipmen Sqz perfs 4138 to 4158 using 15 	t. O sx Prem + cmt w/3% CaCl.	etails, and give pertinent dates vellbore diagram of proposed o		arting any
 Describe Proposed or Completed Opproposed work) SEE RULE 1103 RUPU. Pull injection equipmen Sqz perfs 4138 to 4158 using 15 	t. 0 sx Prem + cmt w/3% CaCl. 24204-10 using 2 spf and 180 deg p	etails, and give pertinent dates vellbore diagram of proposed o		arting any
 Describe Proposed or Completed Opproposed work) SEE RULE 1103 RUPU. Pull injection equipmen Sqz perfs 4138 to 4158 using 15 Perforate the following intervals Stimulate perfs 4204-4266 w/10 RIH w/Guiberson 5.5" UNI VI p 	t. 0 sx Prem + cmt w/3% CaCl. 4204-10 using 2 spf and 180 deg p 50 g 15% acid. c pkr w/XL on/off tool w/1.875 ss"	etails, and give pertinent dates vellbore diagram of proposed control of the cont	completion or recompletion.	arting any
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103 1. RUPU. Pull injection equipment 2. Sqz perfs 4138 to 4158 using 15 3. Perforate the following intervals 4. Stimulate perfs 4204-4266 w/10 5. RIH w/Guiberson 5.5" UNI VI p. 6. Circ csg w/100 bbl pkr fluid. Tst	t. 0 sx Prem + cmt w/3% CaCl. 2 4204-10 using 2 spf and 180 deg p 50 g 15% acid.	etails, and give pertinent dates vellbore diagram of proposed control of the cont	completion or recompletion.	arting any
 Describe Proposed or Completed Opproposed work) SEE RULE 1103 RUPU. Pull injection equipmen Sqz perfs 4138 to 4158 using 15 Perforate the following intervals Stimulate perfs 4204-4266 w/10 RIH w/Guiberson 5.5" UNI VI p 	t. 0 sx Prem + cmt w/3% CaCl. 4204-10 using 2 spf and 180 deg p 50 g 15% acid. c pkr w/XL on/off tool w/1.875 ss"	etails, and give pertinent dates vellbore diagram of proposed control of the cont	completion or recompletion.	arting any
 Describe Proposed or Completed Opproposed work) SEE RULE 1103 RUPU. Pull injection equipmen Sqz perfs 4138 to 4158 using 15 Perforate the following intervals Stimulate perfs 4204-4266 w/10 RIH w/Guiberson 5.5" UNI VI p Circ csg w/100 bbl pkr fluid. Tst RDPU. Clean Location. 	t. 0 sx Prem + cmt w/3% CaCl. 4204-10 using 2 spf and 180 deg p 50 g 15% acid. c pkr w/XL on/off tool w/1.875 ss"	etails, and give pertinent dates vellbore diagram of proposed control of the cont	completion or recompletion.	arting any
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103 1. RUPU. Pull injection equipmen 2. Sqz perfs 4138 to 4158 using 15 3. Perforate the following intervals 4. Stimulate perfs 4204-4266 w/10 5. RIH w/Guiberson 5.5" UNI VI p. 6. Circ csg w/100 bbl pkr fluid. Tst 7. RDPU. Clean Location. Rig Up Date: 02/28/2005	t. 0 sx Prem + cmt w/3% CaCl. 4204-10 using 2 spf and 180 deg p 50 g 15% acid. c pkr w/XL on/off tool w/1.875 ss"	etails, and give pertinent dates vellbore diagram of proposed control of the cont	completion or recompletion.	arting any
 Describe Proposed or Completed Opproposed work) SEE RULE 1103 RUPU. Pull injection equipmen Sqz perfs 4138 to 4158 using 15 Perforate the following intervals Stimulate perfs 4204-4266 w/10 RIH w/Guiberson 5.5" UNI VI p Circ csg w/100 bbl pkr fluid. Tst RDPU. Clean Location. 	t. 0 sx Prem + cmt w/3% CaCl. 4204-10 using 2 spf and 180 deg p 50 g 15% acid. c pkr w/XL on/off tool w/1.875 ss"	etails, and give pertinent dates vellbore diagram of proposed control of the cont	completion or recompletion.	arting any
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103 1. RUPU. Pull injection equipmen 2. Sqz perfs 4138 to 4158 using 15 3. Perforate the following intervals 4. Stimulate perfs 4204-4266 w/10 5. RIH w/Guiberson 5.5" UNI VI p. 6. Circ csg w/100 bbl pkr fluid. Tst 7. RDPU. Clean Location. Rig Up Date: 02/28/2005	t. 0 sx Prem + cmt w/3% CaCl. 4204-10 using 2 spf and 180 deg p 50 g 15% acid. c pkr w/XL on/off tool w/1.875 ss"	etails, and give pertinent dates vellbore diagram of proposed control of the cont	completion or recompletion.	arting any
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103 1. RUPU. Pull injection equipmen 2. Sqz perfs 4138 to 4158 using 15 3. Perforate the following intervals 4. Stimulate perfs 4204-4266 w/10 5. RIH w/Guiberson 5.5" UNI VI p 6. Circ csg w/100 bbl pkr fluid. Tst 7. RDPU. Clean Location. Rig Up Date: 02/28/2005 Rig Down Date: 03/09/2005	t. 0 sx Prem + cmt w/3% CaCl. 4204-10 using 2 spf and 180 deg p 50 g 15% acid. c pkr w/XL on/off tool w/1.875 ss" c csg to 650 psi for 30 min and chart	etails, and give pertinent dates rellbore diagram of proposed control of the cont	completion or recompletion.	arting any
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103 1. RUPU. Pull injection equipmen 2. Sqz perfs 4138 to 4158 using 15 3. Perforate the following intervals 4. Stimulate perfs 4204-4266 w/10 5. RIH w/Guiberson 5.5" UNI VI p. 6. Circ csg w/100 bbl pkr fluid. Tst 7. RDPU. Clean Location. Rig Up Date: 02/28/2005	t. 0 sx Prem + cmt w/3% CaCl. 4204-10 using 2 spf and 180 deg p 50 g 15% acid. c pkr w/XL on/off tool w/1.875 ss" c csg to 650 psi for 30 min and chart	etails, and give pertinent dates rellbore diagram of proposed of the control of t	completion or recompletion.	arting any
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103 1. RUPU. Pull injection equipment 2. Sqz perfs 4138 to 4158 using 153. Perforate the following intervals 4. Stimulate perfs 4204-4266 w/105. RIH w/Guiberson 5.5" UNI VI p. 6. Circ csg w/100 bbl pkr fluid. Tst 7. RDPU. Clean Location. Rig Up Date: 02/28/2005 Rig Down Date: 03/09/2005	t. 0 sx Prem + cmt w/3% CaCl. 4204-10 using 2 spf and 180 deg p 50 g 15% acid. c pkr w/XL on/off tool w/1.875 ss" c csg to 650 psi for 30 min and chart	etails, and give pertinent dates vellbore diagram of proposed of the control of t	completion or recompletion. Soline tbg. Pkr set @4055'.	
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103 1. RUPU. Pull injection equipmen 2. Sqz perfs 4138 to 4158 using 15 3. Perforate the following intervals 4. Stimulate perfs 4204-4266 w/10 5. RIH w/Guiberson 5.5" UNI VI p 6. Circ csg w/100 bbl pkr fluid. Tst 7. RDPU. Clean Location. Rig Up Date: 02/28/2005 Rig Down Date: 03/09/2005	t. 0 sx Prem + cmt w/3% CaCl. 4204-10 using 2 spf and 180 deg p 50 g 15% acid. c pkr w/XL on/off tool w/1.875 ss" c csg to 650 psi for 30 min and chart	etails, and give pertinent dates vellbore diagram of proposed of the control of t	completion or recompletion.	
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103 1. RUPU. Pull injection equipment 2. Sqz perfs 4138 to 4158 using 153. Perforate the following intervals 4. Stimulate perfs 4204-4266 w/105. RIH w/Guiberson 5.5" UNI VI p. 6. Circ csg w/100 bbl pkr fluid. Tst 7. RDPU. Clean Location. Rig Up Date: 02/28/2005 Rig Down Date: 03/09/2005	t. 0 sx Prem + cmt w/3% CaCl. 4204-10 using 2 spf and 180 deg p 50 g 15% acid. pc pkr w/XL on/off tool w/1.875 ss ³³ c csg to 650 psi for 30 min and chart	etails, and give pertinent dates vellbore diagram of proposed of the control of t	completion or recompletion. Soline tbg. Pkr set @4055'.	
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103 1. RUPU. Pull injection equipmen 2. Sqz perfs 4138 to 4158 using 15 3. Perforate the following intervals 4. Stimulate perfs 4204-4266 w/10 5. RIH w/Guiberson 5.5" UNI VI p 6. Circ csg w/100 bbl pkr fluid. Tst 7. RDPU. Clean Location. Rig Up Date: 02/28/2005 Rig Down Date: 03/09/2005 closed according to NMOCD guidelines SIGNATURE	t. 0 sx Prem + cmt w/3% CaCl. 4204-10 using 2 spf and 180 deg p 50 g 15% acid. be pkr w/XL on/off tool w/1.875 ss" c csg to 650 psi for 30 min and chart yet	etails, and give pertinent dates vellbore diagram of proposed of the control of t	completion or recompletion. Pkr set @4055'. Completion or recompletion. Pkr set @4055'. Completion Specialist DATE TELEPHONE NO.	03/18/2005
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103 1. RUPU. Pull injection equipment 2. Sqz perfs 4138 to 4158 using 15 3. Perforate the following intervals 4. Stimulate perfs 4204-4266 w/10 5. RIH w/Guiberson 5.5" UNI VI proposed for cost of the following intervals 7. RDPU. Clean Location. Rig Up Date: 02/28/2005 Rig Down Date: 03/09/2005 closed according to NMOCD guidelines 12 SIGNATURE 12 Public 13 SIGNATURE 12 TYPE OR PRINT NAME 14 Robert Gills 15 For State Use Only	t. 0 sx Prem + cmt w/3% CaCl. 4204-10 using 2 spf and 180 deg p 50 g 15% acid. be pkr w/XL on/off tool w/1.875 ss" c csg to 650 psi for 30 min and chart yet	etails, and give pertinent dates vellbore diagram of proposed of the control of t	completion or recompletion. Pkr set @4055'. Completion or recompletion. Pkr set @4055'. Completion Specialist DATE TELEPHONE NO.	03/18/2005 505/397-8206
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103 1. RUPU. Pull injection equipment 2. Sqz perfs 4138 to 4158 using 153. Perforate the following intervals 4. Stimulate perfs 4204-4266 w/105. RIH w/Guiberson 5.5" UNI VI p. 6. Circ csg w/100 bbl pkr fluid. Tst 7. RDPU. Clean Location. Rig Up Date: 02/28/2005 Rig Down Date: 03/09/2005 closed according to NMOCD guidelines SIGNATURE TYPE OR PRINT NAME Robert Gills For State Use Only APPROVED BY	t. 0 sx Prem + cmt w/3% CaCl. 4204-10 using 2 spf and 180 deg p 50 g 15% acid. be pkr w/XL on/off tool w/1.875 ss" c csg to 650 psi for 30 min and chart yet	etails, and give pertinent dates vellbore diagram of proposed of the control of t	completion or recompletion. Pkr set @4055'. Completion or recompletion. Pkr set @4055'. Completion Specialist DATE TELEPHONE NO.	03/18/2005 505/397-8206
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103 1. RUPU. Pull injection equipmen 2. Sqz perfs 4138 to 4158 using 15 3. Perforate the following intervals 4. Stimulate perfs 4204-4266 w/10 5. RIH w/Guiberson 5.5" UNI VI p. 6. Circ csg w/100 bbl pkr fluid. Tst 7. RDPU. Clean Location. Rig Up Date: 02/28/2005 Rig Down Date: 03/09/2005 closed according to NMOCD guidelines SIGNATURE TYPE OR PRINT NAME Robert Gills For State Use Only	t. 0 sx Prem + cmt w/3% CaCl. 4204-10 using 2 spf and 180 deg p 50 g 15% acid. be pkr w/XL on/off tool w/1.875 ss" c csg to 650 psi for 30 min and chart yet	etails, and give pertinent dates vellbore diagram of proposed of the control of t	completion or recompletion. Pkr set @4055'. Completion or recompletion. Pkr set @4055'. Completion Specialist DATE TELEPHONE NO.	03/18/2005 505/397-8206

