

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

HOBBBS OCD

OIL CONSERVATION DIVISION

APR 24 2013 1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☒

2. Name of Operator

XTO Energy, Inc.

3. Address of Operator

200 N. Lorraine, Ste. 800 Midland, TX 79701

4. Well Location

Unit Letter C : 660 feet from the North line and 1980 feet from the West line

Section 35 Township 21S Range 36E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

WELL API NO.

30-025-04925

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

W A Ramsay NCT 'A'

8. Well Number

18

9. OGRID Number

005380

10. Pool name or Wildcat

Eumant, Yates - 7 Rurs-On

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P AND A ☐

CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

XTO Energy, Inc would like to propose the following as a PxA:

1. Tag existing CIBP.
2. RIH, set CIBP @ 2900'. Cap w/35' cmt. Circ hole w/mud laden fluid.
3. Set 25sx cmt plug @ 1300'.
4. Perf @ 340'. Circ cmt to surface inside & outside csg.
5. Cut off WH, install dry hole marker.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Stephanie Rabadue

TITLE Regulatory Analyst

DATE 04/22/2013

Type or print name Stephanie Rabadue

E-mail address: stephanie.rabadue@xtoenergy.com

PHONE 432-620-6714

For State Use Only

APPROVED BY [Signature]

TITLE Dist. Mgr

DATE 4-25-2013


Conditions of Approval (if any):

APR 25 2013



W. A. RAMSEY NCT 'A' #18

WELLBORE DIAGRAM



GL: 3553'
KB: 3562'
DF: 3561'

DATA

LOCATION: 660' FNL & 1980' FWL, UNIT C. SEC. 35, T-21-S, R-36E

COUNTY/STATE: LEA COUNTY, NM

FIELD: EUMONT

FORMATION:

INITIAL IP:

API #: 30-025-04925

CURRENT STATUS:

PERFS:

2978', 2984',
3079', 3088',
3097', 3107',
3115', 3124',
3133', 3173',
3192', 3202',
3212', 3251'

QUEEN PERFS: W/ 4 JHPE

3760'-66", 3770'-3782'
3798'-3812', 3824'-42'
5 1/4" 14# J-55 CSG @ 3859'. CMT W/2100 SX. DID NOT CIRC. TOC @ 385'