Office	State of New Mexico Minerals and Natural Resources	Form C-103 Revised August 1, 2011		
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.			
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 JAN 17 2015 CC	30-025-32903 5. Indicate Type of Lease			
$\frac{\text{District III}}{\text{District III}} = (303) 334-0178$	20 South St. Francis Dr.	STATE FEE		
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.			
SUNDRY NOTICES AND REP (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL O		7. Lease Name or Unit Agreement Name		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PER	V.M. HENDERSON			
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Gas Well	8. Well Number: 13			
2. Name of Operator Chevron U.S.A. INC.	9. OGRID Number 4323			
3. Address of Operator 6301 DEAUVILLE BLVD, MIDLAND, TX 7	9706 RMN3002	10. Pool name or Wildcat PENROSE SKELLY; GRAYBURG		
4. Well Location				
	om the <u>NORTH</u> line and	660 feet from the WEST line		
	ownship 21S Range 37E (Show whether DR, RKB, RT, GR, etc.	NMPM County Lea		
3503'	(Snow whether DR, RRB, R1, GR, etc.)			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION T		SEQUENT BERGET OF		
PERFORM REMEDIAL WORK ☐ PLUG AND A TEMPORARILY ABANDON ☐ CHANGE PLA				
PULL OR ALTER CASING MULTIPLE CO				
DOWNHOLE COMMINGLE	_	P&A R		
		1 000 11		
	□ OTHER:			
OTHER: 13. Describe proposed or completed operations		d give pertinent dates, including estimated date		
OTHER:	. (Clearly state all pertinent details, and	d give pertinent dates, including estimated date		
OTHER: 13. Describe proposed or completed operations of starting any proposed work). SEE RULI proposed completion or recompletion.	. (Clearly state all pertinent details, and E 19.15.7.14 NMAC. For Multiple Con	d give pertinent dates, including estimated date		
OTHER: 13. Describe proposed or completed operations of starting any proposed work). SEE RULI	. (Clearly state all pertinent details, and E 19.15.7.14 NMAC. For Multiple Con	d give pertinent dates, including estimated date		
OTHER: 13. Describe proposed or completed operations of starting any proposed work). SEE RULI proposed completion or recompletion. 1. Call and notify NMOCD 24 hrs. 12. MIRU. NDWH. NU BOPE.	E 19.15.7.14 NMAC. For Multiple Conbefore operations begin.	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of		
OTHER: 13. Describe proposed or completed operations of starting any proposed work). SEE RULI proposed completion or recompletion. 1. Call and notify NMOCD 24 hrs. 12. MIRU. NDWH. NU BOPE. 3. Set CIBP@3,350',circulate well seed to the completion of the completion of the completion.	before operations begin. w/9.5 ppg mud and spot 25sx	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of of cmt. on top. Pressure test casing.		
OTHER: 13. Describe proposed or completed operations of starting any proposed work). SEE RULL proposed completion or recompletion. 1. Call and notify NMOCD 24 hrs. In 2. MIRU. NDWH. NU BOPE. 3. Set CIBP@3,350',circulate well with the second completion.	before operations begin. w/9.5 ppg mud and spot 25sx of the many state all pertinent details, and the many state all pertinent details and the many state all pertinent details, and the many state all pertinent details, and the many state all pertinent details, and the many state all pertinent details and the many state all pertinent d	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of of cmt. on top. Pressure test casing.		
OTHER: 13. Describe proposed or completed operations of starting any proposed work). SEE RULI proposed completion or recompletion. 1. Call and notify NMOCD 24 hrs. 12. MIRU. NDWH. NU BOPE. 3. Set CIBP@3,350',circulate well with the second completion of the second completion.	before operations begin. w/9.5 ppg mud and spot 25sx of com 2,310'-2,110', WOC&Tagorn 1,250-1,050'; WOC&Tagorn 2,000 and 2,00	of cmt. on top. Pressure test casing. g. (B.Salt) 2500' (T.Salt) 1400'		
13. Describe proposed or completed operations of starting any proposed work). SEE RULL proposed completion or recompletion. 1. Call and notify NMOCD 24 hrs. It 2. MIRU. NDWH. NU BOPE. 3. Set CIBP@3,350',circulate well with the second completion of the second completion of the second completion of the second completion of the second complete	before operations begin. w/9.5 ppg mud and spot 25sx om 2,310'-2,110', WOC&Tagom 1,250-1,050'; WOC&Tagom 475' to surface. (Shoe/FW	of cmt. on top. Pressure test casing. (T.Salt) 1400 (Vsurface).		
OTHER: 13. Describe proposed or completed operations of starting any proposed work). SEE RULL proposed completion or recompletion. 1. Call and notify NMOCD 24 hrs. In the standard starting any proposed work). SEE RULL proposed completion or recompletion. 1. Call and notify NMOCD 24 hrs. In the standard starting in the starting in	before operations begin. w/9.5 ppg mud and spot 25sx of the company of the compa	of cmt. on top. Pressure test casing. g. (B.Salt) 2500' (T.Salt) 1400' //surface). nchors 3' below grade. Weld on		
other: 13. Describe proposed or completed operations of starting any proposed work). SEE RULL proposed completion or recompletion. 1. Call and notify NMOCD 24 hrs. In the starting and proposed completion or recompletion. 2. MIRU. NDWH. NU BOPE. 3. Set CIBP@3,350', circulate well with the starting and complete to the starting and proposed complete on the starting and proposed work). See RULL proposed complete on the starting and proposed work). See RULL proposed complete on the starting and proposed work). See RULL proposed complete on the starting and proposed work). See RULL proposed complete on the starting and proposed work). See RULL proposed completion or recompletion.	before operations begin. w/9.5 ppg mud and spot 25sx of the state of 1,250-1,050°; WOC&Tag. om 475° to surface. (Shoe/FW asings. Cut off wellhead and and the state of the st	of cmt. on top. Pressure test casing. g. (B.Salt) 2500' (T.Salt) 1400' //surface). nchors 3' below grade. Weld on		
other: 13. Describe proposed or completed operations of starting any proposed work). SEE RULL proposed completion or recompletion. 1. Call and notify NMOCD 24 hrs. In the starting any proposed work). SEE RULL proposed completion or recompletion. 1. Call and notify NMOCD 24 hrs. In the starting and seed the starting any proposed completion or recompletion. 2. MIRU. NDWH. NU BOPE. 3. Set CIBP@3,350', circulate well with the starting and clean from the starting and clean seed the starting and clean location of starting any proposed work). SEE RULL proposed work).	before operations begin. w/9.5 ppg mud and spot 25sx of the state of 1,250-1,050°; WOC&Tag. om 475° to surface. (Shoe/FW asings. Cut off wellhead and and the state of the st	of cmt. on top. Pressure test casing. g. (B.Salt) 2500' (T.Salt) 1400' //surface). nchors 3' below grade. Weld on		
 Describe proposed or completed operations of starting any proposed work). SEE RULL proposed completion or recompletion. Call and notify NMOCD 24 hrs. In the completion of the completion. MIRU. NDWH. NU BOPE. Set CIBP@3,350', circulate well of the completion. Spot 25sx of Class "C" cement for the completion. Spot 25sx of Class "C" cement for the completion. Verify cement to surface on all can dryhole marker and clean location. Closed loop above ground tank symmetric complete. 	before operations begin. w/9.5 ppg mud and spot 25sx of the state of 1,250-1,050°; WOC&Tag. om 475° to surface. (Shoe/FW asings. Cut off wellhead and and the state of the st	of cmt. on top. Pressure test casing. g. (B.Salt) 2500' (T.Salt) 1400' //surface). nchors 3' below grade. Weld on		
other: 13. Describe proposed or completed operations of starting any proposed work). SEE RULL proposed completion or recompletion. 1. Call and notify NMOCD 24 hrs. In the starting any proposed work). SEE RULL proposed completion or recompletion. 1. Call and notify NMOCD 24 hrs. In the starting and seed the starting any proposed completion or recompletion. 2. MIRU. NDWH. NU BOPE. 3. Set CIBP@3,350', circulate well with the starting and clean from the starting and clean seed the starting and clean location of starting any proposed work). SEE RULL proposed work).	before operations begin. w/9.5 ppg mud and spot 25sx of the state of 1,250-1,050°; WOC&Tag. om 475° to surface. (Shoe/FW asings. Cut off wellhead and and the state of the st	of cmt. on top. Pressure test casing. (T.Salt) 1400 (Vsurface).		
13. Describe proposed or completed operations of starting any proposed work). SEE RULI proposed completion or recompletion. 1. Call and notify NMOCD 24 hrs. In the starting and notify NMOCD 24 hrs. In	before operations begin. w/9.5 ppg mud and spot 25sx or 2,310°-2,110°, WOC&Tagrom 475° to surface. (Shoe/FW asings. Cut off wellhead and an eystem will be used for fluids. NOTIFY OC BEGINNING	of cmt. on top. Pressure test casing. g. (B.Salt) 2500 (T.Salt) 1400 Vsurface). nchors 3' below grade. Weld on ED 24 HOURS PRIOR TO ED 24 HOURS OPERATIONS ES PLUGGING OPERATIONS		
13. Describe proposed or completed operations of starting any proposed work). SEE RULL proposed completion or recompletion. 1. Call and notify NMOCD 24 hrs. It 2. MIRU. NDWH. NU BOPE. 3. Set CIBP@3,350',circulate well with 4. Spot 25sx of Class "C" cement from 5. Spot 25sx of Class "C" cement from 6. Spot 55sx of Class "C" cement from 7. Verify cement to surface on all care dryhole marker and clean location closed loop above ground tank systems.	before operations begin. w/9.5 ppg mud and spot 25sx om 2,310'-2,110', WOC&Tagom 1,250-1,050'; WOC&Tagom 475' to surface. (Shoe/FWasings. Cut off wellhead and and surface.) ystem will be used for fluids. TITLE Project Manager	of cmt. on top. Pressure test casing. g. (B.Salt) 2500′ (T.Salt) 1400′ //surface). nchors 3' below grade. Weld on DATE 01/16/17		
13. Describe proposed or completed operations of starting any proposed work). SEE RULI proposed completion or recompletion. 1. Call and notify NMOCD 24 hrs. In the starting and notify NMOCD 24 hrs. In	before operations begin. w/9.5 ppg mud and spot 25sx of the second 2,310'-2,110', WOC&Tag om 1,250-1,050'; WOC&Tag om 475' to surface. (Shoe/FW asings. Cut off wellhead and an	of cmt. on top. Pressure test casing. (B.Salt) 2500 (T.Salt) 1400 (T.Salt) 1400 (T.Surface). (T.Salt) PRIOR TO (S.D 24 HOURS PRIOR TO (S.D 24 HOURS OPERATIONS) (S.D 24 HOURS OPERATIONS)		
13. Describe proposed or completed operations of starting any proposed work). SEE RULL proposed completion or recompletion. 1. Call and notify NMOCD 24 hrs. In the starting any proposed work). SEE RULL proposed completion or recompletion. 1. Call and notify NMOCD 24 hrs. In the starting and notify NMOCD 24 hrs. In the st	before operations begin. w/9.5 ppg mud and spot 25sx of the second 2,310'-2,110', WOC&Tag om 1,250-1,050'; WOC&Tag om 475' to surface. (Shoe/FW asings. Cut off wellhead and an	of cmt. on top. Pressure test casing. g. (B.Salt) 2500′ (T.Salt) 1400′ //surface). nchors 3' below grade. Weld on DATE 01/16/17		







Chevron U.S.A. Inc. Wellbore Diagram: VMHENDERSON13G

Lease: OEU EUNICE FMT

Well No.: HENDERSON V. M. 13G Field: PENROSE SKELLY

Location: 1890FNL660FWL

Sec.: N/A

Blk: Survey: N/A

County: Lea St.: New Mexico Refno: BE3398

API: 3002532903 Cost Center: UCU493800

Section: E037


Township: 30 S

Range: S021 E

Current Status: ACTIVE

Dead Man Anchors Test Date: NONE

Directions:



Ground Elevation (MSL): 3503.00 Well Depth Datum: Kelly Bushing

Spud Date: 06/19/1995 Elevation (MSL): 0.00

Compl. Date: 09/01/2003 Correction Factor: 10.00

Last Updated by: kswa

Date: 01/09/2015

PROPOSED WELLBORE DIAGRAM

Lease: Location:	V.M. HEND	DERSON & 660' FWL	Well No: 13 30-T21S-37	Field: PENROSE SKELLY; GRAYBURG
County:	Lea			API: <u>30-025-06902</u> Cost Center:
Surface Csg Size: Wt.: Set @: Sxs cmt: Circ: TOC: Hole Size:	8-5/8" 24# 425 200 Yes Surf 12-1/4"			T.SALT 1420' B.SALT 2460'
Production Size: Wt.: Set @: Sxs Cmt: Circ: TOC Hole Size: PBTD: TD:	Csg. 5-1/2" 15.5# 3700' 725 Yes Surf 7-7/8"		MLF	SPOT 55SX CLASS "C" FROM 475'-SURFAC (SHOE/FW/SURFACE) SPOT 25SX CLASS "C" FROM 1250'-1185' (T.SALT) WOC&TAG
	Cement	t Squeezed Perfs 3390'-363		SPOT 25SX CLASS "C" FROM 2310'-2110' (B.SALT) WOC&TAG CIBP@3350' AND SPOT 25SX CLASS "C" CEMENT ON TOP
	OH 4-3/4"	3700'-3868'		
Remarks:				
			Updated by: LRQS Date: 01/16/17	Prepared by: Date: