Submit 1 Copy To Appropriate District	State of New Mexicon	Form C-103
Office <u>District I</u> – (575) 393-6161 E	nergy, Minerals and Natural Resources	Revised July 18, 2013 WELL API NO.
<u>District II</u> – (575) 748-1283	DIL CONSERVATION DIVISION	30-025-06397
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505//	STATE FEE ✓ 6. State Oil & Gas Lease No.
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505		0. State Off & Gas Lease NO.
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		West Blinebry Drinkard Unit (WBDU) / 37346
1. Type of Well: Oil Well Gas W	ell 🗌 Other Injection Well	8. Well Number 008
2. Name of Operator Apache Corporation	/	9. OGRID Number 873
3. Address of Operator		10. Pool name or Wildcat
303 Veterans Airpark Lane, Suite 1000 Mi	dland, TX 79705	Eunice; B-T-D, North (22900)
4. Well Location Unit Letter 1 : 1980 feet from the South line and 660 feet from the East line		
Unit Letter : 1980 Section 4	Township 21S Range 37E	feet from the Last line NMPM County Lea
	levation (Show whether DR, RKB, RT, GR, etc.)	
	3470' GL	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A		
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM		
OTHER: DEEPEN/RUN LINER OTHER: OTHER: OTHER: OTHER:		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
Apache intends to deepen this well, run a liner and conform to the Drinkard, per the attached procedure and WBD's.		
Spud Date: 4/1/1954	Rig Release Date: 4/16/1954	
Lharaby certify that the information above i	s true and complete to the best of my knowledge	e and halief
Thereby certify that the information above is	s the and complete to the best of my knowledg	e and bener.
SIGNATURE Roesa Lisho	C TITLE Sr. Staff Reg Analyst	DATE 1/11/2017
- pe	E-mail address: Reesa.Fisher@apa	achecorp.com PUONE. (432) 818 1062
Type or print name Reesa Fisher For State Use Only	E-mail address:	achecorp.com PHONE: (432) 818-1062
Petroleum Engineer nul aufen		
APPROVED BY: Conditions of Approval (if any):	TITLE FEIGICIAN 2-5	DATE 01/2//17
Conditions of Approvar (It ally).		

WBDU 8: Deepen Well, Run Liner and Conform to Drinkard (30-025-06397)

January 6, 2017

- Day 0: Prior to start of workover: Schedule and install buried fiberglass injection line.
- Day 1: MIRU. ND WH and NU BOPs. POOH and LD 2-3/8" Injection tubing.
- Day 2: RIH w/ Tungsten Carbide Junk Mill on 2-7/8" work string. Tag and drill out CICR at 6675', RU Foam N2 Unit as required.
- Day 3: Continue milling on CICR.
- Day 4/5: Continue milling on CICR. If no progress made, POOH and RIH with Cone Buster mill.
- **Day 6:** Continue milling on CICR. If seeing cement in returns, POOH and RIH w/ bit and continue drilling out cement to new TD of +/- 6821'. (+/- 75' below predicted bottom perf).
- **Day 7:** Complete drilling well out well to new TD at +/- 6821'. Circulate wellbore clean and POOH and LD 2-7/8" work string and bit.
- **Day 8:** RU casing crew and equipment and RIH with 4-1/2" 11.6 lb/ft flush joint casing with float collar and float shoe to +/- 6821'.

RU cement crew, perform single stage cement job to surface consisting of 300 bbl fresh water flush, 80 bbl stop loss spacer, and 181 sacks of TXI Lite cement + additives (weight 12.5 ppg, yield 1.64 cf/sack, volume 52.9 bbl), and 71 sacks of TXI Lite cement + additives (weight 13.2 ppg, yield 1.39 cf/sack, volume 17.6 bbl). Total 150% excess slurry of 70.5 bbl. Displace with 105 bbls fresh water (confirm all volumes).

- Day 9: WOC
- Day 10: RIH w/ 3-1/4" bit on 2-3/8" work string. Drill out float collar and cement to +/- 6806'. Circulate clean. POOH
- Day 11: MIRU WL and RIH w/ GR/CBL/CCL/CNL, log well from TD to surface, POOH
 - PU and RIH w/ 3-1/8" TAGs loaded with SDP charges and perforate the Drinkard @ 4 SPF, 90 deg phasing (estimated 70', 280 shots), POOH

PU and RIH w/ treating packer on 2-3/8" work string

Day 12: Cont. RIH w/ treating packer on 2-3/8" work string. Set packer @ +/-6550'

MIRU acid crew. Acidize the Drinkard w/10,000 gals 15% HCl and rock salt in 3 equal stages @ +/- 10 BPM. Release packer. Wash out salt. POOH

- Day 13: PU and RIH with 4-1/2" injection packer with 2-3/8" IPC tubing subs, upper and lower profile nipples, and on/off tool on 2-3/8" work string. Set packer @ +/-6550'. Release on/off tool and pressure test casing to 500 psi. POOH and LD 2-3/8" work string
- **Day 14:** PU & RIH w/2-3/8" IPC injection tubing and on/off tool. Circulate packer fluid and latch onto packer with on/off tool. ND BOPs and NU WH. Pressure test casing to 500 psi. RDMO.
- Day 15: Perform MIT test for NM OCD. Perform bottom hole static pressure test. Place well on injection.



