Form 3160-5 (June 2015)

## OCD-HOBBS

UNITED STATES DEPARTMENT OF THE INTERIOR


FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

. В						
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					5. Lease Serial No. NMNM03085	
					6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No. NM 709 766	
Type of Well     ☐ Gas Well ☐ Other					8. Well Name and No. LEA UNIT 17	
Name of Operator Contact: D. PATRICK DARDEN, PE LEGACY RESERVES OPERATING LÆ-Mail: pdarden@legacylp.com					9. API Well No. 30-025-32794	
3a. Address 303 W WALL ST SUITE 1800 MIDLAND, TX 79701		3b. Phone No. (include area code) Ph: 432-689-5200 Ext: 5237			10. Field and Pool or Exploratory Area LEA; DEVONIAN	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State	
Sec 13 T20S R34E SWSE 900 FSL 1756FEL					LEA CO COUNTY, NM	
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICAT	ΓE NATURE OF	NOTICE,	REPORT, OR OTH	IER DATA
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	☐ Acidize	☐ Deep	pen	☐ Product	ion (Start/Resume)	☐ Water Shut-Off
Notice of Intent	☐ Alter Casing	☐ Hydi	raulic Fracturing	☐ Reclam	ation	☐ Well Integrity
☐ Subsequent Report	☐ Casing Repair	□ New	Construction	Recomp	olete	Other
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug	and Abandon	☐ Tempor	arily Abandon	
	☐ Convert to Injection	☐ Convert to Injection ☐ Plug Back ☐ Water Disposal		Disposal		
13. Describe Proposed or Completed Op If the proposal is to deepen direction: Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f  Legacy Reserves will be testing be set at ~9,530' with 35' cem be perforated and tested from	ally or recomplete horizontally, rk will be performed or provide to operations. If the operation re bandonment Notices must be fi inal inspection.  In and recompleting the lent placed on top. New F	give subsurface let the Bond No. on sults in a multiple led only after all r	locations and measur file with BLM/BIA e completion or reco- requirements, including	ed and true von Required sumpletion in a ng reclamation	ertical depths of all pertin- bsequent reports must be new interval, a Form 3160 n, have been completed a	ent markers and zones. filed within 30 days 3-4 must be filed once and the operator has
Current and proposed wellbor	e diagrams attached.					
APPROVED						
SUBJECT TO LIKE						
APPROVAL BY STATE						
WITNESS						
14. I hereby certify that the foregoing is true and correct.  Electronic Submission #382110 verified by the BLM Well Information System  For LEGACY RESERVES OPERATING LP, sent to the Hobbs  Committed to AFMSS for processing by PRISCILLA PEREZ on 08/09/2017 ()						
Name (Printed/Typed) D. PATRICK DARDEN, PE			Title SR ENGINEERING ADVISOR			
Signature (Electronic	Submission)	Date 07/21/20	Date 07/21/2017			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved By Paul R Swart 10/23/17 Title TPET Date						
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office	CARLSBAD FIELD OFFICE		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

\*\* OPERATOR-SUBMITTED \*\* OPERATOR-SUBMITTED \*\* OPERATOR-SUBMITTED



## **Conditions of Approval**

## Legacy Reserves Operating, LP Lea Unit - 17, API 3002532794 T20S-R34E, Sec 13, 900FSL & 1756FEL October 23, 2017

- 1. Begin wellbore operations within 90 days of these conditions of approval for the processed Electronic Submission #382110 notice of intent or request an extension.
- 2. Operator is required to have the BLM approved NOI procedure with applicable conditions of approval on location during this workover operation.
- 3. Due to being within the Lesser Prairie Chicken habitat, this workover activity will be restricted to the hours of 9:00am through 3:00am for the period of March 1 through June 15.
- 4. The Unit agreement for this well (NM70976b) does not include the Delaware pay. Operator is removing well from the unitized formation. Operator shall remove "Unit" from the well name via sundry, and or rename well to produce on a lease basis.
- 5. Subject to like approval by the New Mexico Oil Conservation Division.
- 6. Before adding, replacing, or repairing casing or a liner, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 7. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 8. Surface disturbance beyond the existing pad shall have prior BLM approval.
- 9. Functional H<sub>2</sub>S monitoring equipment shall be on location.
- 10. Blow Out Prevention Equipment 5000 (5M) to be used. All BOPE and workover procedures shall establish fail safe well control. Ram(s) for the work string(s) used is required equipment. Manual BOP closure system including a blind ram and pipe ram(s) designed to close on all (hand wheels or automatic locking devices) equipment installed regardless of BOP design. Function test the installed BOPE to 500psig when well conditions allow. Related equipment, (choke manifolds, kill trucks, gas vent or flare lines, etc.) employed when needed for reasonable well control requirements.
- 11. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created during work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Portojohns and trash containers will be on-location during fracturing operations or any other crewintensive operations.
- 12. Notify BLM 575-393-3612 Lea Co as work begins. Some procedures witnessed. If there is no response, leave a voice mail with the API#, workover purpose, and a call back phone number.

- 13. The BLM PET witness is to run tbg tally and agree to cement volumes and placement. Sample each plug for cement curing time and tag and/or pressure test as requested by BLM PET witness.
- 14. This procedure is subject to the next three numbered paragraphs.
- 15. Set cement plugs to cover a minimum of 100ft plus 10ft for every 1,000ft from the bottom of the plug, rounding the number of necessary sacks up to the nearest 5 sacks. Never use less than 25sx. Examples: A cement plug set at 8000 in 7" casing would require a min of 35sx. A 25sx plug in 5 ½" casing should cover 250ft, which may exceed 100ft plus 10ft per 1000ft.
- 16. Class H > 7500ft & C < 7500ft) cement plugs(s) will be necessary. For any plug that requires a tag or pressure test a minimum WOC time of 4 hours(C) & 8 hours(H) is recommended. Formation isolation plugs of Class "C" to be mixed 14.8#/gal, 1.32 ft<sup>3</sup>/sx, 6.3gal/sx water and "H" to be mixed 16.4#/gal, 1.06ft<sup>3</sup>/sx, 4.3gal/sx water.
- 17. Minimum requirement for mud placed between plugs is 25 sacks of salt water gel per 100 barrels in 9 lb/gal brine.
- 18. Remove all restrictions within the 7" casing and tag and record PBTD above the CIBP set at 14300 on 06/08/1995.
- 19. Set a min 50sx Class "H" balanced plug on the PBTD, WOC and tag the plug with tbg at 14053' or above isolating the Devonian formation.
- 20. Set a CIBP within 100'above the top Morrow perf of 13022'. Set a min 75sx Class "H" balanced plug on the CIBP, WOC and tag the plug with tbg at 12661' or above covering the Morrow formation top at 12722'.
- 21. Set a CIBP within 100'above the top Strawn perf of 12345'. Set a min 30sx Class "H" balanced plug on the CIBP, WOC and tag the plug with tbg at 12202' or above covering the Strawn formation top at 12277'.
- 22. Set a CIBP within 100'above the top Bone Spring perf of 9558'. Set a min 30sx Class "H" balanced plug on the CIBP, WOC and tag the plug with tbg at 9416' or above covering the 1st Bone Spring sand at 9494'.
- 23. Set a min 25sx Class "H" balanced plug from 8370' over the Bone Spring formation top at 8274'. WOC and tag the plug with tbg at 8203' or above covering the Bone Spring formation top.
- 24. After setting the top plug and before perforating, **perform a charted casing integrity test** of 800psig minimum. Document the pressure test on a one hour full rotation calibrated (within 6 months) recorder chart registering within 35 to 85 per cent of its full range. **Verify all annular casing vents plumbed to the surface and open during this pressure test.** Call BLM 575-393-3612 Lea Co. and arrange for a BLM witness of that pressure test. Include a copy of the chart with the subsequent sundry for this workover.
- 25. Provide BLM with an electronic copy (Adobe Acrobat Document) cement bond log record from the new PBTD' with 0psig casing pressure to TOC. Attach the CBL to a pswartz@blm.gov email.
- 26. File **subsequent sundry** Form 3160-**5** within 30 days of workover procedures. Include (dated daily) descriptions of the well work, i.e. procedure descriptions and setting depths of each plug in the subsequent sundry.

- 27. The subsequent report is to include stimulation injection pressures. Report maximum/minimum injection rate (BPM) and max/min stimulation injection pressures.
- 28. Submit a (BLM Form 3160-5 subsequent report describing (dated daily) all wellbore activity and the Mechanical Integrity Test. File intermediate Form 3160-5 within 30 days of any interrupted workover procedures and a complete workover subsequent sundry.
- 29. A BLM Well Recompletion Form 3160-4 and a NMOCD Form C-102 "Well Location and Acreage Dedication Plat" with updated information is necessary with the subsequent package when recompletion changes a well's Pool designation.
- 30. File intermediate **subsequent sundry** Form 3160-**5** within 30 days of any interrupted workover procedures and a complete workover subsequent sundry.

An inactive/shut-in well bore is a non-producing completion that is capable of "beneficial use" i.e. production in **paying quantities** or of service use.

- 31. Submit evidence to support your determination that the well is in active "beneficial use" for BLM approval on the Sundry Notice Form 3160-5 within 90 days of this sundry's approval date.
- 32. Should "beneficial use" not be achieved submit for BLM approval a plan for plug and abandonment.

