Submit 3 Copies To Appropriate District	State of Nev	v Mexico			m C-103
Office District I	Energy, Minerals and	Natural Resources			ay 27, 2004
1625 N French Dr , Hobbs, NM 88240			WELL API NO		
District II OU CONSEDUATION DIVISION		30-025-03483			
1301 W Grand Ave, Artesia, NM 88210  District III  1220 South St. Francis Dr.		5. Indicate Type of Lease			
1000 D - D - D - D - A-top NM 97410		STATE S FEE			
District IV Santa Fe, Nivi 8/303		6. State Oil & Gas Lease No.			
1220 S St. Francis Dr., Santa Fe, NM 87505				E-3154	
SUNDRY NOTIC	CES AND REPORTS ON W	ELLS		or Unit Agreement	Name:
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA	ALS TO DRILL OR TO DEEPEN O	R PLUG BACK TO A	State "19"		
PROPOSALS.)	TION FOR FERWIT (FORWIC-IN	T) TOR SOCIT			
1. Type of Well: Oil Well Gas Well Other			8. Well No. 1		
2. Name of Operator			9. OGRID Number		
Hal J. Rasmussen, Operat	ing Inc.				
3. Address of Operator			10. Pool name or Wildcat		
550 West Texas Ave., Ste. 500, Midland, TX 79705			N. San Simon Yates Assoc.		
4. Well Location					
i	660 feet from the Nor	th line and 660	) feet	from the East	line
Section 19	Township 21S	Range 35E	NMPM	County Lea	
	11. Elevation (Show whether			and the same of	
Mark the second of the second	(	3645		Participation of the Control of the	
Pit or Below-grade Tank Applicati	on 🗌 or Closure 🔲				
Pit type Depth to Groundw		earest fresh water well	Distance from n	nearest surface water	
Pit Liner Thickness:			ols; Construction Ma		
			<u> </u>		
12. Check Ap	propriate Box to Indica	ie Nature of Notice, i	Report or Othe	er Data	
NOTICE OF IN⁻	TENTION TO:	SUB	SEQUENT R	REPORT OF:	
	PLUG AND ABANDON 🛛	REMEDIAL WORK		ALTERING CAS	ING 🗌
	CHANGE PLANS	COMMENCE DRIL			
PULL OR ALTER CASING		CASING/CEMENT		]	
PULL OR ALTER CASING	MULTIPLE  COMPLETION			]	
PÜLL ÖR ALTER CASING	MULTIPLE	CASING/CEMENT		]	
PÜLL ÖR ALTER CASING   OTHER:	MULTIPLE COMPLETION	CASING/CEMENT OTHER:	JOB	]	
OTHER:  13. Describe proposed or completed	MULTIPLE COMPLETION  operations. (Clearly state al	OTHER:  I pertinent details, and given	ye pertinent dates	] s, including estimat	ed date of
OTHER:  13. Describe proposed or completed starting any proposed work). SE	MULTIPLE COMPLETION  operations. (Clearly state al	OTHER:  I pertinent details, and given	ye pertinent dates	s, including estimates for proposed comple	ed date of
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.	MULTIPLE COMPLETION  operations. (Clearly state al	OTHER:	ye pertinent dates	s, including estimat of proposed comple	ed date of
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.  13 3/8 @ 100' circ.	MULTIPLE COMPLETION  operations. (Clearly state al	OTHER:	ye pertinent dates	] s, including estimat of proposed comple	ed date of
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.  13 3/8 @ 100' circ.  10 3/4 @ 650' circ.	MULTIPLE COMPLETION  operations. (Clearly state al EE RULE 1103. For Multiple	OTHER:	ye pertinent dates	of proposed comple	ed date of
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.  13 3/8 @ 100' circ.  10 3/4 @ 650' circ.  8-5/8-@-1300' circ.	MULTIPLE COMPLETION  operations. (Clearly state all EE RULE 1103. For Multiple	OTHER:	ye pertinent dates	of proposed comple	ed date of
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.  13 3/8 @ 100' circ.  10 3/4 @ 650' circ.  8 5/8 @ 1300' circ.  5 1/2 @ 3848' w/ 100 sx. TOC 3131	MULTIPLE COMPLETION  operations. (Clearly state all EE RULE 1103. For Multiple	OTHER: I pertinent details, and give Completions: Attach we	ye pertinent dates	of proposed comple	ed date of
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.  13 3/8 @ 100' circ.  10 3/4 @ 650' circ.  8-5/8-@-1300' circ.	MULTIPLE COMPLETION  operations. (Clearly state all EE RULE 1103. For Multiple	OTHER: I pertinent details, and give Completions: Attach we	ye pertinent dates	of proposed comple	ed date of
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.  13 3/8 @ 100' circ.  10 3/4 @ 650' circ.  8 5/8 @ 1300' circ.  5 1/2 @ 3848' w/ 100 sx. TOC 3131 perfs @ 3788-3804	MULTIPLE COMPLETION  operations. (Clearly state all EE RULE 1103. For Multiple	OTHER: I pertinent details, and give Completions: Attach we	ye pertinent dates	of proposed comple	ed date of
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.  13 3/8 @ 100' circ.  10 3/4 @ 650' circ.  8 5/8 @ 1300' circ.  5 1/2 @ 3848' w/ 100 sx. TOC 3131 perfs @ 3788-3804  1. MIRU plugging equipment.	MULTIPLE COMPLETION  operations. (Clearly state al EE RULE 1103. For Multiple calc.	OTHER: I pertinent details, and give Completions: Attach we	ve pertinent dates	of proposed comple	ed date of
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.  13 3/8 @ 100' circ.  10 3/4 @ 650' circ.  8 5/8 @ 1300' circ.  5 1/2 @ 3848' w/ 100 sx. TOC 3131 perfs @ 3788-3804  1. MIRU plugging equipment.  2. RIH w/ tbg to 3780, spot 35 sx cr	MULTIPLE COMPLETION  operations. (Clearly state al EE RULE 1103. For Multiple calc.  calc.	OTHER: I pertinent details, and give Completions: Attach we	ve pertinent dates ellbore diagram o	of proposed comple	tion or
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.  13 3/8 @ 100' circ.  10 3/4 @ 650' circ.  8 5/8:@ 1300' circ.  5 1/2 @ 3848' w/ 100 sx. TOC 3131 perfs @ 3788-3804  1. MIRU plugging equipment.  2. RIH w/ tbg to 3780, spot 35 sx cr 3. RIH w/ wireline and perf 5 1/2 @	MULTIPLE COMPLETION  operations. (Clearly state al EE RULE 1103. For Multiple calc.  calc.	OTHER: I pertinent details, and give Completions: Attach we	ve pertinent dates ellbore diagram o	of proposed comple	tion or
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.  13 3/8 @ 100' circ.  10 3/4 @ 650' circ.  8 5/8:@ 1300' circ.  5 1/2 @ 3848' w/ 100 sx. TOC 3131 perfs @ 3788-3804  1. MIRU plugging equipment.  2. RIH w/ tbg to 3780, spot 35 sx cr 3. RIH w/ wireline and perf 5 1/2 @ 650'.	MULTIPLE COMPLETION  operations. (Clearly state all EE RULE 1103. For Multiple calc.  and @ 3780-3580. WOC and @ 1350. POH. RIH w/ packet	OTHER: I pertinent details, and give Completions: Attach we are a completions. Tag. Circ. hole with 9.5 er. Set @ 1250. Sqz. 45 s	ve pertinent dates ellbore diagram of mud.	of proposed comple	. POH to
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.  13 3/8 @ 100' circ.  10 3/4 @ 650' circ.  8 5/8 @ 1300' circ.  5 1/2 @ 3848' w/ 100 sx. TOC 3131 perfs @ 3788-3804  1. MIRU plugging equipment.  2. RIH w/ tbg to 3780, spot 35 sx cr 3. RIH w/ wireline and perf 5 1/2 @ 650'.	MULTIPLE COMPLETION  operations. (Clearly state all EE RULE 1103. For Multiple calc.  nt @ 3780-3580. WOC and 1350. POH. RIH w/ packers.	CASING/CEMENT OTHER: I pertinent details, and give Completions: Attach we Tag. Circ. hole with 9.5 er. Set @ 1250. Sqz. 45 st	ve pertinent dates ellbore diagram of mud.	and pressure test	. POH to
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.  13 3/8 @ 100' circ.  10 3/4 @ 650' circ.  8 5/8 @ 1300' circ.  5 1/2 @ 3848' w/ 100 sx. TOC 3131 perfs @ 3788-3804  1. MIRU plugging equipment.  2. RIH w/ tbg to 3780, spot 35 sx cr 3. RIH w/ wireline and perf 5 1/2 @ 650'.	MULTIPLE COMPLETION  operations. (Clearly state all EE RULE 1103. For Multiple calc.  nt @ 3780-3580. WOC and 1350. POH. RIH w/ packers.	CASING/CEMENT OTHER: I pertinent details, and give Completions: Attach we Tag. Circ. hole with 9.5 er. Set @ 1250. Sqz. 45 st	ve pertinent dates ellbore diagram of mud.	and pressure test	. POH to
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.  13 3/8 @ 100' circ.  10 3/4 @ 650' circ.  8 5/8:@ 1300' circ.  5 1/2 @ 3848' w/ 100 sx. TOC 3131 perfs @ 3788-3804  1. MIRU plugging equipment.  2. RIH w/ tbg to 3780, spot 35 sx cr 3. RIH w/ wireline and perf 5 1/2 @ 650'.	MULTIPLE COMPLETION  operations. (Clearly state all EE RULE 1103. For Multiple calc.  nt @ 3780-3580. WOC and 1350. POH. RIH w/ packers.	CASING/CEMENT OTHER: I pertinent details, and give Completions: Attach we Tag. Circ. hole with 9.5 er. Set @ 1250. Sqz. 45 st	ve pertinent dates ellbore diagram of mud.	and pressure test	. POH to
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.  13 3/8 @ 100' circ.  10 3/4 @ 650' circ.  8 5/8 @ 1300' circ.  5 1/2 @ 3848' w/ 100 sx. TOC 3131 perfs @ 3788-3804  1. MIRU plugging equipment.  2. RIH w/ tbg to 3780, spot 35 sx cr 3. RIH w/ wireline and perf 5 1/2 @ 650'.	MULTIPLE COMPLETION  operations. (Clearly state all EE RULE 1103. For Multiple calc.  nt @ 3780-3580. WOC and 1350. POH. RIH w/ packers.	CASING/CEMENT OTHER: I pertinent details, and give Completions: Attach we Tag. Circ. hole with 9.5 er. Set @ 1250. Sqz. 45 st	ve pertinent dates ellbore diagram of mud.	and pressure test	. POH to
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.  13 3/8 @ 100' circ.  10 3/4 @ 650' circ.  8 5/8 @ 1300' circ.  5 1/2 @ 3848' w/ 100 sx. TOC 3131 perfs @ 3788-3804  1. MIRU plugging equipment.  2. RIH w/ tbg to 3780, spot 35 sx cr 3. RIH w/ wireline and perf 5 1/2 @ 650'.	MULTIPLE COMPLETION  operations. (Clearly state all EE RULE 1103. For Multiple calc.  nt @ 3780-3580. WOC and 1350. POH. RIH w/ packers.	CASING/CEMENT OTHER: I pertinent details, and give Completions: Attach we Tag. Circ. hole with 9.5 er. Set @ 1250. Sqz. 45 st	ve pertinent dates ellbore diagram of mud.	and pressure test	. POH to
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.  13 3/8 @ 100' circ.  10 3/4 @ 650' circ.  8-5/8:@-1300' circ.  5 1/2 @ 3848' w/ 100 sx. TOC 3131 perfs @ 3788-3804  1. MIRU plugging equipment.  2. RIH w/ tbg to 3780, spot 35 sx cm  3. RIH w/ wireline and perf 5 1/2 @ 650'.  4. RIH w/ wireline and perf 5 1/2 @ 5. Perf. 5 1/2 @ 150'. Sqz. 45 sx. do	MULTIPLE COMPLETION  operations. (Clearly state all EE RULE 1103. For Multiple calc.  at @ 3780-3580. WOC and @ 1350. POH. RIH w/ packer @ 700'. POH. Set packer @ wn 5 1/2 and up 8 5/8. Cut	OTHER: I pertinent details, and give Completions: Attach were a completions: Attach were a completions of the completions of th	we pertinent dates ellbore diagram of the control o	and pressure test sure test. POH w/	. POH to packer.
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.  13 3/8 @ 100' circ.  10 3/4 @ 650' circ.  8 5/8 @ 1300' circ.  5 1/2 @ 3848' w/ 100 sx. TOC 3131 perfs @ 3788-3804  1. MIRU plugging equipment.  2. RIH w/ tbg to 3780, spot 35 sx cr 3. RIH w/ wireline and perf 5 1/2 @ 650'.  4. RIH w/ wireline and perf 5 1/2 @ 5. Perf. 5 1/2 @ 150'. Sqz. 45 sx. do	MULTIPLE COMPLETION  operations. (Clearly state al EE RULE 1103. For Multiple calc.  at a 3780-3580. WOC and 1350. POH. RIH w/ packer a 700'. POH. Set packer a wn 5 1/2 and up 8 5/8. Cut	CASING/CEMENT OTHER: I pertinent details, and give Completions: Attach were completed as a second se	we pertinent dates ellbore diagram of the work work.  work work and presson Dry Hole Ma	and pressure test sure test. POH w/ arker. Clean loc. m	POH to packer.
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.  13 3/8 @ 100' circ.  10 3/4 @ 650' circ.  8-5/8:@-1300' circ.  5 1/2 @ 3848' w/ 100 sx. TOC 3131 perfs @ 3788-3804  1. MIRU plugging equipment.  2. RIH w/ tbg to 3780, spot 35 sx cm  3. RIH w/ wireline and perf 5 1/2 @ 650'.  4. RIH w/ wireline and perf 5 1/2 @ 5. Perf. 5 1/2 @ 150'. Sqz. 45 sx. do	MULTIPLE COMPLETION  operations. (Clearly state al EE RULE 1103. For Multiple calc.  at a 3780-3580. WOC and 1350. POH. RIH w/ packer a 700'. POH. Set packer a wn 5 1/2 and up 8 5/8. Cut	CASING/CEMENT OTHER: I pertinent details, and give Completions: Attach were completed as a second se	we pertinent dates ellbore diagram of the work work.  work work and presson Dry Hole Ma	and pressure test sure test. POH w/ arker. Clean loc. m	POH to packer.
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.  13 3/8 @ 100' circ.  10 3/4 @ 650' circ.  8 5/8 @ 1300' circ.  5 1/2 @ 3848' w/ 100 sx. TOC 3131 perfs @ 3788-3804  1. MIRU plugging equipment.  2. RIH w/ tbg to 3780, spot 35 sx cr 3. RIH w/ wireline and perf 5 1/2 @ 650'.  4. RIH w/ wireline and perf 5 1/2 @ 5. Perf. 5 1/2 @ 150'. Sqz. 45 sx. do Perf. 5 1/2	MULTIPLE COMPLETION  operations. (Clearly state all EE RULE 1103. For Multiple calc.  at @ 3780-3580. WOC and 1350. POH. RIH w/ packer @ wn 5 1/2 and up 8 5/8. Cut to is true and complete to the best cording to NMOCD guidelines [	CASING/CEMENT OTHER: I pertinent details, and give Completions: Attach were completed at the complete of the c	we pertinent dates ellbore diagram of the work work.  work work and presson Dry Hole Ma	and pressure test sure test. POH w/ urker. Clean loc. m	POH to packer. love off.
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.  13 3/8 @ 100' circ.  10 3/4 @ 650' circ.  8 5/8 @ 1300' circ.  5 1/2 @ 3848' w/ 100 sx. TOC 3131 perfs @ 3788-3804  1. MIRU plugging equipment.  2. RIH w/ tbg to 3780, spot 35 sx cr 3. RIH w/ wireline and perf 5 1/2 @ 650'.  4. RIH w/ wireline and perf 5 1/2 @ 5. Perf. 5 1/2 @ 150'. Sqz. 45 sx. do	MULTIPLE COMPLETION  operations. (Clearly state all EE RULE 1103. For Multiple calc.  at @ 3780-3580. WOC and 1350. POH. RIH w/ packer @ wn 5 1/2 and up 8 5/8. Cut to is true and complete to the best cording to NMOCD guidelines [	CASING/CEMENT OTHER: I pertinent details, and give Completions: Attach were completed as a second se	we pertinent dates ellbore diagram of the work work.  work work and presson Dry Hole Ma	and pressure test sure test. POH w/ arker. Clean loc. m	POH to packer. love off.
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.  13 3/8 @ 100' circ.  10 3/4 @ 650' circ.  8-5/8:@-1300' circ.  5 1/2 @ 3848' w/ 100 sx. TOC 3131 perfs @ 3788-3804  1. MIRU plugging equipment.  2. RIH w/ tbg to 3780, spot 35 sx cm  3. RIH w/ wireline and perf 5 1/2 @ 650'.  4. RIH w/ wireline and perf 5 1/2 @ 5. Perf. 5 1/2 @ 150'. Sqz. 45 sx. do  Plus 1 (1972 A) 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	MULTIPLE COMPLETION  operations. (Clearly state all ERULE 1103. For Multiple calc.  at @ 3780-3580. WOC and @ 1350. POH. RIH w/ packer @ 700'. POH. Set packer @ wn 5 1/2 and up 8 5/8. Cut  e is true and complete to the bescording to NMOCD guidelines [	CASING/CEMENT OTHER: I pertinent details, and give Completions: Attach were completed at the complete of the complete of my knowledge and belied of the complete of the complete of my knowledge and belied of the complete of the	we pertinent dates ellbore diagram of the work work. WOC and presson Dry Hole Ma	and pressure test sure test. POH w/ urker. Clean loc. m that any pit or belowative OCD-approved DATE 11/13/0	POH to packer. love off.
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.  13 3/8 @ 100' circ.  10 3/4 @ 650' circ.  8-5/8 @ 1300' circ.  5 1/2 @ 3848' w/ 100 sx. TOC 3131 perfs @ 3788-3804  1. MIRU plugging equipment.  2. RIH w/ tbg to 3780, spot 35 sx cm  3. RIH w/ wireline and perf 5 1/2 @ 650'.  4. RIH w/ wireline and perf 5 1/2 @ 5. Perf. 5 1/2 @ 150'. Sqz. 45 sx. do  1 hereby certify that the information above has been/will be constructed or closed accompliance.  SIGNATURE ROGER Brooks	MULTIPLE COMPLETION  operations. (Clearly state all ERULE 1103. For Multiple calc.  at @ 3780-3580. WOC and @ 1350. POH. RIH w/ packer @ 700'. POH. Set packer @ wn 5 1/2 and up 8 5/8. Cut  e is true and complete to the bescording to NMOCD guidelines [	CASING/CEMENT OTHER: I pertinent details, and give Completions: Attach were completed at the complete of the c	we pertinent dates ellbore diagram of the work work. WOC and presson Dry Hole Ma	and pressure test sure test. POH w/ urker. Clean loc. m	POH to packer. love off.
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.  13 3/8 @ 100' circ.  10 3/4 @ 650' circ.  8-5/8:@-1300' circ.  5 1/2 @ 3848' w/ 100 sx. TOC 3131 perfs @ 3788-3804  1. MIRU plugging equipment.  2. RIH w/ tbg to 3780, spot 35 sx cm  3. RIH w/ wireline and perf 5 1/2 @ 650'.  4. RIH w/ wireline and perf 5 1/2 @ 5. Perf. 5 1/2 @ 150'. Sqz. 45 sx. do  Plus 1 (1972 A) 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	MULTIPLE COMPLETION  operations. (Clearly state al EE RULE 1103. For Multiple  calc.  nt @ 3780-3580. WOC and 1350. POH. RIH w/ packer 0 700'. POH. Set packer @ wn 5 1/2 and up 8 5/8. Cut  e is true and complete to the bescording to NMOCD guidelines [ what TIT  E-mail	OTHER: I pertinent details, and give Completions: Attach were Completions: Attach were completed at the complete complet	we pertinent dates ellbore diagram of the work of the	cand pressure test sure test. POH w/ arker. Clean loc. m  that any pit or belowative OCD-approved  DATE 11/13/0 cphone No. 432-580	POH to packer. sove off.
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.  13 3/8 @ 100' circ.  10 3/4 @ 650' circ.  8 5/8 @ 1300' circ.  5 1/2 @ 3848' w/ 100 sx. TOC 3131 perfs @ 3788-3804  1. MIRU plugging equipment.  2. RIH w/ tbg to 3780, spot 35 sx cm.  3. RIH w/ wireline and perf 5 1/2 @ 650'.  4. RIH w/ wireline and perf 5 1/2 @ 5. Perf. 5 1/2 @ 150'. Sqz. 45 sx. do recompleted and specific square starting and perf.  Type or print name Roger Brooks For State Use Only	MULTIPLE COMPLETION  operations. (Clearly state al EE RULE 1103. For Multiple  calc.  nt @ 3780-3580. WOC and 1350. POH. RIH w/ packer 0 700'. POH. Set packer @ wn 5 1/2 and up 8 5/8. Cut  e is true and complete to the bescording to NMOCD guidelines [ what TIT  E-mail	CASING/CEMENT OTHER: I pertinent details, and give Completions: Attach were completed at the complete of the complete of my knowledge and belied of the complete of the complete of my knowledge and belied of the complete of the	we pertinent dates ellbore diagram of the work of the	cand pressure test sure test. POH w/ arker. Clean loc. m  that any pit or belowative OCD-approved  DATE 11/13/0 cphone No. 432-580	POH to packer. love off.
OTHER:  13. Describe proposed or completed starting any proposed work). SE recompletion.  13 3/8 @ 100' circ.  10 3/4 @ 650' circ.  8-5/8 @ 1300' circ.  5 1/2 @ 3848' w/ 100 sx. TOC 3131 perfs @ 3788-3804  1. MIRU plugging equipment.  2. RIH w/ tbg to 3780, spot 35 sx cm  3. RIH w/ wireline and perf 5 1/2 @ 650'.  4. RIH w/ wireline and perf 5 1/2 @ 5. Perf. 5 1/2 @ 150'. Sqz. 45 sx. do  1 hereby certify that the information above has been/will be constructed or closed accompliance.  SIGNATURE ROGER Brooks	MULTIPLE COMPLETION  operations. (Clearly state al EE RULE 1103. For Multiple  calc.  nt @ 3780-3580. WOC and 1350. POH. RIH w/ packer 0 700'. POH. Set packer @ wn 5 1/2 and up 8 5/8. Cut  e is true and complete to the bescording to NMOCD guidelines [ what TIT  E-mail	OTHER: I pertinent details, and give Completions: Attach were Completions: Attach were completed at the complete complet	we pertinent dates ellbore diagram of the work of the	cand pressure test sure test. POH w/ arker. Clean loc. m  that any pit or belowative OCD-approved  DATE 11/13/0 cphone No. 432-580	POH to packer. nove off.

