

RECEIVED

OCT 28 2009

HOBBSOCD

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well [ ] Oil Well [ ] Gas Well [X] Other Injection

2. Name of Operator OXY USA Inc. 16696

3a. Address P.O. Box 50250, Midland, TX 79710-0250 3b. Phone No. (include area code) 432-685-5717

4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 660 FNL 1980 FWL NENW(C) Sec 4 T18S R33E

5. Lease Serial No. NMLC029489B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No. Central Corbin #209 Queen Unit

9. API Well No. 30-025-29777

10. Field and Pool, or Exploratory Area Corbin Queen, Central

11. County or Parish, State Lea NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

- [X] Notice of Intent [ ] Subsequent Report [ ] Final Abandonment Notice


- [ ] Acidize [ ] Deepen [ ] Production (Start/Resume) [ ] Water Shut-Off [ ] Alter Casing [ ] Fracture Treat [ ] Reclamation [ ] Well Integrity [ ] Casing Repair [ ] New Construction [ ] Recomplete [ ] Other [ ] Change Plans [X] Plug and Abandon [ ] Temporarily Abandon [ ] Convert to Injection [ ] Plug Back [ ] Water Disposal

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

TD-4450' PBDT-4020' Perfs-4152-4168' CIBP-4020'

8-5/8" 24# csg @ 391' w/300sx, 12-1/4" hole, TOC-Surf-Circ 5-1/2" 15.5# csg @ 4450' w/ 1400sx, 7-7/8" hole, TOC-Surf-Circ

- 1. RIH & Tag CIBP @ 4020 ; M&P 25sx cmt to 3880' 2. M&P 25sx cmt @ 3015-2885' WOC-Tag 3. M&P 45sx cmt @ 1600-1425' WOC-Tag 4. M&P 25sx cmt @ 441-335' WOC-Tag 5. M&P 25sx cmt @ 150'-Surface 10# MLF between plugs



SEE ATTACHED FOR CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)

David Stewart

Title

Sr. Regulatory Analyst

Date

10/20/09

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

OXY USA Inc. - Proposed  
Central Corbin Queen Unit #209  
API No. 30-025-29777

25sx @ 150'-Surface


25sx @ 441-335' WOC-Tag

45sx @ 1600-1425' WOC-Tag

25sx @ 3015-2885' WOC-Tag

25sx @ 4020-3880'  
8/04-CIBP @ 4020'

PB-4412'



TD-4450'

12-1/4" hole @ 391'  
8-5/8" csg @ 391'  
w/ 300sx-TOC-Surf-Circ

Perfs @ 4152-4166'

7-7/8" hole @ 4450'  
5-1/2" csg @ 4450'  
w/ 1400sx-TOC-Surf-Circ

OXY USA Inc. - Current  
Central Corbin Queen Unit #209  
API No. 30-025-29777

12-1/4" hole @ 391'  
8-5/8" csg @ 391'  
w/ 300sx-TOC-Surf-Circ


8/04-CIBP @ 4020'

Perfs @ 4152-4166'

PB-4412'

7-7/8" hole @ 4450'  
5-1/2" csg @ 4450'  
w/ 1400sx-TOC-Surf-Circ

TD-4450'



**Central Corbin Queen Unit #209  
30-025-29777  
OXY USA Inc.  
October 26, 2009  
Conditions of Approval**

- 1. OK**
- 2. OK**
- 3. Move this plug to 1,632' to be 50' below the top of salt.**
- 4. OK**
- 5. OK**
- 6. It is recommended that you combine plugs 4 & 5, this will save a tag.**

**MAK 102609**