

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised May 08, 2003

WELL API NO. 30-025-26169
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. NM B - 1428
7. Lease Name or Unit Agreement Name State 'U' <u>Gas Com</u>
8. Well Number 002
9. OGRID Number 000495
10. Pool name or Wildcat Eumont Yates 7 Rivers Queen

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☐ Gas Well ☒ Other

2. Name of Operator  
Amerada Hess Corporation

3. Address of Operator  
P.O. Box 840 Seminole, TX 79360

4. Well Location

Unit Letter C : 990 feet from the North line and 2160 feet from the West line

Section 32 Township 19S Range 37E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3705' KB

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐


COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

MIRU and install BOP. Perf the following intervals:  
3055'-3062', 3080'-3082', 3084'-3086', 3093'-3095',  
3110'-3120', 3142'-3149', 3168'-3176', 3252'-3261',  
3271'-3286'. Test lines to 3000 psi. Acidize well,  
swab well and return to production.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Carol J. Moore TITLE Senior Advisor DATE 1/12/2004

Type or print name Carol J. Moore cmoore@hess.com Telephone No. (432) 738-6738

(This space for State use)

APPROVED BY Harry W. Wink TITLE OG FIELD REPRESENTATIVE / STAFF MANAGER DATE JAN 15 2004

Conditions of approval, if any: