

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amerada Hess Corporation	8. Farm or Lease Name W.E. Mathers
3. Address of Operator 1209 South Main - Lovington, New Mexico	9. Well No. #1
4. Location of Well UNIT LETTER <u>H</u> <u>662'</u> FEET FROM THE <u>East</u> LINE AND <u>1980'</u> FEET FROM THE <u>North</u> LINE, SECTION <u>3</u> TOWNSHIP <u>12-S</u> RANGE <u>33-E</u> NMPM.	10. Field and Pool, or Wildcat Bagley Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4254' G.R.	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
FULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

W.E. Mathers #1 - Set Cast Iron Bridge Plug @ 8950' w/35 sacks of Cement on top of plug. Load Hole w/Salt Water Mud and cut 5-1/2" Csg. @ 4000', spot 35 sacks cement 4050' to 3950', and spot 35 sack plug 3813' to 3913'. Cut 8-5/8" Csg. @ 1000' spot 100 sack plug 1050' to 950', and spot 100 sack plug 258' to 358'. Spot 20' plug top of 13-3/8" with 4"x10' Dry Hole Marker. After Plugging operation will clean location for State inspection. Plan to start plugging operation on 4/9/73.

24 hr notice

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W.E. Mathers TITLE Area Supt. DATE 3/30/73

WITNESSED BY _____ TITLE _____ DATE _____